

1250 West Century Avenue Mailing Address: P.O. Box 5601 Bismarck, ND 58506-5601 (701) 530-1600

November 12, 2021

Kimberly D. Bose, Secretary Federal Energy Regulatory Commission 888 First Street, N.E., Room 1A Washington, D.C. 20426

Re: WBI Energy Transmission, Inc. Docket Nos. CP20-52-000 and CP20-52-001 North Bakken Expansion Project Weekly Status Report No. 23

Dear Ms. Bose:

WBI Energy Transmission, Inc. (WBI Energy) herewith submits its Weekly Status Report No. 23 for the North Bakken Expansion Project, in compliance with Environmental Condition 8 of the Appendix to the Federal Energy Regulatory Commission's June 1, 2021 Order Issuing Certificate in the above referenced dockets.

The attached report addresses the period November 1, 2021 to November 7, 2021.

Should you have any questions or comments regarding this filing, please call the undersigned at (701) 530-1563.

Sincerely,

/s/ Lori Myerchin

Lori Myerchin Director, Regulatory Affairs and Transportation Services

Courtesy Copies: Dawn Ramsey, FERC



WBI Energy Transmission, Inc. North Bakken Expansion Project Status Report No. 23 FERC Docket Nos. CP20-52-000 CP20-52-001

Reporting Period: November 1, 2021 through November 7, 2021

A. Update on Federal Authorizations

WBI Energy has obtained all necessary federal permits and authorizations required for construction of the North Bakken Expansion Project.

B. Construction Status - Pipeline Facilities

- Environmental Inspectors conducted onsite environmental training as needed.
- Continued installing and maintaining various project signage and erosion control devices around Project sites.



Activity	Completed Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Clearing / Grading		100%	
Stringing		100%	
Bending		100%	
Welding		100%	
Joint Coating		100%	
Ditching		100%	
Lowering		100%	
Backfill		100%	
Cleanup		100%	
Seeding	0%	0%	1/
Hydrostatic Testing		100%	
fence will be re-installed an Work Planned for next R	completed in conjunction with the fil nd re-seeding along the fence will o eporting Period and Schedule Ch d for the next reporting period.	1 0	or Station. The security
Problem Areas, Correctiv	ve Actions and Effectiveness:		
 No problem areas 	were identified during reporting per	iod.	
Non-Compliance Issues,	Corrective Actions and Effective		
	e issues were identified during repo	ution a second and	

¹ This reroute was included as part of WBI Energy's response to Environmental Condition 5 of its June 8, 2021 Response to Environmental Conditions of Order Issuing Certificate (Attachment 5-1, Table 5A, Modification Reference ID AF-1).

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

Activity	Total % Completed This Period	% of Total Job Completed	Comments
lipeline			
Clearing / Grading		100%	
Stringing		100%	
Bending		100%	
Welding		100%	
Joint Coating		100%	
Ditching		100%	
Lowering		100%	
Backfill		100%	
Cleanup		100%	
Seeding	20%	100%	Included applying straw mulch over seeded areas followed by a crimper to anchor the straw mulch.
Pig Launcher/Receiver ²		2 of 2	Pig launcher/receivers completed 1/
Block Valve ³		1 of 1	Block Valve completed
Bores		8 of 8	Bores completed
Hydrostatic Testing		100%	
1/ Final tie-ins will be completed i	n conjunction with the com	missioning of the loope	ed pipeline.
 Work Planned for next Reporting No work is planned for the 	-	Changes:	
Problem Areas, Corrective Acti	1 21	Possible:	
	identified during reporting		
Non-Compliance Issues, Corre	0 1 01		
No non-compliance issue			

² Includes a pig launcher / receiver at the Nesson valve setting (MP 0.0) and the Tioga Compressor Station (MP 9.6).

³ The Temple Valve site was included as part of WBI Energy's response to Environmental Condition 5 of its June 8, 2021 Response to Environmental Conditions of Order Issuing Certificate (Attachment 5-1, Table 5A, Modification Reference ID LS30-1).

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action
11/5/2021	Mark Schmidt	3.5/ 2	A natural drainage swale had its outlet covered up during restoration.	The covered drainage area was uncovered and restored. The Environmental Inspector found the restoration acceptable.
	© 23°N (T) + 4	8°21'48.9", -10	2°58'10.6" ±3 m	Date: 11/05/2021

North Bakken Expansion Uprate Line 30 Section

Notes: Restored drainage path.



Date: 11/01/2021

Location: Sta. Nos. 314+82 to 333+23

Notes: Installation of permanent fencing and the seeded, mulched, and crimped right-of-way on the Line Section 30 Loop.

Work Completed	during Reporting	Period:		
Continue	ed seeding along th	e right-of-way. Fina	I seed mix and rates are ba	sed upon landowner preference, local soil
			olicable land management a ck valve at 56th Avenue NV	
	• •			
Act	ivity	Total % Compl This Period		Comments
Pipeline				
Clearing / Gradin	g		100%	
Stringing	0		100%	
Bending			100%	
Welding			100%	
Joint Coating			100%	
Ditching			100%	
Lowering			100%	
Backfill			100%	
Cleanup			100%	
Seeding		20%	90%	Included applying straw mulch over seeded areas followed by a crimper to anchor the straw mulch.
Pig Launcher/Re	ceiver ⁴		2 of 2	Pig launcher/receivers completed
Block Valve ⁵			1 of 1	Block valve completed
Bores			20 of 20	Bores completed
Hydrostatic Testi	ng		100%	
Work Planned f	or next Reporting	Period and Schedu	ile Changes:	
Continue	seeding activities.			
Problem Areas,	Corrective Action	s and Effectivenes	s:	
		ntified during report		
•	•	ve Actions and Effe		
		vere identified during		
•			Permitting Agencies and	d Response:
 No non-o Copies included: 	•	vere identified during	g reporting period.	
Landowner Issu	11			
	ies. None	Milonaat /		
Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

⁴ Includes a pig launcher / receiver at the Tioga Compressor Station (MP 0.0) and at 104th Avenue NW (MP 6.2).

⁵ Includes a block valve at 56th Avenue NW (MP 16.2).


 NW
 N
 NE
 E

 300
 330
 0
 30
 60
 90

 I 16°N (M)
 48°17'54"N, 103°0'34"W ±9ft
 2260ft


 Station 525+51
 North Bakken Expansion

 Tioga to Elkhorn Creek Line.
 North Bakken Expansion



Location: Sta. No. 525+51

Notes: Seeded, mulched, and crimped right-of-way on the Tioga-Elkhorn Creek Pipeline.



Location: Sta. No. 648+00

Notes: Seeded, mulched, and crimped right-of-way on the south side of 60th Street NW on the Tioga-Elkhorn Creek Pipeline.



NE

North Bakken Expansion

02 Nov 2021, 09:02:18

Location: Sta. No. 641+20

Notes: Erosion control blankets in place and properly functioning in bar ditch north of 60th Street NW on the Tioga-Elkhorn Creek Pipeline.



Date: 11/02/2021

Location: Sta. No. 715+00

Notes: Seeded, mulched, and crimped portions of right-ofway on the Tioga-Elkhorn Creek Pipeline.

W 270

Station 641+20

Tioga to Elkhorn Creek Line

NW

© 351°N (M) ● 48°17'2"N, 103°1'9"W ±16ft ▲ 2180ft

 SW
 W
 N
 NI

 240
 270
 300
 330
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 30
 10
 30
 10
 30
 10
 30
 10
 30
 10
 30
 10
 30
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10
 10

Date: 11/03/2021

Location: Sta. No. 894+77

Notes: Installation of permanent fencing and seeded, mulched, and crimped right-ofway on the Tioga-Elkhorn Creek Pipeline.

Date: 11/03/2021

Location: Sta. No. 1099+16

Notes: Erosion control blankets in place and properly functioning west of 103rd Avenue NW on the Tioga-Elkhorn Creek Pipeline.



 NW
 N
 NE
 E


 300
 330
 0
 30
 10
 60
 90
 10

 © 8°N (M)
 © 48°12'6"N, 103°2'41"W ±9ft
 1950ft
 1950ft
 1950ft

Date: 11/04/2021

Location: Sta. No. 996+00

Notes: Spreading straw mulch on the seeded right-of-way on the Tioga-Elkhorn Creek Pipeline.



Location: Sta. No. 855+94

Notes: Continued installation of a security fence around a block valve at 56th Avenue NW on the Tioga-Elkhorn Creek Pipeline.



TABLE 1-3b Tioga-Elkhorn Creek Pipeline- Spread 2 (MP 23.0 to 62.8)

Work Completed during Reporting Period:

- On November 1, 2021, FERC approved WBI Energy's October 29, 2021 Level 3 variance request (V63) for a minor reroute between mileposts 51.2 and 51.4 due to the presence of a third-party pipeline. The reroute will allow the necessary clearance between WBI Energy and the third party's pipeline for safe operations.
- Continued cleanup activities.
- Continued seeding activities along the right-of-way. Final seed mix and rates are based upon landowner preference, local soil conservation authority recommendations, or applicable land management agency requirements.
- Continued construction activities at remaining bore locations.

 On November 1, 2021, multiple small inadvertent releases (IRs) occurred in an upland area at milepost 58.3 during boring activities. WBI Energy quickly implemented measures identified in the Horizontal Directional Drill/Guided Bore Drilling Fluid Monitoring and Operations Plan (HDD Plan) for the containment and cleanup of drilling fluids. Hand tools, sediment control devices, and a vac-truck were utilized to contain and remove released fluids. The IRs originated within the Project right-of-way, though some drilling fluid migrated slightly west of the approved limits of disturbance. The FERC Compliance Monitor was informed of the IR location and response efforts. No further cleanup was required. No wetland or waterbody resources were impacted.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Clearing / Grading		100%	
Stringing		100%	
Bending		100%	
Welding		100%	
Joint Coating		100%	
Ditching		100%	
Lowering		100%	
Backfill		100%	
Cleanup	30%	95%	Included rock picking, final grading and the removal of construction material and debris.
Seeding	50%	70%	Included applying straw mulch over seeded areas followed by a crimper to anchor the straw mulch.
Pig Launcher/Receiver ⁶		1 of 1	Pig launcher/receiver completed
Block Valves ⁷		3 of 3	Block Valves completed
Bores	0 of 38	35 of 38	
Hydrostatic Testing	0%	0%	
Begin hydrostatically test	eeding activities. tivities at remaining bore lo ting pipeline.	•	
Problem Areas, Corrective Act No problem areas were i	ions and Effectiveness: dentified during reporting p	eriod.	
Non-Compliance Issues, Corre No non-compliance issue	ctive Actions and Effectives were identified during re		
Non-Compliance Issues from F • No non-compliance issue	Federal, State or Local Pe es were identified during re		d Response:

Copies included: Not applicable

⁶ Includes a pig launcher / receiver at the Elkhorn Compressor Station (MP 62.8).

⁷ Includes block valves at South Lake (MP 26.2), Highway 10 (MP 37.0) and Cherry Creek (MP 51.4).

Landowner Issu	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action
10/29/2021	Lemoine D & Clarice J. / J.T. Hartel	52.4 Sheet 24	Following the completion of a bore of waterbody s-ibt- 001a (Cherry Creek), it was determined there was an approximate 1-foot uplift of the waterbody's banks (above the bore pipe). No erosion or sediment release occurred within the waterbody due to the uplift.	The contractor has been made aware of the uplift of the waterbody banks. The area has been documented in the restoration punch list, and the contractor has indicated that the waterbody banks will be reshaped to match pre-construction conditions once the appropriate equipment can be mobilized to the area.
Update				A contractor has been scheduled to resolve the uplift of the waterbody banks on Monday, November 8, 2021.
10/29/2021	Lemoine D & Clarice J. / J.T. Hartel	52.4 Sheet 24	The landowner indicated the seed mix used in restoring the right-of-way did not contain the requested quantities of Big Bluestem grass.	A seed mix containing the requested quantities of Big Bluestem grass will be delivered on November 10, 2021. The tract(s) will be reseeded via the broadcasting method at twice the drilling rate. No reseeding date has been scheduled yet.



Location: Sta. No. 3046+36

Notes: A discovered inadvertent release on the Tioga-Elkhorn Creek Pipeline before containment and removal.



Location: Sta. Nos. 2878+88 to 2878+51

Notes: Removal of construction mats at wetland w-mk-ef-007e on the Tioga-Elkhorn Creek Pipeline.



Date: 11/01/2021

Location: Sta. No. 2825+00

Notes: Restoration of right-of-way on the Tioga-Elkhorn Creek Pipeline.

Location: Sta. No. 1378+00

Notes: An intact dewatering structure after dewatering activities on the Tioga-Elkhorn Creek Pipeline.



SE

=

LAT: 48.114145 LON: -103.093241 ±16ft 1930ft

1 . 1 .

S

01 Nov 2021, 10:35

Date: 11/02/2021

Location: Sta. Nos. 2860+00 to 2862+00

Notes: Seeded, mulched, and crimped right-of-way on the Tioga-Elkhorn Creek Pipeline.

NE

Dewatering structure at station

North Bakken Expansion

1378+00

1 • 1 • 1 • 1 • 1 •



Location: Sta. No. 2995+00

Notes: Removal of timber mats on the Tioga-Elkhorn Creek Pipeline.



Date: 11/03/2021

Location: Sta. No. 2995+00

Notes: Spreading of straw on the right-ofway on the Tioga-Elkhorn Creek Pipeline.



Location: Sta. Nos. 2889+00 to 2902+33.

Notes: Seeded, mulched, and crimped right-of-way on the Tioga-Elkhorn Creek Pipeline.

NW N N N N O NE 60 90 LAT: 47.742500 LON: -103.198392 ±19ft A 2266ft

Date: 11/03/2021

Location: Sta. No. 2979+00

Notes: Spreading of topsoil across the right-of-way on the Tioga-Elkhorn Creek Pipeline

	eo eouloment remova		ativitian at the LIDD have ait.	
Act	ivity	Total % Completed T Period	his the HDD bore situ % of Total Job Completed	e. Comments
Pipeline				
Site Prep			100%	
Stringing			100%	
Bending		N/A	N/A	
Welding			100%	
Joint Coating			100%	
Pilot Hole Drillin	g		100%	The pilot hole intersect was completed or September 17, 2021.
Reaming Opera	tions		100%	· ·
Pipe Installation			100%	Completed on October 25, 2021.
Hydrostatic Testing			100%	
	or next Reporting P		•	
Problem Areas • No prob Non-Compliance	Corrective Actions lem areas were ident ce Issues, Corrective compliance issues w	and Effectiven ified during repo e Actions and E	rting period. ffectiveness:	
•	compliance issues w		cal Permitting Agencies ar ing reporting period.	nd Response:
Landowner Iss	ues: None	1		
		Milepost / Alignment		



Location: North Spread HDD bore site.

Notes: Removal of pipe rollers used in the installation of the bore pipe under Lake Sakakawea.

 SE
 S
 V
 W
 NW

 • 226°SW (M)
 • 48°9'24"N, 103°4'37"W ±13ft
 • 1870ft

 • 226°SW (M)
 • 48°9'24"N, 103°4'37"W ±13ft
 • 1870ft

 • Station 1216+50° Tioga to Elkhorn Creek Line
 North Bakken Expansion on Nor 2021, 12:28:17

Date: 11/03/2021

Location: North Spread HDD bore site.

Notes: Clean-up activities at the North Spread HDD bore site. Lake Sakakawea in the background.



Date: 11/05/2021

Location: North Spread HDD bore site.

Notes: Removal of construction mats from the HDD bore site.

 SW
 W
 NW
 N

 210
 240
 270
 300
 330
 0

 © 276°W (M)
 © 48°9'52"N, 103°4'26"W ±13ft
 1895ft

 Image: Station 1183+84
 Image: Station 1183+84
 Image: Station 1183+84

 Image: Station 1183+84
 Image: Station 1183+84
 Image: Station 1183+84

 Image: Station 1183+84
 Image: Station 1183+84
 Image: Station 1183+84

 Image: Station 1183+84
 Image: Station 1183+84
 Image: Station 1183+84

 Image: Station 1183+84
 Image: Station 1183+84
 Image: Station 1183+84

 Image: Station 1183+84
 Image: Station 1183+84
 Image: Station 1183+84

 Image: Station 1183+84
 Image: Station 1183+84
 Image: Station 1183+84

 Image: Station 1183+84
 Image: Station 1183+84
 Image: Station 1183+84

 Image: Station 1183+84
 Image: Station 1183+84
 Image: Station 1183+84

 Image: Station 1183+84
 Image: Station 1183+84
 Image: Station 1183+84

Date: 11/05/2021

Location: North Spread HDD bore site.

Notes: Replacing subsoil along the pullback string rightof-way at the North Spread HDD bore site.



Date: 11/06/2021

Location: North Spread HDD bore site.


Notes: Disked subsoil at the pullback string right-of-way at the North Spread HDD bore site.

•	during Reporting		ctivities at the HDD bore site	э.
Acti	vity	Total % Completed Th Period	is % of Total Job Completed	Comments
Pipeline				
Site Prep			100%	
Pilot Hole Drilling			100%	The pilot hole intersect was completed or September 17, 2021.
Reaming Operat	ons		100%	
Swab Pass			100%	
Pull Back & Pipe Installation			100%	Completed on October 25, 2021.
Problem Areas, • No probl Non-Complianc • No non-co Non-Complianc	Corrective Action om areas were iden susues, Correcti compliance issues susues from Fed compliance issues	s and Effectivenentified during report ve Actions and Effective vere identified duri eral, State or Loc	ing period.	
Landowner Issu				
	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action



Location: South Spread HDD bore site.

Notes: Removal of equipment from the South Spread HDD bore site.



Location: South Spread HDD bore site.

Notes: Fuel tank within adequate secondary containment at the South Spread HDD bore site.

 No work v 	vas completed du	ring this reporting p	period.	
Activ	ity	Total % Completed Th Period	% of Total Job Completed	Comments
Pipeline				
Clearing / Grading]		100%	
Stringing			100%	
Bending			100%	
Welding			100%	
Joint Coating			100%	
Ditching			100%	
Lowering			100%	
Backfill			100%	
Cleanup			100%	
Seeding			100%	Included applying straw mulch over seeded areas followed by a crimper to anchor the straw mulch.
Pig Launcher/Rec	eiver ⁸		2 of 2	Pig launcher/receivers completed
Bores			1 of 1	Bore completed
Hydrostatic Testin	g		100%	
Work Planned fo	r next Reporting	Period and Schee	dule Changes:	
		next reporting perio		
		ns and Effectivene		
		ntified during repor	<u>.</u> .	
•		ve Actions and E		
			ng reporting period.	
			al Permitting Agencies and ng reporting period.	a kesponse:
Copies included:	•		ng reporting period.	
Landowner Issue				
		Milepost /		
		Alignment		
Date	Name	Sheet #	Problem/Concern	Corrective Action

 $^{^{8}}$ Includes pig launcher/receivers at the Tioga Plant Receipt Station (MP 0.0) and the Tioga Compressor Station (MP 0.5).

	Elk	horn Creek to No	TABLE 1-6 orthern Border Interconnec	ct Pipeline
CompletedBegan cleaBegan see	ring Reporting F backfilling activit hydrostatically te n-up activities. ding along the rig	Period ies. sting pipeline. ht-of-way. Final s		d upon landowner preference, local soil
Activit	έ y	Total % Completed T Period	% of Total Job his Completed	Comments
Pipeline				
Clearing / Grading			100%	
Stringing			100%	
Bending			100%	
Welding			100%	
Joint Coating			100%	
Ditching			100%	
Lowering			100%	
Backfill		100%	100%	
Cleanup		63%	63%	
Seeding		5%	5%	
Block Valve		0 of 1	0 of 1	
Hydrostatic Testing		100%	100%	
Work Planned for Continue c Problem Areas, C	lean-up and seed	ing activities.	-	
No problem	n areas were ider	tified during repo	rting period.	
Non-Compliance	,		ffectiveness: ing reporting period.	
 No non-con Copies included: No 	mpliance issues v lot applicable	•	cal Permitting Agencies an ing reporting period.	d Response:
Landowner Issues	s: None			
Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action



Location: Elkhorn Creek to Northern Border Pipeline

Notes: Backfilling activities.



Date: 11/05/2021

Location: Elkhorn Creek to Northern Border Pipeline

Notes: Backfilling activities.



Location: Elkhorn Creek to Northern Border Pipeline

Notes: Final grading activities.

local soi • Comple	il conservation auth ted installing securi	ority recommendation to the second seco	ons, or applicable land ma	rates are based upon landowner preference, anagement agency requirements. No. 6.8 at 102nd Avenue NW. /.
Act	ivity	Total % Completed Th Period	is % of Total Job Completed	Comments
Pipeline				
Clearing / Gradi	ng		100%	
Stringing	0		100%	
Bending			100%	
Welding			100%	
Joint Coating			100%	
Ditching			100%	
Lowering			100%	
Backfill			100%	
Cleanup			100%	
Seeding		20%	100%	Included applying straw mulch over seeded areas followed by a crimper to anchor the straw mulch.
Pig Launcher/Re	eceiver ⁹		2 of 2	Pig launcher/receivers completed
Block Valves ¹⁰			2 of 2	Block Valves completed
Bores			27 of 27	Bores completed
Hydrostatic Test	ling		100%	
	for next Reporting		•	
	, Corrective Action lem areas were ide			
No non-		were identified duri	ng reporting period.	
No non- Copies included	compliance issues : Not applicable		al Permitting Agencies and reporting period.	and Response:
Landowner Iss	ues: None			
Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action
Bato				

⁹ Includes pig launcher/receivers at the Tioga Compressor Station (MP 0.0) and the Norse Transfer Station (MP 20.3).

¹⁰ Includes block valves at Valve No. 6.8 at 102nd Road (MP 6.9) and Valve No. 13.6 at 81st Street (MP 13.6).



Location: Sta. No. 360+00

Notes: Completed security fence for the Block Valve No. 6 at 102nd Avenue NW on the Line Section 25 Loop.



Date: 11/05/2021

Location: Sta. No. 360+00

Notes: Spread gravel within the security fence for the Block Valve No. 6 at 102nd Avenue NW on the Line Section 25 Loop.

© 140°SE (T) • 48°35'20.4", -102°51'12.0" ±4 m

Date: 11/03/2021

Location: Sta. No. 717+00

Notes: Installation of security fence for the Block Valve No. 13.6 at 81st Street NW on the Line Section 25 Loop.

		BLE 1-8	
	•	Line Section 25	
Work Completed during Reportin	•	in a sur Manualaus Manual	sh sa 4, 0004
 Completed tie-in activitie existing Line Section 25 (Completed backfilling act Completed seeding the right 	on November 2, 2021. ivities at all replacement pi ght-of-way at the 92 nd Aver	Avenue NW 8-inch rep pe locations. nue NW bore. Final se	placement pipeline via guided bore along the ed mix and rates are based upon landowner
 Began final grading, insta pipe locations. 	allation of erosion control b	lankets, and removal o	le land management agency requirements. f construction material at all replacement
			e. on of 8-inch Line Section 25 pipeline
Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline ¹¹			
Clearing / Grading		100%	
Stringing		100%	
Bending		100%	
Welding		100%	
Joint Coating		100%	
Ditching		100%	
Lowering		100%	
Backfill		100%	
Cleanup	5%	95%	
Seeding	33%	33%	Included applying straw mulch over seeded areas followed by a crimper to anchor the straw mulch.
Pig Launcher/Receiver ¹²		2 of 3	Pig launcher/receivers completed 1/
Bores ¹³		4 of 4	Bores completed
Hydrostatic Testing	25%	100%	· · ·
, .	e Lignite Plant Receipt Sta	tion had to be refabrica	ated and will be tied-in the week of
Work Planned for next Reportin Continue cleanup activitie	-	Changes:	
Transfer Stations.	•	peline right-of-way sou	th and east of Norse Plant and Norse
•	dentified during reporting p		
Non-Compliance Issues, Corre No non-compliance issue	ctive Actions and Effectives were identified during re		
Non-Compliance Issues from F No non-compliance issue Copies included: Not applicable	ederal, State or Local Pe es were identified during re		d Response:

¹¹ Includes replacing the existing 0.1 mile 6-inch-diameter Stoneview-Conoco Lateral with 0.1 mile of 8-inchdiameter natural gas pipeline from the Norse Transfer Station to the existing Line Section 25 and the replacing and rerouting about 0.1 mile of existing 8-inch-diameter pipeline from the 86th Street NW bore to the proposed Norse Transfer Station.

¹² Includes three 8-inch pig launcher/receivers for the existing Line Section 24 with one at the Lignite Receipt Station and two at the new Norse Transfer Station (one northbound and the other southbound).

¹³ Includes the replacement of about 0.4 mile of existing pipeline via the guided bore method at four county road crossings and one state highway crossing (92nd Street NW; 93rd Street NW/89th Avenue NW (both crossed by the same bore); 86th Street NW, and Highway 40).

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action



Location: 93rd Street NW / 89th Avenue NW bore crossing.

Notes: Drying of the 8-inch replacement pipeline at the end of the uprating of Line Section 25.



Date: 11/02/2021

Location: Southeast of Norse Transfer Station.

Notes: The removal of 8-inch Line Section 25 pipeline that was replaced with new 8inch pipeline. The old pipeline will be cut into 40-foot sections and removed.



Location: 92nd Street NW bore crossing (south side tie-in).

Notes: Padding and backfilling of the tiein of the 8-inch bore replacement pipeline to the existing Line Section 25.



Date: 11/03/2021

Location: The 6-inch Stoneview-Conoco Lateral south of Norse Plant Receipt Station.

Notes: The removal of the 6-inch pipeline.



Location: 92nd Street NW bore crossing.

Notes: Backfilling activities at the tie-in site of the 8-inch bore replacement pipeline to the existing Line Section 25.



Date: 11/04/2021

Location: 93rd Street NW / 89th Avenue NW bore crossing bore crossing (north side).

Notes: Backfilling activities at the tie-in site of the 8-inch bore replacement pipeline to the existing Line Section 25.



Location: 8-inch replacement pipeline east of Norse Transfer Station.

Notes: Backfilling activities are complete at the 0.1 mile 8-inch replacement pipeline east of the Norse Transfer Station.



Date: 11/06/2021


Location: 86th Street NW bore crossing (north side tie-in).

Notes: Backfilling activities are complete at the tie-in of the 8inch bore replacement pipeline.



Location: Highway 40 guided bore crossing (west side tie-in).

Notes: Backfilling activities are complete at the tie-in of the 8inch bore replacement pipeline.



Date: 11/06/2021

Location: Highway 40 guided bore crossing (east side tie-in).

Notes: Backfilling activities are complete at the tie-in of the 8inch bore replacement pipeline.



Location: 92nd Street NW bore crossing (south side tie-in).

Notes: Restoration of right-of-way for the 8-inch bore replacement pipeline.



Date: 11/06/2021

Location: 92nd Street NW bore crossing (north side tie-in).

Notes: Restoration of right-of-way for the 8-inch bore replacement pipeline.



Location: 92nd Street NW bore crossing (south side tie-in).

Notes: Installation of erosion control blanket at bar ditch for the 8-inch bore replacement pipeline.



Date: 11/06/2021

Location: 92nd Street NW bore crossing (south side tie-in).

Notes: Installation of erosion control blanket on hillside for the 8-inch bore replacement pipeline.



Location: 93rd Street NW / 89th Avenue NW bore crossing (south side tie-in).

Notes: Backfilling activities of the 8inch bore replacement pipeline.



Date: 11/06/2021

Location: 93rd Street NW / 89th Avenue NW bore crossing (north side tie-in).

Notes: Restoration of right-of-way for the 8-inch bore replacement pipeline.



Location: 93rd Street NW / 89th Avenue NW bore crossing (north side tie-in).

Notes: Completed seeding and began spreading mulch on the north side of the right-of-way for the 8-inch bore replacement pipeline.

C. <u>Construction Status – Aboveground Facilities</u>

Activ		101a	ul %	% of Total	Comments
	vity	Complet Peri		Job Completed	
Initial Site Work			100	100%	
Waste Systems		5%	%	85%	
Foundations & Concr	ete	0%	%	99%	Less than 1% work was completed and included pouring concrete for door stoops.
Installation of Building	js	19	%	71%	Included the continued construction of th Transfer, Compressor and Auxiliary buildings.
Installation of Piping		15'	%	75%	Included installation of piping to the Compressor and Transfer buildings and auxiliary piping installations.
Installation of Structural Supports		4%	%	74%	
Setting of Equipment		0%	%	90%	
Insulation		0%	%	0%	
Start-Up & Commissioning - Mechanical		0%	%	0%	
Start-Up & Commissioning - Electrical		0%	%	0%	
Cleanup / Restoration	ı	0%	%	0%	
Work Planned for ne			-		
				ural supports and s	setting of equipment.
Problem Areas, Cor					
	areas were identified	U	01		
Non-Compliance Iss	•				
	liance issues were				
Non-Compliance Iss	bliance issues were				tesponse:
Copies included: Not			ig reporting	penoa.	
Landowner Issues:	None				
		Milepost /			
D (Alignment			
Date	Name	Sheet #	Prob	em/Concern	Corrective Action

	ted all building construct ed installing piping, strue ed concrete activities.		ind equipment.	
	Activity	Total Complete Perio	d This Job	
Initial Site Work			100%	
Waste Systems		30%	6 100%	
Foundations & 0	Concrete	0%	99%	Less than 1% work was completed and included pouring concrete for sidewalks
Installation of Bu	uildings	149	6 100%	
Installation of Piping		14%	6 84%	Included installation of fuel gas and boile piping and piping in Compressor building
Installation of Structural Supports		5%	97%	
Setting of Equipment		1%		Included installation of boiler.
Insulation		0%	0%	
Start-Up & Commissioning - Mechanical		0%	0%	
Start-Up & Commissioning - Electrical		0%	0%	
Cleanup / Restoration		0%	÷	
Continu Problem Areas No prob	, Corrective Actions ar lem areas were identifie	stems, concrete d Effectivenes d during reportin	e, piping, structural supp s: ng period.	ports and setting of equipment.
•	ce Issues, Corrective A compliance issues were			
No non- Copies included				and Response:
Landowner Iss	ues: None	r		
		Milepost / Alignment Sheet #	Problem/Concer	n Corrective Action



Location: Elkhorn Creek Compressor Station

Notes: Poured concrete.



Date: 11/03/2021

Location: Elkhorn Creek Compressor Station

Notes: Trenching on south side of station.

Continue Removed	d cleanup activity v	vith spreading of addi		o Line Section 25. site. Clean fill dirt has been brought in to
Act	ivity	Total % Completed This Period	% of Total Job s Completed	Comments
Site Preparation			100%	
Facility Installation	on	1%	100%	Included meter building, odorization facilities and station piping. 1/
Cleanup		10%	90%	2/
Problem Areas, No proble Non-Compliance No non-compliance	em areas were ider e Issues, Correctiv compliance issues v e Issues from Fed	s and Effectiveness tified during reporting /e Actions and Effect vere identified during eral, State or Local I vere identified during) period. : tiveness: reporting period. Permitting Agencies and	Response:
•	•			
No non-c	Not applicable			




Location: Lignite Plant Receipt Station

Notes: Removal of contaminated soil discovered last week during excavation for tie-in activity.



Location: Lignite Plant Receipt Station

Notes: Stockpile of fill dirt to replace removed contaminated soil.



Date: 11/06/2021

Location: Lignite Plant Receipt Station

Notes: A new meter building (far right), odorization facilities (front right) and associated station piping.

Ac	tivity	Total % Completed T Period	% of Total Job This Completed	Comments
Site Preparation			100%	
Facility Installati	on		100%	Included meter building and remaining station piping.
Cleanup		15%	85%	1/
No prob Non-Compliance No non-		tified during repor /e Actions and Ef vere identified duri	ting period.	d Response:
No non- Copies included	compliance issues v Not applicable		ng reporting period.	
Landowner Iss	ues: None			
		Milepost / Alignment	Problem/Concern	Corrective Action

(northboi		0	pe between the Norse Tran	sfer Station and the pig launcher/receiver
Act	vity	Total % Completed T Period	% of Total Job This Completed	Comments
Site Preparation			100%	
Facility Installation	n	3%	100%	
Cleanup		15%	85%	1/
Continue Problem Areas, No proble Non-Compliance No non-c Non-Compliance	Corrective Actions of a Issues, Corrective ompliance issues were a Issues from Feder ompliance issues were Not applicable	Backfilling will be of a and Effectivene tified during repor re Actions and Effections and Effections rere identified duri aral, State or Loc	completed Monday, Noveml ess: ting period.	
Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action



Location: Norse Transfer Station

Notes: Tie-in of the 8-inch pipeline to a pig launcher/receiver (northbound). The Transfer Station is in the background.

			TABLE 3-4 rn Border Interconnect		
•	luring Reporting I was completed dur		period		
Acti	•	Total % Completed Period	% of Total Job	Comments	
Site Preparation		0%	99%	1/	
Facility Installatio	n		100%		
Cleanup		0%	99%		
No work is planned for the next reporting period. // The access road will be asphalted post facility construction. Problem Areas, Corrective Actions and Effectiveness: No problem areas were identified during reporting period. Non-Compliance Issues, Corrective Actions and Effectiveness: No non-compliance issues were identified during reporting period. Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response: No non-compliance issues were identified during reporting period. Copies included: Not applicable					
Landowner Issu Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action	

		Robinson	TABLE 3-5 Lake Plant Receipt Station	
•	uring Reporting Pe			
No work o	occurred during the r	eport period.		
Activ	vity	Total % Completed Period	/	Comments
Site Preparation			100%	
Facility Installation	า		100%	
Cleanup			100%	
No proble Non-Compliance No non-co Non-Compliance	Issues from Feder ompliance issues we Not applicable	fied during report Actions and E are identified dur ral, State or Loo	rting period.	d Response:
Landowner Issue	es: None	Milopoot /		
Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

•	during Reporting P was completed duri		riod.	
Act	ivity	Total % Completed Th Period	is % of Total Job Completed	Comments
Site Preparation		0%	0%	
Facility Installation	n	0%	0%	
Cleanup		0%	0%	
No proble Non-Compliance No non-c Non-Compliance	ompliance issues w Not applicable	tified during reportir e Actions and Effe ere identified during eral, State or Local	ng period. ectiveness: g reporting period. I Permitting Agencies and	Response:
Date	es: None Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

	occurred during the		1 1	
Act	ivity	Total % Completed This Period	% of Total Job Completed	Comments
Site Preparation			100%	
Facility Installation	on		100%	
Cleanup			100%	
No probl Non-Complianc No non-c Non-Complianc	em areas were iden e Issues, Correctiv compliance issues w e Issues from Fede compliance issues w Not applicable	rere identified during r	iveness: eporting period. ermitting Agencies and Rea	sponse:
		Milepost / Alignment	Problem/Concern	Corrective Action

TABLE 4 Changes to Stream Crossings or Work in Environmental Sensitive Areas

Schedule changes to stream crossings.

None during reporting period •

Schedule changes for work in other environmentally sensitive areas.

None during reporting period

		Waterbodies Crossed	
Approx. Milepost	Feature ID	Waterbody Name	Crossing Method
Tioga to Elkhorn Cre	eek		
0.8	s-wm-ea-001p	Unnamed tributary to Paulson Creek	Open Cut
2.4	s-wm-ea-002	Unnamed tributary to Dry Fork Creek	Open Cut
12.3	s-wm-ee-001	Unnamed tributary to Beaver Creek	Open Cut
18.2	s-wm-eb-002	Beaver Creek	GuidedBore
24.4	s-wm-eb-003p	Lake Sakakawea	HDD
25.7	o-mk-ee-001	NaturalPond	HDD
27.1	s-mk-eb-001	Unnamed tributary to Sand Creek	Open Cut
27.5	s-mk-ea-001	Unnamed tributary to Sand Creek	GuidedBore
29.0	s-mk-wa-001	Unnamed tributary to Tobacco Garden Creek	GuidedBore
30.3	s-mk-eb-002	Tobacco Garden Creek	GuidedBore
36.5	s-mk-ea-003	Tobacco Garden Creek	GuidedBore
39.2	s-mk-ea-002	Unnamed tributary to Tobacco Garden Creek	Open Cut
44.9	DSK_NHD_11	Timber Prong Creek	GuidedBore
44.9	DSK_NHD_5	Timber Prong Creek	GuidedBore
51.5	s-mk-eb-005	Northfork Creek	GuidedBore
52.4	s-lbt-001a	CherryCreek	GuidedBore
58.0	DSK_NHD_2	Unnamed tributary to Sevenmile Creek	Open Cut
Line Section 25 Loo	р		
13.4	s-bk-eb-001p	White Earth Creek	GuidedBore
Line Section 30 Loo	р		
7.2	s-wm-ea-002	Unnamed tributary to Dry Fork Creek	Open Cut
8.8	s-wm-ea-001p	Unnamed tributary to Paulson Creek	Open Cut
Tioga Compressor S	Station		
NA	o-wm-eb-001	Man-made pond	N/A
Yards	<u>.</u>		
EngetYard	o-mt-ee-001	Man-made pond	N/A

N 1	Netlands Crossed or Otherwise Affected	by Project
Approx. Milepost	Feature ID	Crossing Method
Tioga to Elkhorn Creek		
0.9	w-wm-ea-008e	Open Cut
12.8	w-wm-ee-001e	Open Cut
16.9	w-wm-eg-001e	Open Cut
18.0	w-wm-eb-008e	Open Cut
28.0	w-mk-ea-001e	Open Cut
29.3	w-mk-eb-002e	Open Cut
38.5	w-mk-ea-003e	Guided Bore
40.0	w-mk-ef-004e	Open Cut
41.5	w-mk-eb-003e	Open Cut
44.9	DSK_NWI_7	Guided Bore
47.0	w-mk-ea-004e	Guided Bore
51.0	w-mk-eb-004e	Open Cut

52.5	w-lbt-003	Open Cut
52.6	w-lbt-001b	Open Cut
52.6	w-lbt-001a	Open Cut
53.7	w-mk-wa-002e	Open Cut
55.0	w-mk-ef-007e	Open Cut
55.0	w-mk-wa-001e	Open Cut
55.7	w-mk-ef-008e	Open Cut
62.4	w-mk-eg-001	Open Cut
Line Section 25 Loop	· · · · · · · · · · · · · · · · · · ·	
0.7	w-wm-eb-002e	Guided Bore
4.7	w-wm-ea-002e	Open Cut
4.8	w-wm-ea-001e	Open Cut
9.8	w-mt-ea-001e	Open Cut
11.0	w-bk-ea-013	Open Cut
11.9	w-bk-ea-005e	Open Cut
11.9	w-bk-ea-006e	Open Cut
13.2	w-bk-ee-002e	Open Cut
13.5	w-bk-eb-001e	Guided Bore
14.8	w-bk-wa-001e	Guided Bore
16.0	w-bk-ea-003e	Open Cut
16.1	w-bk-ea-002e	Open Cut
16.3	w-bk-ea-001e	Guided Bore
Line Section 30 Loop		
0.0	w-wm-ee-002e	Open Cut
0.2	w-wm-ec-004e	Open Cut
0.3	w-wm-ec-005e	Open Cut
0.4	w-wm-ef-002e	Open Cut
5.8	w-wm-ec-003e	Open Cut
8.7	w-wm-ea-008e °	Open Cut
Uprating Existing Line		·
N/A	w-bk-ea-010e	GuidedBore
Access Roads	· · · · ·	
N/A	w-wm-eb-009e	N/A - Matting
Yards		-
N/A	w-wm-ef-004e	N/A - Matting
N/A	w-wm-ef-005e	N/A - Matting
	1	·