

WBI ENERGY TRANSMISSION, INC.

North Bakken Expansion Project

Appendix

Docket Nos. CP20-52-000 CP20-52-001

Table of Contents

A	. Construction Status - Pipeline Facilities	.2
	Williston-Tioga-Minot Reroute	.2
	Line Section 30 Loop	.4
	North Spread - Tioga-Elkhorn Creek Pipeline (MP 0.0 to 23.0)	. 5
	South Spread - Tioga-Elkhorn Creek Pipeline (MP 23 to 62.8)	.6
	Lake Sakakawea HDD - North Spread HDD Bore Site	. 8
	Lake Sakakawea HDD - South Spread HDD Bore Site	10
	Tioga Compressor Lateral	12
	Elkhorn Creek to Northern Border Interconnect Pipeline	15
	Line Section 25 Loop	17
	Uprates to Line Section 25	18
В.	Construction Status – Aboveground Facilities	19
	Tioga Compressor Station	19
	Elkhorn Creek Compressor Station	21
	Lignite Plant Receipt and Town Border Stations	28
	Norse Plant Receipt Station	30
	Norse Transfer Station	31
	Northern Border Interconnect	33
	Robinson Lake Plant Receipt Station	35
	Springbrook Plant Receipt Station	37
	Tioga Plant Receipt Station	38

Attachment A - Line Section 30 Loop Restoration Photos

Attachment B – North Spread - Tioga-Elkhorn Creek Pipeline Restoration Photos

Attachment C - South Spread - Tioga-Elkhorn Creek Pipeline Restoration Photos

Attachment D - Line Section 25 Loop Restoration Photos

Attachment E – Uprates to Line Section 25 Restoration Photos

A. Construction Status - Pipeline Facilities

Williston-Tioga-Minot Reroute

		LE 1-1 a-Minot Reroute	
Activity	Completed Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Clearing / Grading		100%	
Stringing		100%	
Bending		100%	
Welding		100%	
Joint Coating		100%	
Ditching		100%	
Lowering		100%	
Backfill		100%	
Cleanup		100%	
Seeding		0%	1/
Hydrostatic Testing		100%	
2022, the remainder of seeding will occur alon Problem Areas, Corrective A	gravel will be spread throughou g the fence line. ctions and Effectiveness:	the final restoration of the Tioga Comp ut the station yard, the security fence of	will be re-installed and re-
 No current issues are i weekly status reports. 	dentified. Any previous probler	n areas, corrective actions and effecti	veness were reported in
• •	rective Actions and Effective		
	ance issues are identified. Any orted in weekly status reports.	previous non-compliance issues, con	rective actions and
No current non-complia		nitting Agencies and Response: identified. Any previous non-complia tus reports	nce issues, corrective

Landowner Issues:

• No current landowner issues are identified. Any previous landowner issues and corrective actions were reported in weekly status reports.



Date: 7/27/2021

Location: Tioga Compressor Station – Williston- Tioga-Minot 12-inch Mainline Reroute.

Notes: Completed backfilling and grading of the rerouted 12-inch mainline.

Line Section 30 Loop

		BLE 1-2 ction 30 Loop	
Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Clearing / Grading		100%	·
Stringing		100%	
Bending		100%	
Welding		100%	
Joint Coating		100%	
Ditching		100%	
Lowering		100%	
Backfill		100%	
Cleanup		100%	
Seeding		100%	
Pig Launcher/Receiver ¹		2 of 2	Pig launcher/receivers completed 1/
Block Valve ²		1 of 1	Block Valve completed 1/
Bores		8 of 8	Bores completed
Hydrostatic Testing		100%	
Purging and Packing of Pipeline		100%	Completed purging and packing of the pipeline on December 22, 2021.
Iauncher/receiver in Spring Problem Areas, Corrective Action • No current issues are iden weekly status reports.	2022. Is and Effectiveness: tified. Any previous prob	lem areas, corrective a	ple Valve setting and the Nesson pig actions and effectiveness were reported in
effectiveness were reported	issues are identified. Ar I in weekly status reports	ny previous non-compl	iance issues, corrective actions and
Non-Compliance Issues from Fed			
No current non-compliance actions and effectiveness w			vious non-compliance issues, corrective
Landowner Issues:			
 No current landowner issue weekly status reports. 	s are identified. Any pre	vious landowner issue	s and corrective actions were reported in

Representative photos of construction/restoration.

See Attachment A for Line Section 30 Loop restoration photos.

¹ Includes a pig launcher/receiver at the Nesson valve setting (MP 0.0) and the Tioga Compressor Station (MP 9.6). Restoration included backfilling at both locations. The Nesson pig launcher/receiver and the Temple block valve will have a security fence installed around both facilities and gravel spread in Spring 2022 after the removal of the old block valve. Final restoration of the Tioga pig launcher/receiver will be completed in conjunction with the final restoration of the Tioga Compressor Station.

² The Temple Valve site (MP 0.0) was included as part of WBI Energy's response to Environmental Condition 5 of its June 8, 2021 Response to Environmental Conditions of Order Issuing Certificate (Attachment 5-1, Table 5A, Modification Reference ID LS30-1).

North Spread - Tioga-Elkhorn Creek	Pipeline (MP 0.0 to 23.0)

	TABLE oga-Elkhorn Creek Pipeling		0 23 0)
Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Clearing / Grading		100%	
Stringing		100%	
Bending		100%	
Welding		100%	
Joint Coating		100%	
Ditching		100%	
Lowering		100%	
Backfill		100%	
Cleanup		100%	
Seeding		100%	
Pig Launcher/Receiver ³		2 of 2	Pig launcher/receivers completed
Block Valve ⁴		1 of 1	Block valve completed
Bores		20 of 20	Bores completed
Hydrostatic Testing		100%	
Purging and Packing of Pipeline		0%	1/
completed the week of Janu Problem Areas, Corrective Action	ary 17, 2022. s and Effectiveness:		e Cherry Creek block valve will be ons and effectiveness were reported in
Non-Compliance Issues, Correctiv			and for the section of the section o
 No current non-compliance i effectiveness were reported 		previous non-compliar	nce issues, corrective actions and
Non-Compliance Issues from Fede No current non-compliance i actions and effectiveness we	ssues with an agency are	identified. Any previo	Response: us non-compliance issues, corrective
Landowner Issues:	<u> </u>		and corrective actions were reported in

See Attachment B for North Spread - Tioga-Elkhorn Creek Pipeline restoration photos.

³ Includes a pig launcher / receiver at the Tioga Compressor Station (MP 0.0) and at 104th Avenue NW (MP 6.2). Restoration included backfilling at both locations. Final restoration of the Tioga pig launcher/receiver will be completed in conjunction with the final restoration of the Tioga Compressor Station. The 104th Avenue pig launcher/receiver had a security fence installed and gravel spread.

⁴ Includes a block valve at 56th Avenue NW (MP 16.2). Restoration included backfilling, a security fence installed, and gravel spread.

South Spread - Tioga-Elkhorn Creek P	ipeline (MP 23 to 62.8)

Activity	Total %	% of Total Job	Comments
	Completed This Period	Completed	
Pipeline			
Clearing / Grading		100%	
Stringing		100%	
Bending		100%	
Welding		100%	
Joint Coating		100%	
Ditching		100%	
Lowering		100%	
Backfill		100%	
Cleanup		100%	
Seeding		100%	
Pig Launcher/Receiver ⁵		1 of 1	Pig launcher/receiver completed
Block Valves ⁶		3 of 3	Block Valves completed
Bores		38 of 38	Bores completed
Hydrostatic Testing		100%	·
Purging and Packing of Pipeline		30%	Completed purging and packing of the pipeline from the Elkhorn Creek Compressor Station to the Cherry Cree block valve on December 17, 2021.1/
Remaining Work 1/: • Purging and packing of the r Problem Areas, Corrective Action	s and Effectiveness:		
 No current issues are identif weekly status reports. 	ied. Any previous probl	em areas, corrective a	actions and effectiveness were reported in
Non-Compliance Issues, Correctiv	ve Actions and Effectiv	veness:	
 No current non-compliance i effectiveness were reported 	ssues are identified. Ar in weekly status reports	ny previous non-comp	liance issues, corrective actions and
 Non-Compliance Issues from Federation No current non-compliance in actions and effectiveness weat 	ssues with an agency a	re identified. Any pre-	d Response: vious non-compliance issues, corrective
Landowner Issues:			
 No current landowner issues weekly status reports. 	are identified. Any pre	vious landowner issue	es and corrective actions were reported in

See Attachment C for South Spread - Tioga-Elkhorn Creek Pipeline restoration photos.

Comprehensive photo documentation of the restored Tioga to Elkhorn Creek pipeline right-of-way was unable to be obtained between stations 1622+46 - 1914+65 (mileposts 30.7 - 36.3) and stations 2085+00 - 2290+00 (mileposts 39.5 - 43.4). Following satisfactory subsoil and topsoil replacement, grading, seeding, stabilizing, and other requisite restoration activities as observed by on-site environmental inspectors and compliance monitors, barbed wire fences were promptly re-installed across the project

⁵ Includes a pig launcher / receiver at the Elkhorn Compressor Station (MP 62.8). Restoration included backfilling. Final restoration of the Elkhorn pig launcher/receiver will be completed in conjunction with the final restoration of the Elkhorn Compressor Station.

⁶ Includes block valves at South Lake (MP 26.2), Highway 10 (MP 37.0) and Cherry Creek (MP 51.4). Restoration included backfilling, a security fence installed, and gravel spread at both locations. Page 6

right-of-way at landowners' requests due to the areas being utilized for livestock grazing. Multiple rows of barbed wire fences were installed delineating independently-owned tracts/properties, resulting in significant portions of the aforementioned areas being inaccessible by foot for the inspectors and monitors to safely photo document restoration statuses.

Lake Sakakawea HDD - North Spread HDD Bore Site

	Lake Sal	3LE 1-4a kakawea HDD f Lake Sakakawea	
Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Site Prep		100%	
Stringing		100%	
Bending		N/A	
Welding		100%	
Joint Coating		100%	
Pilot Hole Drilling		100%	The pilot hole intersect was completed or September 17, 2021.
Reaming Operations		100%	
Pipe Installation		100%	Completed on October 25, 2021.
Hydrostatic Testing		100%	
Remaining Work: None.			
 Problem Areas, Corrective A No current issues are i weekly status reports. 		em areas, corrective a	actions and effectiveness were reported in
Non-Compliance Issues, Cor	rective Actions and Effectiv	/eness:	
	ance issues are identified. An orted in weekly status reports		liance issues, corrective actions and
		re identified. Any prev	d Response: vious non-compliance issues, corrective
Landowner Issues:	· ·	·	
 No current landowner i weekly status reports. 	ssues are identified. Any pre	vious landowner issue	es and corrective actions were reported in



Date: 11/29/2021

Location: Sta. No. 1214+00

Notes: Status of restored right-of-way and North Spread HDD bore site.



Date: 11/29/2021

Location: Sta. No. 1215+50

Notes: Status of restored right-of-way and North Spread HDD bore site.

Lake Sakakawea HDD - South Spread HDD Bore Site

	Lake Sa	BLE 1-4b kakawea HDD f Lake Sakakawea	
Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Site Prep		100%	
Pilot Hole Drilling		100%	The pilot hole intersect was completed or September 17, 2021.
Reaming Operations		100%	
Swab Pass		100%	
Pull Back & Pipe Installation		100%	Completed on October 25, 2021.
Remaining Work: None. Problem Areas, Corrective Acti No current issues are ide: weekly status reports.		lem areas, corrective a	actions and effectiveness were reported in
•		ny previous non-compl	liance issues, corrective actions and
Non-Compliance Issues from F	ederal, State or Local Pe	rmitting Agencies an	d Response:
	e issues with an agency a were reported in weekly s		vious non-compliance issues, corrective
Landowner Issues:			
 No current landowner issu weekly status reports. 	ues are identified. Any pre	evious landowner issue	es and corrective actions were reported in



Date: 12/10/2021

Location: Sta. No. 1370+00

Notes: Status of restored right-of-way and South Spread HDD bore site.



Date: 12/10/2021

Location: Sta. No. 1371+00

Notes: Status of restored right-of-way and South Spread HDD bore site.

Tioga Compressor Lateral

		BLE 1-5 pressor Lateral	
Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Clearing / Grading		100%	
Stringing		100%	
Bending		100%	
Welding		100%	
Joint Coating		100%	
Ditching		100%	
Lowering		100%	
Backfill		100%	
Cleanup		100%	
Seeding		100%	
Pig Launcher/Receiver ⁷		2 of 2	Pig launcher/receivers completed
Bores		1 of 1	Bore completed
Hydrostatic Testing		100%	•
Purging and Packing of Pipeline		100%	The purging and packing of the lateral was completed the week of January 10, 2022
Remaining Work: • None. Problem Areas, Corrective Action • No current issues are identive weekly status reports.		lem areas, corrective a	actions and effectiveness were reported in
 Non-Compliance Issues, Correcti No current non-compliance effectiveness were reported 	issues are identified. A	ny previous non-compl	liance issues, corrective actions and
Non-Compliance Issues from Fed	leral, State or Local Pe issues with an agency a	rmitting Agencies an are identified. Any prev	d Response: <i>v</i> ious non-compliance issues, corrective
Landowner Issues:	· · ·	·	
 No current landowner issue weekly status reports. 	s are identified. Any pre	evious landowner issue	es and corrective actions were reported in

⁷ Includes pig launcher/receivers at the Tioga Plant Receipt Station (MP 0.0) and the Tioga Compressor Station (MP 0.5). Restoration included backfilling at both locations. Final restoration of the Tioga Plant Receipt Station and the Tioga Compressor Station pig launcher/receivers will be completed in conjunction with the final restoration of the stations.



Date: 11/29/2021

Location: Sta. No. 7+36

Notes: Status of restored right-of-way.



Date: 11/29/2021

Location: Sta. No. 16+00


Notes: Status of restored right-of-way.

E SE SW W 210 240 270 0 182°S (T) O 48°24'10"N, 102°54'57"W ±13ft A 2301ft

Date: 11/29/2021

Location: Tioga Plant Receipt Station

Notes: New Tioga Compressor Lateral pig launcher/receiver.



Location: Tioga Compressor Station

Notes: New Tioga Compressor Lateral pig launcher/receiver.



Elkhorn Creek to Northern Border Interconnect Pipeline

Elk	TA horn Creek to Norther	BLE 1-6 n Border Interconnec	t Pipeline
Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Clearing / Grading		100%	
Stringing		100%	
Bending		100%	
Welding		100%	
Joint Coating		100%	
Ditching		100%	
Lowering		100%	
Backfill		100%	
Cleanup		100%	
Seeding		100%	
Block Valve		1 of 1	Block valve completed
Hydrostatic Testing		100%	
Purging and Packing of Pipeline		100%	Completed purging and packing of the pipeline on December 17, 2021.
Problem Areas, Corrective Action • No current issues are identif weekly status reports.		em areas, corrective a	ctions and effectiveness were reported in
Non-Compliance Issues, Correctiv	e Actions and Effectiv	veness:	
• •	ssues are identified. A	ny previous non-compl	iance issues, corrective actions and
Non-Compliance Issues from Fed	eral, State or Local Pe ssues with an agency a	rmitting Agencies and re identified. Any prev	d Response: ious non-compliance issues, corrective
Landowner Issues: • No current landowner issues weekly status reports.	are identified. Any pre	evious landowner issue	s and corrective actions were reported in



Date: 11/12/2021

Location: Elkhorn Creek to Northern Border Interconnect Pipeline

Notes: Status of rightof-way. The Elkhorn Creek Compressor Station is in the background and to the right.



Date: 12/21/2021

Location: Elkhorn Creek to Northern Border Interconnect Pipeline

Notes: Status of restored right-of-way. Elkhorn Creek Compressor Station to the right.

Line Section 25 Loop

		BLE 1-7 ction 25 Loop	
Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Clearing / Grading		100%	
Stringing		100%	
Bending		100%	
Welding		100%	
Joint Coating		100%	
Ditching		100%	
Lowering		100%	
Backfill		100%	
Cleanup		100%	
Seeding		100%	
Pig Launcher/Receiver ⁸		2 of 2	Pig launcher/receivers completed
Block Valves ⁹		2 of 2	Block Valves completed
Bores		27 of 27	Bores completed
Hydrostatic Testing		100%	
Purging and Packing of Pipeline		100%	Completed purging and packing of the pipeline the week of January 10, 2022
Remaining Work: • None. Problem Areas, Corrective Action • No current issues are identi weekly status reports.		em areas, corrective a	ctions and effectiveness were reported in
Non-Compliance Issues, Correcti	issues are identified. Ar	ny previous non-compl	iance issues, corrective actions and
Non-Compliance Issues from Fed No current non-compliance actions and effectiveness w	issues with an agency a	re identified. Any prev	d Response: rious non-compliance issues, corrective
Landowner Issues:	· ·	·	
 No current landowner issue weekly status reports. 	s are identified. Any pre	evious landowner issue	s and corrective actions were reported in

Representative photos of construction/restoration.

See Attachment D for South Spread - Tioga-Elkhorn Creek Pipeline restoration photos.

⁸ Includes pig launcher/receivers at the Tioga Compressor Station (MP 0.0) and the Norse Transfer Station (MP 20.3). Restoration included backfilling at both locations. Final restoration of the Line Section 25 pig launcher/receiver at the Tioga Compressor Station will be completed in conjunction with the final restoration of the station. The Norse Transfer Station pig launcher/receiver had a security fence installed and gravel spread in conjunction with the restoration of the Norse Transfer Station.

⁹ Includes block valves at Valve No. 6.8 at 102nd Road (MP 6.9) and Valve No. 13.6 at 81st Street (MP 13.6). Restoration included backfilling, a security fence installed, and gravel spread at each location.

Uprates to Line Section 25

		BLE 1-8 Line Section 25	
Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline ¹⁰			
Clearing / Grading		100%	
Stringing		100%	
Bending		100%	
Welding		100%	
Joint Coating		100%	
Ditching		100%	
Lowering		100%	
Backfill		100%	
Cleanup		100%	
Seeding		100%	
Pig Launcher/Receiver ¹¹		3 of 3	Pig launcher/receivers completed
Bores ¹²		4 of 4	Bores completed
Hydrostatic Testing		100%	
Remaining Work: • None. Problem Areas, Corrective Action • No current issues are iden weekly status reports.		em areas, corrective ac	tions and effectiveness were reported in
Non-Compliance Issues, Correc	e issues are identified. Ai	ny previous non-complia	nce issues, corrective actions and
Non-Compliance Issues from Fe	deral, State or Local Pe e issues with an agency a	rmitting Agencies and re identified. Any previo	Response: bus non-compliance issues, corrective
 Landowner Issues: No current landowner issu weekly status reports. 	es are identified. Any pre	evious landowner issues	and corrective actions were reported in

Representative photos of construction/restoration.

See Attachment E for Uprates to Line Section 25 restoration photos.

¹⁰ Includes replacing the existing 0.1 mile 6-inch-diameter Stoneview-Conoco Lateral with 0.1 mile of 8-inchdiameter natural gas pipeline from the Norse Transfer Station to the existing Line Section 25 and the replacing and rerouting about 0.1 mile of existing 8-inch-diameter pipeline from the 86th Street NW bore to the proposed Norse Transfer Station.

¹¹ Includes three 8-inch pig launcher/receivers for the existing Line Section 25 with one at the Lignite Receipt Station and two at the new Norse Transfer Station (one northbound and the other southbound). Restoration included backfilling with a security fence installed and gravel spread in conjunction with the restoration at each station.

¹² Includes the replacement of about 0.4 mile of existing pipeline via the guided bore method at four county road crossings and one state highway crossing (92nd Street NW; 93rd Street NW/89th Avenue NW (both crossed by the same bore); 86th Street NW, and Highway 40). Page 18

B. Construction Status – Aboveground Facilities

Tioga Compressor Station

	TABL Tioga Compre		
Activity	Total % Completed This Period	% of Total Job Completed	Comments
Initial Site Work		100%	
Waste Systems		100%	
Foundations & Concrete		100%	
Installation of Buildings		100%	
Installation of Piping		100%	
Installation of Structural Supports		100%	
Setting of Equipment		100%	
Insulation		100%	
Start-Up & Commissioning - Mechanical		100%	
Start-Up & Commissioning - Electrical		87%	Estimated completion the week of 1/17/2022.
Cleanup / Restoration		95%	1/
seeding along the fence line. Problem Areas, Corrective Actions and	Effectiveness:		avel, re-installing the security fence and re
 Non-Compliance Issues, Corrective Act No current non-compliance issues effectiveness were reported in week 	are identified. Any prev		issues, corrective actions and
Non-Compliance Issues from Federal, S			
 No current non-compliance issues and effectiveness were reported in 		tified. Any previous	non-compliance issues, corrective actions
Landowner Issues:			
 No current landowner issues are id status reports. 	dentified. Any previous I	andowner issues and	corrective actions were reported in week



Date: 12/08/2021

Location: Tioga Compressor Station

Notes: Erosion control devices are in place and properly functioning.



Date: 12/10/2021

Location: Tioga Compressor Station

Notes: New Units 2 and 3, and Unit 4 compressor buildings (right), new transfer building (tall building to the left), new auxiliary building (front and right of transfer building).





Date: 12/13/2021

Location: Tioga Compressor Station

Notes: New suction scrubbers and discharge coalescer (center) and new transfer building (right).

Date: 12/15/2021

Location: Tioga Compressor Station

Notes: New gas chromatograph building (front left.





Date: 12/19/2021

Location: Tioga Compressor Station

Notes: New Tioga Compressor Lateral pig launcher/receiver (left), transfer building and station ESD valves (right) and Unit 4 compressor building (background).

Elkhorn Creek Compressor Station

Activity	Elkhorn Creek Cor Total % Completed This Period	% of Total Job Completed	Comments
Initial Site Work		100%	
Waste Systems		100%	
Foundations & Concrete		100%	
Installation of Buildings		100%	
Installation of Piping		100%	
Installation of Structural Supports		100%	
Setting of Equipment		100%	
Insulation		100%	
Start-Up & Commissioning - Mechanical		100%	
Start-Up & Commissioning - Electrical		90%	Estimated completion the week of 1/24/2022.
Cleanup / Restoration		99%	1/
Pile of topsoil will be spread and re Problem Areas, Corrective Actions and	e-seeded in Spring 2022 Effectiveness:		2022 per the county highway requiremen as and effectiveness were reported in week
 Non-Compliance Issues, Corrective Act No current non-compliance issues effectiveness were reported in week 	are identified. Any prev		e issues, corrective actions and
 Non-Compliance Issues from Federal, S No current non-compliance issues and effectiveness were reported in 	with an agency are ider		sponse: non-compliance issues, corrective actions
Landowner Issues: No current landowner issues are id			d corrective actions were reported in week



Date: 11/27/2021

Location: Elkhorn Creek Compressor Station

Notes: Completed installation of security fence on the north side of station yard.



Date: 12/01/2021

Location: Elkhorn Creek Compressor Station

Notes: New Unit 1 compressor building (right), transfer building (background), auxiliary building (left) and associated station piping.



Date: 12/01/2021

Location: Elkhorn Creek Compressor Station

Notes: New Unit 1 compressor building (left), and transfer building (right).



Date: 12/12/2021

Location: Elkhorn Creek Compressor Station

Notes: New combination gas and engine jacket water cooler (left) and Unit 1 compressor building (center).



Date: 12/14/2021

Location: Elkhorn Creek Compressor Station

Notes: West wall of new transfer building with suction and discharge headers, ESD block valves and ESD blowdown valves.



Date: 12/14/2021

Location: Elkhorn Creek Compressor Station

Notes: New station piping and valves, transfer building (left), Unit 1 compressor building (background left), and auxiliary building (background right).

South Elevation

LAT: 47.675656 LON: -103.220053 ±16ft 2373ft



Date: 1/8/2022

Location: Elkhorn Creek Compressor Station

Notes: East wall of transfer building with suction scrubber to the left of building



Date: 1/8/2022

Location: Elkhorn Creek Compressor Station

Notes: New Unit 1 compressor building.

Lignite Plant Receipt and Town Border Stations

	TAE Lignite Plant Receipt an	LE 3-1 d Town Border Statio	ns 1/
Activity	Total % Completed This Period	% of Total Job Completed	Comments
Site Preparation		100%	
Facility Installation		100%	
Cleanup		96%	1/
No current issues are ide weekly status reports. Non-Compliance Issues, Corre	, , , ,		ons and effectiveness were reported in
	ce issues are identified. Any ted in weekly status reports.	/ previous non-compliar	nce issues, corrective actions and
Non-Compliance Issues from F	ederal, State or Local Perr	nitting Agencies and F	Response:
	ce issues with an agency are s were reported in weekly sta		us non-compliance issues, corrective
Landowner Issues:			
 No current landowner iss weekly status reports. 	ues are identified. Any prev	ious landowner issues a	and corrective actions were reported in

Representative photos of construction/restoration.



Date: 12/02/2021

Location: Lignite Plant Receipt Station

Notes: A new meter building (left), odorization facilities (right) and associated station piping.

 NE
 E
 SE
 S0


 30
 60
 90
 120
 150
 180

 Ithe (T) ● 48°52'23.5", -102°32'44.8" ±3 m ▲ 586 m

Date: 12/02/2021

Location: Lignite Plant Receipt Station

Notes: A new meter building (right), odorization facilities (front) and associated station piping.



Date: 12/02/2021

Location: Lignite Plant Receipt Station

Notes: New meter building and associated station piping.

Norse Plant Receipt Station

		ABLE 3-2 nt Receipt Station	
Activity	Total % Completed This Period	% of Total Job Completed	Comments
Site Preparation		100%	
Facility Installation		100%	
Cleanup		100%	
Remaining Work: • None Problem Areas, Corrective Actions • No current issues are identified weekly status reports.		olem areas, correctiv	e actions and effectiveness were reported in
Non-Compliance Issues, Corrective	e Actions and Effect	iveness:	
 No current non-compliance is effectiveness were reported i 			npliance issues, corrective actions and
Non-Compliance Issues from Fede	ral, State or Local Po	ermitting Agencies	and Response:
 No current non-compliance is actions and effectiveness we 			revious non-compliance issues, corrective
Landowner Issues: No current landowner issues weekly status reports.	are identified. Any pr	evious landowner iss	sues and corrective actions were reported in

Representative photos of construction/restoration.



Date: 11/22/2021 Location: Norse Plant Receipt Station

Notes: New meter building and associated station piping.

Norse Transfer Station

		BLE 3-3 ansfer Station	
Activity	Total % Completed This Period	% of Total Job Completed	Comments
Site Preparation		100%	
Facility Installation		100%	
Cleanup		100%	
weekly status reports.	ed. Any previous prob		e actions and effectiveness were reported in
 Non-Compliance Issues, Corrective No current non-compliance is effectiveness were reported in 	sues are identified. A	ny previous non-cor	npliance issues, corrective actions and
 Non-Compliance Issues from Fede No current non-compliance is actions and effectiveness were 	sues with an agency a	are identified. Any p	and Response: revious non-compliance issues, corrective
 Landowner Issues: No current landowner issues weekly status reports. 	are identified. Any pre	evious landowner iss	sues and corrective actions were reported in

Representative photos of construction/restoration.



Date: 11/22/2021

Location: Norse Transfer Station

Notes: New transfer building and associated station piping. The upgraded Norse Plant Receipt Station meter building is in background. Completed the installation of the security fence the week of December 13, 2021.



Date: 11/22/2021

Location: Norse Transfer Station

Notes: New transfer building and associated station piping.



Date: 12/13/2021

Location: Norse Plant Receipt and Norse Transfer Stations

Notes: Completed installation of a security fence around both stations.

Northern Border Interconnect

		BLE 3-4 der Interconnect	
Activity	Total % Completed This Period	% of Total Job Completed	Comments
Site Preparation		100%	
Facility Installation		100%	
Cleanup		99%	1/
weekly status reports	· ·		ons and effectiveness were reported in
No current non-comp	prective Actions and Effective liance issues are identified. Any ported in weekly status reports.		ce issues, corrective actions and
Non-Compliance Issues fro	m Federal, State or Local Peri	mitting Agencies and R	esponse:
	liance issues with an agency are ness were reported in weekly sta		s non-compliance issues, corrective
Landowner Issues:			
 No current landowner weekly status reports 		ious landowner issues a	nd corrective actions were reported in



Date: 12/01/2021

Location: Northern Border Interconnect

Notes: New RTU building (left) and pipeline (left).



Date: 12/21/2021

Location: Northern Border Interconnect

Notes: New facilities.

Robinson Lake Plant Receipt Station

		BLE 3-5 Iant Receipt Station	
Activity	Total % Completed This Period	% of Total Job Completed	Comments
Site Preparation		100%	
Facility Installation		100%	
Cleanup		100%	
weekly status reports.	ed. Any previous proble		ons and effectiveness were reported in
Non-Compliance Issues, Correctiv No current non-compliance i effectiveness were reported	ssues are identified. An	y previous non-compliane	ce issues, corrective actions and
 Non-Compliance Issues from Fede No current non-compliance i actions and effectiveness we 	ssues with an agency ar	e identified. Any previou	esponse: s non-compliance issues, corrective
 Landowner Issues: No current landowner issues weekly status reports. 	are identified. Any prev	vious landowner issues a	nd corrective actions were reported in

Representative photos of construction/restoration.



Date: 11/22/2021

Location: Robinson Lake Plant Receipt Station.

Notes: New meter building (far left) and associated station piping.



Date: 11/22/2021

Location: Robinson Lake Plant Receipt Station.

Notes: New security fence and spread gravel around facilities.



Date: 11/22/2021

Location: Robinson Lake Plant Receipt Station.

Notes: New security fence and spread gravel around facilities.

Springbrook Plant Receipt Station

ACII	vity	Total %		Comments
		Completed T Period	This Completed	
Site Preparation			0%	
Facility Installatio	n		0%	
Cleanup			0%	
No currer weekly st Non-Compliance No non-co Non-Compliance	atus reports. Issues, Correctiv ompliance issues v Issues from Fede	ied. Any previous ve Actions and Ef vere identified duri eral, State or Loc	problem areas, corrective a ffectiveness: ng reporting period. al Permitting Agencies and	ctions and effectiveness were reported in
No non-co Copies included: Landowner Issue	Not applicable	vere identified duri	ng reporting period.	
		Milepost / Alignment		

Tioga Plant Receipt Station

	_	Receipt Station	
Activity	Total % Completed This Period	% of Total Job Completed	Comments
Site Preparation		100%	
Facility Installation		100%	
Cleanup		99%	1/
Due to cold weather condition security fence will be completed as a security fence will be completed as	eted in the Spring 2022.		rity fence posts. The installation of the be spread in Spring 2022.
security fence will be compl Problem Areas, Corrective Action	eted in the Spring 2022.	Additional gravel will b	
 Due to cold weather conditions security fence will be complemented by the secure by the secure by the secure by the security fence will be co	eted in the Spring 2022. A is and Effectiveness: fied. Any previous proble	Additional gravel will b em areas, corrective a	e spread in Spring 2022.
Due to cold weather condition security fence will be complemented by the compleme	eted in the Spring 2022. A s and Effectiveness: fied. Any previous proble ve Actions and Effective issues are identified. Any	Additional gravel will b em areas, corrective a eness: y previous non-compl	e spread in Spring 2022.
Due to cold weather conditions security fence will be complemented by the complem	eted in the Spring 2022. A s and Effectiveness: fied. Any previous proble ve Actions and Effective issues are identified. Any in weekly status reports.	Additional gravel will b em areas, corrective a eness: y previous non-compl	e spread in Spring 2022. ctions and effectiveness were reported in ance issues, corrective actions and

Representative photos of construction/restoration.



Date: 11/29/2021

Location: Tioga Plant Receipt Station.

Notes: New odorant system (left), communications (middle) and meter (background) buildings, and associated station piping.



© 225°SW (T) ● 48°24'10"N, 102°54'56"W ±13ft ▲ 2291ft



Date: 11/29/2021

Location: Tioga Plant Receipt Station.

Notes: New pig launcher/receiver (right) meter building (center background), and associated station piping.