

1250 West Century Avenue Mailing Address: P.O. Box 5601 Bismarck, ND 58506-5601 (701) 530-1600

January 6, 2022

Kimberly D. Bose, Secretary Federal Energy Regulatory Commission 888 First Street, N.E., Room 1A Washington, D.C. 20426

Re: WBI Energy Transmission, Inc. Docket Nos. CP20-52-000 and CP20-52-001 North Bakken Expansion Project

Weekly Status Report No. 31

Dear Ms. Bose:

WBI Energy Transmission, Inc. (WBI Energy) herewith submits its Weekly Status Report No. 31 for the North Bakken Expansion Project, in compliance with Environmental Condition 8 of the Appendix to the Federal Energy Regulatory Commission's June 1, 2021 Order Issuing Certificate in the above referenced dockets.

The attached report addresses the period December 27, 2021 to January 2, 2021.

Should you have any questions or comments regarding this filing, please call the undersigned at (701) 530-1563.

Sincerely,

/s/ Lori Myerchin

Lori Myerchin Director, Regulatory Affairs and Transportation Services

Courtesy Copies:

Dawn Ramsey, FERC



WBI Energy Transmission, Inc. North Bakken Expansion Project Status Report No. 31 FERC Docket Nos. CP20-52-000 CP20-52-001

Reporting Period: December 27, 2021 through January 2, 2022

A. Update on Federal Authorizations

WBI Energy has obtained all necessary federal permits and authorizations required for construction of the North Bakken Expansion Project.

B. Construction Status - Pipeline Facilities

• Continued maintaining erosion control devices around Project sites.

TABLE 1-1 Williston-Tioga-Minot Reroute ¹

Work Completed during Reporting Period

• No work was completed during this reporting period.

Activity	Completed Total % Completed This Period	% of Total Job Completed	Comments	
Pipeline				
Clearing / Grading		100%		
Stringing		100%		
Bending		100%		
Welding		100%		
Joint Coating		100%		
Ditching		100%		
Lowering		100%		
Backfill		100%		
Cleanup		100%		
Seeding	0%	0%	1/	
Hydrostatic Testing		100%		

^{1/} Final restoration will be completed in conjunction with the final restoration of the Tioga Compressor Station. The security fence will be re-installed and re-seeding along the fence will occur in Spring 2022.

Work Planned for next Reporting Period and Schedule Changes:

• No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable.

¹ This reroute was included as part of WBI Energy's response to Environmental Condition 5 of its June 8, 2021 Response to Environmental Conditions of Order Issuing Certificate (Attachment 5-1, Table 5A, Modification Reference ID AF-1).

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

TABLE 1-2 Line Section 30 Loop

Work Completed during Reporting Period:

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Clearing / Grading		100%	
Stringing		100%	
Bending		100%	
Welding		100%	
Joint Coating		100%	
Ditching		100%	
Lowering		100%	
Backfill		100%	
Cleanup		100%	
Seeding		100%	
Pig Launcher/Receiver ²		2 of 2	Pig launcher/receivers completed
Block Valve ³		1 of 1	Block Valve completed
Bores		8 of 8	Bores completed
Hydrostatic Testing		100%	

Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness: Possible:

No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Landowner issu	Landowner issues. None						
Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action			

² Includes a pig launcher / receiver at the Nesson valve setting (MP 0.0) and the Tioga Compressor Station (MP 9.6). Restoration included backfilling at both locations. The Nesson pig launcher/receiver and the Temple block valve will have a security fence installed around both facilities and gravel spread in Spring 2022 after the removal of the old block valve. Final restoration of the Tioga pig launcher/receiver will be completed in conjunction with the final restoration of the Tioga Compressor Station.


³ The Temple Valve site (MP 0.0) was included as part of WBI Energy's response to Environmental Condition 5 of its June 8, 2021 Response to Environmental Conditions of Order Issuing Certificate (Attachment 5-1, Table 5A, Modification Reference ID LS30-1).



Date: 1/1/2022

Location: Sta. No. 1+00

Notes: The Nesson pig launcher/receiver, Temple Valve site and restored right-ofway remained frozen and stabilized.



Date: 1/1/2022

Location:

Sta. No. 168+85

TABLE 1-3a Tioga-Elkhorn Creek Pipeline- Spread 1 (MP 0.0 to 23.0)

Work Completed during Reporting Period:

No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Clearing / Grading		100%	
Stringing		100%	
Bending		100%	
Welding		100%	
Joint Coating		100%	
Ditching		100%	
Lowering		100%	
Backfill		100%	
Cleanup		100%	
Seeding		100%	
Pig Launcher/Receiver ⁴		2 of 2	Pig launcher/receivers completed
Block Valve ⁵		1 of 1	Block valve completed
Bores		20 of 20	Bores completed
Hydrostatic Testing		100%	

Work Planned for next Reporting Period and Schedule Changes:

• No work is planned for the next reporting period .

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

⁴ Includes a pig launcher / receiver at the Tioga Compressor Station (MP 0.0) and at 104th Avenue NW (MP 6.2).

⁵ Includes a block valve at 56th Avenue NW (MP 16.2).



Date: 1/1/2022

Location:

Sta. No. 486+69


Notes: Restored rightof-way remained frozen and stabilized.



Date: 1/1/2022

Location:

Sta. No. 487+09



Date: 1/1/2022

Location:

Sta. No. 1215+00

Notes: Restored rightof-way remained frozen and stabilized.



Date: 1/1/2022

Location:

Sta. No. 1216+00

TABLE 1-3b Tioga-Elkhorn Creek Pipeline- Spread 2 (MP 23.0 to 62.8)

Work Completed during Reporting Period:

No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Clearing / Grading		100%	
Stringing		100%	
Bending		100%	
Welding		100%	
Joint Coating		100%	
Ditching		100%	
Lowering		100%	
Backfill		100%	
Cleanup		100%	
Seeding		100%	
Pig Launcher/Receiver ⁶		1 of 1	Pig launcher/receiver completed
Block Valves ⁷		3 of 3	Block Valves completed
Bores		38 of 38	Bores completed
Hydrostatic Testing		100%	

Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness:

No problem areas were identified during reporting period

Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Landowner issue	Landowner issues. Notice					
Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action		

⁶ Includes a pig launcher / receiver at the Elkhorn Compressor Station (MP 62.8).

⁷ Includes block valves at South Lake (MP 26.2), Highway 10 (MP 37.0) and Cherry Creek (MP 51.4).



Date: 1/2/2022

Location:

Sta. No. 2510+00

Notes: Restored rightof-way remained frozen and stabilized.



Date: 1/2/2022

Location:

Sta. No. 2530+00

TABLE 1-4a Lake Sakakawea HDD North Side of Lake Sakakawea

Work Completed during Reporting Period

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Site Prep		100%	
Stringing		100%	
Bending	N/A	N/A	
Welding		100%	
Joint Coating		100%	
Pilot Hole Drilling		100%	The pilot hole intersect was completed on September 17, 2021.
Reaming Operations		100%	
Pipe Installation		100%	Completed on October 25, 2021.
Hydrostatic Testing		100%	

Work Planned for next Reporting Period and Schedule Changes:

• No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

TABLE 1-4b Lake Sakakawea HDD South Side of Lake Sakakawea

Work Completed during Reporting Period

• No work was completed during this reporting period.

	0 1 01		·
Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Site Prep		100%	
Pilot Hole Drilling		100%	The pilot hole intersect was completed on September 17, 2021.
Reaming Operations		100%	
Swab Pass		100%	
Pull Back & Pipe Installation		100%	Completed on October 25, 2021.

Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

TABLE 1-5 **Tioga Compressor Lateral**

Work Completed during Reporting Period:

No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Clearing / Grading		100%	
Stringing		100%	
Bending		100%	
Welding		100%	
Joint Coating		100%	
Ditching		100%	
Lowering		100%	
Backfill		100%	
Cleanup		100%	
Seeding		100%	
Pig Launcher/Receiver ⁸		2 of 2	Pig launcher/receivers completed
Bores		1 of 1	Bore completed
Hydrostatic Testing		100%	

Work Planned for next Reporting Period and Schedule Changes:

• No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Landowner iss	Landowner issues: None							
Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action				

⁸ Includes pig launcher/receivers at the Tioga Plant Receipt Station (MP 0.0) and the Tioga Compressor Station (MP 0.5).

TABLE 1-6 Elkhorn Creek to Northern Border Interconnect Pipeline

Work Completed during Reporting Period

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Clearing / Grading		100%	
Stringing		100%	
Bending		100%	
Welding		100%	
Joint Coating		100%	
Ditching		100%	
Lowering		100%	
Backfill		100%	
Cleanup		100%	
Seeding		100%	
Block Valve		1 of 1	Block valve completed
Hydrostatic Testing		100%	

Work Planned for next Reporting Period and Schedule Changes:

• No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

TABLE 1-7 Line Section 25 Loop

Work Completed during Reporting Period:

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Clearing / Grading		100%	
Stringing		100%	
Bending		100%	
Welding		100%	
Joint Coating		100%	
Ditching		100%	
Lowering		100%	
Backfill		100%	
Cleanup		100%	
Seeding		100%	
Pig Launcher/Receiver ⁹		2 of 2	Pig launcher/receivers completed
Block Valves ¹⁰		2 of 2	Block Valves completed
Bores		27 of 27	Bores completed
Hydrostatic Testing		100%	

Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:


• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Dete	Nome	Milepost / Alignment	Broklem/Company	Commontive Antique
Date	Name	Sheet #	Problem/Concern	Corrective Action

⁹ Includes pig launcher/receivers at the Tioga Compressor Station (MP 0.0) and the Norse Transfer Station (MP 20.3).

¹⁰ Includes block valves at Valve No. 6.8 at 102nd Road (MP 6.9) and Valve No. 13.6 at 81st Street (MP 13.6).



Date: 12/28/2021

Location:

Sta. No. 543+46

Notes: Restored rightof-way remained frozen and stabilized.



Date: 12/28/2021

Location:

Sta. No. 604+49

TABLE 1-8
Uprates to Line Section 25

Work Completed during Reporting Period:

No work was completed during this reporting period

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline ¹¹			
Clearing / Grading		100%	
Stringing		100%	
Bending		100%	
Welding		100%	
Joint Coating		100%	
Ditching		100%	
Lowering		100%	
Backfill		100%	
Cleanup		100%	
Seeding		100%	
Pig Launcher/Receiver 12		3 of 3	Pig launcher/receivers completed
Bores ¹³		4 of 4	Bores completed
Hydrostatic Testing		100%	

Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Landowner issi	Landowner Issues. Notice							
Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action				

¹¹ Includes replacing the existing 0.1 mile 6-inch-diameter Stoneview-Conoco Lateral with 0.1 mile of 8-inch-diameter natural gas pipeline from the Norse Transfer Station to the existing Line Section 25 and the replacing and rerouting about 0.1 mile of existing 8-inch-diameter pipeline from the 86th Street NW bore to the proposed Norse Transfer Station.

¹² Includes three 8-inch pig launcher/receivers for the existing Line Section 25 with one at the Lignite Receipt Station and two at the new Norse Transfer Station (one northbound and the other southbound).

¹³ Includes the replacement of about 0.4 mile of existing pipeline via the guided bore method at four county road crossings and one state highway crossing (92nd Street NW; 93rd Street NW/89th Avenue NW (both crossed by the same bore); 86th Street NW, and Highway 40).

C. <u>Construction Status – Aboveground Facilities</u>

TABLE 2-1 Tioga Compressor Station

Work Completed during Reporting Period:

- Completed the installation of piping, structural supports, and insulation.
- Continued pre-startup activities.
- Continued cleanup/restoration activities.

Softmadd distingly softmation assistance.					
Activity	Total % Completed This Period	% of Total Job Completed	Comments		
Initial Site Work		100%			
Waste Systems		100%			
Foundations & Concrete		100%			
Installation of Buildings		100%			
Installation of Piping	1%	100%			
Installation of Structural Supports	1%	100%			
Setting of Equipment		100%			
Insulation	19%	100%			
Start-Up & Commissioning - Mechanical		100%	Compressors are mechanically complete but await the introduction of natural gas for start-up. Continue to review any items remaining on mechanical checklist.		
Start-Up & Commissioning - Electrical	5%	85%	Continued electrical installation, pre-startup, and testing activities.		
Cleanup / Restoration	5%	95%	Continued spreading gravel and demobilizing equipment.		

Work Planned for next Reporting Period and Schedule Changes:

Continue pre-startup activities.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

No non-compliance issues were identified during reporting period.

$\label{lem:non-compliance} \textbf{Non-Compliance Issues from Federal}, \textbf{State or Local Permitting Agencies and Response:}$

No non-compliance issues were identified during reporting period.

Copies included: Not applicable

	Zandownor recedent tone							
	Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action			
1								

TABLE 2-2 Elkhorn Creek Compressor Station

Work Completed during Reporting Period:

- Completed the installation of insulation.
- Continued pre-startup activities.
- Continued cleanup/restoration activities.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Initial Site Work		100%	
Waste Systems		100%	
Foundations & Concrete		100%	
Installation of Buildings		100%	
Installation of Piping		100%	
Installation of Structural Supports		100%	
Setting of Equipment		100%	
Insulation	5%	100%	
Start-Up & Commissioning - Mechanical		100%	Compressor is mechanically complete but awaits the introduction of natural gas for start-up. Continue to review any items remaining on mechanical checklist.
Start-Up & Commissioning - Electrical	5%	85%	Continued pre-startup and testing activities.
Cleanup / Restoration		99%	Less than 1% work completed. Continue demobilizing equipment.1/

1/ Forty feet of the approach from the county highway will be asphalted in Spring 2022 per the county highway requirements.

Work Planned for next Reporting Period and Schedule Changes:

• Continue pre-startup activities.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

TABLE 3-1 Lignite Plant Receipt and Town Border Stations

Work Completed during Reporting Period:

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Site Preparation		100%	
Facility Installation		100%	Included meter building, odorization facilities and station piping. 1/
Cleanup	0%	96%	2/

^{1/} No new facilities at the Lignite Town Border station were installed other than a new 2-inch pipe to connect the border station to the new measurement facilities at the receipt station.

Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness:

No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Edita O Wilci 1990	Euroviile 1550cs. None						
Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action			

^{2/} Due to cold weather conditions, concrete can no longer be set for the security fence posts and the installation of the security fence around the Lignite Plant Receipt and Town Border Stations will be completed in the Spring 2022. Gravel has been spread.

TABLE 3-2 Norse Plant Receipt Station

Work Completed during Reporting Period:

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Site Preparation		100%	
Facility Installation		100%	
Cleanup		100%	

Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Landowner Issues: None

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

TABLE 3-3 Norse Transfer Station

Work Completed during Reporting Period:

No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Site Preparation		100%	
Facility Installation		100%	
Cleanup		100%	

Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness:

No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

TABLE 3-4 Northern Border Interconnect

Work Completed during Reporting Period:

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Site Preparation		100%	
Facility Installation		100%	
Cleanup	0%	99%	1/

1/ Fifty feet of the approach from the county highway will be asphalted in Spring 2022 per the county highway requirements.

Work Planned for next Reporting Period and Schedule Changes:

• No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Landowner Issues: None

		Milepost / Alignment		
Date	Name	Sheet #	Problem/Concern	Corrective Action

TABLE 3-5 Robinson Lake Plant Receipt Station

Work Completed during Reporting Period:

No work occurred during the report period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Site Preparation		100%	
Facility Installation		100%	
Cleanup		100%	

Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

TABLE 3-6 Springbrook Plant Receipt Station

Work Completed during Reporting Period

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Site Preparation	0%	0%	
Facility Installation	0%	0%	
Cleanup	0%	0%	

Work Planned for next Reporting Period and Schedule Changes:

• No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Landowner Issues: None

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

TABLE 3-7 Tioga Plant Receipt Station

Work Completed during Reporting Period

• No work occurred during the reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Site Preparation		100%	
Facility Installation		100%	
Cleanup		99%	1/

^{1/} Due to cold weather conditions, concrete can no longer be set for the security fence posts and the installation of the security fence will be completed in the Spring 2022. Additional gravel will be spread in Spring 2022.

Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

TABLE 4 Changes to Stream Crossings or Work in Environmental Sensitive Areas

Schedule changes to stream crossings.

None during reporting period

Schedule changes for work in other environmentally sensitive areas.

None during reporting period

Waterbodies Crossed				
Approx. Milepost	Feature ID	Waterbody Name	Crossing Method	
Tioga to Elkhorn Cro	eek			
0.8	s-wm-ea-001p	Unnamed tributary to Paulson Creek	Open Cut	
2.4	s-wm-ea-002	Unnamed tributary to Dry Fork Creek	Open Cut	
12.3	s-wm-ee-001	Unnamed tributary to Beaver Creek	Open Cut	
18.2	s-wm-eb-002	Beaver Creek	GuidedBore	
24.4	s-wm-eb-003p	Lake Sakakawea	HDD	
25.7	o-mk-ee-001	NaturalPond	HDD	
27.1	s-mk-eb-001	Unnamed tributary to Sand Creek	Open Cut	
27.5	s-mk-ea-001	Unnamed tributary to Sand Creek	GuidedBore	
29.0	s-mk-wa-001	Unnamed tributary to Tobacco Garden Creek	GuidedBore	
30.3	s-mk-eb-002	Tobacco Garden Creek	GuidedBore	
36.5	s-mk-ea-003	Tobacco Garden Creek	GuidedBore	
39.2	s-mk-ea-002	Unnamed tributary to Tobacco Garden Creek	Open Cut	
44.9	DSK_NHD_11	Timber Prong Creek	GuidedBore	
44.9	DSK_NHD_5	Timber Prong Creek	GuidedBore	
51.5	s-mk-eb-005	Northfork Creek	GuidedBore	
52.4	s-lbt-001a	CherryCreek	GuidedBore	
58.0	DSK_NHD_2	Unnamed tributary to Sevenmile Creek	Open Cut	
Line Section 25 Loo	р			
13.4	s-bk-eb-001p	White Earth Creek	GuidedBore	
Line Section 30 Loo	р			
7.2	s-wm-ea-002	Unnamed tributary to Dry Fork Creek	Open Cut	
8.8	s-wm-ea-001p	Unnamed tributary to Paulson Creek	Open Cut	
Tioga Compressor S	Station			
NA	o-wm-eb-001	Man-made pond	N/A	
Yards				
EngetYard	o-mt-ee-001	Man-made pond	N/A	

Wetlands Crossed or Otherwise Affected by Project			
Approx. Milepost	Feature ID	Crossing Method	
Tioga to Elkhorn Creek	·		
0.9	w-wm-ea-008e	Open Cut	
12.8	w-wm-ee-001e	Open Cut	
16.9	w-wm-eg-001e	Open Cut	
18.0	w-wm-eb-008e	Open Cut	
28.0	w-mk-ea-001e	Open Cut	
29.3	w-mk-eb-002e	Open Cut	
38.5	w-mk-ea-003e	Guided Bore	
40.0	w-mk-ef-004e	Open Cut	
41.5	w-mk-eb-003e	Open Cut	
44.9	DSK_NWI_7	Guided Bore	

47.0	w-mk-ea-004e	Guided Bore
51.0	w-mk-eb-004e	Open Cut
52.5	w-lbt-003	Open Cut
52.6	w-lbt-001b	Open Cut
52.6	w-lbt-001a	Open Cut
53.7	w-mk-wa-002e	Open Cut
55.0	w-mk-ef-007e	Open Cut
55.0	w-mk-wa-001e	Open Cut
55.7	w-mk-ef-008e	Open Cut
62.4	w-mk-eg-001	Open Cut
Line Section 25 Loop	-	
0.7	w-wm-eb-002e	Guided Bore
4.7	w-wm-ea-002e	Open Cut
4.8	w-wm-ea-001e	Open Cut
9.8	w-mt-ea-001e	Open Cut
11.0	w-bk-ea-013	Open Cut
11.9	w-bk-ea-005e	Open Cut
11.9	w-bk-ea-006e	Open Cut
13.2	w-bk-ee-002e	Open Cut
13.5	w-bk-eb-001e	Guided Bore
14.8	w-bk-wa-001e	Guided Bore
16.0	w-bk-ea-003e	Open Cut
16.1	w-bk-ea-002e	Open Cut
16.3	w-bk-ea-001e	Guided Bore
Line Section 30 Loop		
0.0	w-wm-ee-002e	Open Cut
0.2	w-wm-ec-004e	Open Cut
0.3	w-wm-ec-005e	Open Cut
0.4	w-wm-ef-002e	Open Cut
5.8	w-wm-ec-003e	Open Cut
8.7	w-wm-ea-008e °	Open Cut
Uprating Existing Line		
N/A	w-bk-ea-010e	GuidedBore
Access Roads		
N/A	w-wm-eb-009e	N/A - Matting
Yards		
N/A	w-wm-ef-004e	N/A - Matting
N/A	w-wm-ef-005e	N/A - Matting