



---

1250 West Century Avenue  
Mailing Address:  
P.O. Box 5601  
Bismarck, ND 58506-5601  
(701) 530-1600

June 8, 2021

Kimberly D. Bose, Secretary  
Federal Energy Regulatory Commission  
888 First Street, N.E., Room 1A  
Washington, D.C. 20426

Re: WBI Energy Transmission, Inc.  
Docket Nos. CP20-52-000 and CP20-52-001  
North Bakken Expansion Project  
Weekly Status Report No. 1

Dear Ms. Bose:

WBI Energy Transmission, Inc. (WBI Energy) herewith submits its Weekly Status Report No. 1 for the North Bakken Expansion Project, in compliance with Environmental Condition 8 of the Appendix to the Federal Energy Regulatory Commission's June 1, 2021 Order Issuing Certificate in the above referenced dockets.

The attached report addresses the period June 1, 2021 to June 8, 2021.

Should you have any questions or comments regarding this filing, please call the undersigned at (701) 530-1563.

Sincerely,

/s/ Lori Myerchin

Lori Myerchin  
Director, Regulatory Affairs and  
Transportation Services

Courtesy Copies:

Dawn Ramsey, FERC  
Shannon Crosley, FERC



**WBI Energy Transmission, Inc.**  
**North Bakken Expansion Project Status Report No. 1**  
**FERC Docket Nos. CP20-52-000**  
**CP20-52-001**

**Reporting Period:** June 1, 2021 through June 8, 2021

**A. Update on Federal Authorizations**

Please refer to WBI Energy’s response to Environmental Condition 10 filed with its June 8, 2021 Response to Environmental Conditions of Order Issuing Certificate. WBI Energy anticipates receiving the right-of-way grant from the U.S. Department of the Interior, Bureau of Land Management in June 2021.

**B. Construction Status - Pipeline Facilities**

<b>TABLE 1-1</b> <b>Williston-Tioga-Minot Reroute</b>				
<b>Work Completed during Reporting Period</b> <ul style="list-style-type: none"> <li>No work was completed during this reporting period. Please refer to this reroute included as part of WBI Energy's response to Environmental Condition 5 of its June 8, 2021 Response to Environmental Conditions of Order Issuing Certificate (Attachment 5-1, Table 5A, Modification Reference ID AF-1).</li> </ul>				
Activity	Total % Completed This Period	% of Total Job Completed	Comments	
<b>Pipeline</b>				
Clearing / Grading	0%	0%		
Stringing	0%	0%		
Bending	0%	0%		
Welding	0%	0%		
Joint Coating	0%	0%		
Ditching	0%	0%		
Lowering	0%	0%		
Backfill	0%	0%		
Cleanup	0%	0%		
Seeding	0%	0%		
Hydrostatic Testing	0%	0%		
<b>Work Planned for next Reporting Period and Schedule Changes:</b> <ul style="list-style-type: none"> <li>No work is planned for the next reporting period.</li> </ul>				
<b>Problem Areas, Corrective Actions and Effectiveness:</b> <ul style="list-style-type: none"> <li>No problem areas were identified during reporting period.</li> </ul>				
<b>Non-Compliance Issues, Corrective Actions and Effectiveness:</b> <ul style="list-style-type: none"> <li>No non-compliance during reporting period.</li> </ul>				
<b>Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:</b> <ul style="list-style-type: none"> <li>No non-compliance during reporting period.</li> </ul> Copies included: Not applicable.				
<b>Landowner Issues:</b>				
<b>Date</b>	<b>Name</b>	<b>Milepost / Alignment Sheet #</b>	<b>Problem/Concern</b>	<b>Corrective Action</b>

**TABLE 1-2  
Line Section 30 Loop**

**Work Completed during Reporting Period**

- No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
<b>Pipeline</b>			
Clearing / Grading	0%	0%	
Stringing	0%	0%	
Bending	0%	0%	
Welding	0%	0%	
Joint Coating	0%	0%	
Ditching	0%	0%	
Lowering	0%	0 %	
Backfill	0%	0%	
Cleanup	0%	0%	
Seeding	0%	0%	
Pig Launcher/Receiver	0 of 2	0 of 2	
Bores	0 of 8	0 of 8	
Hydrostatic Testing	0%	0%	

**Work Planned for next Reporting Period and Schedule Changes:**

- No work is planned for the next reporting period.

**Problem Areas, Corrective Actions and Effectiveness:**

- No problem areas were identified during reporting period.

**Non-Compliance Issues, Corrective Actions and Effectiveness:**

- No non-compliance during reporting period.

**Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:**

- No non-compliance during reporting period.

Copies included: Not applicable

**Landowner Issues:**

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

**TABLE 1-3a**  
**Tioga-Elkhorn Creek Pipeline- Spread 1 (MP 0.0 to 23.0)**

**Work Completed during Reporting Period**

- No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
<b>Pipeline</b>			
Clearing / Grading	0%	0%	
Stringing	0%	0%	
Bending	0%	0%	
Welding	0%	0%	
Joint Coating	0%	0%	
Ditching	0%	0%	
Lowering	0%	0 %	
Backfill	0%	0%	
Cleanup	0%	0%	
Seeding	0%	0%	
Pig Launcher/Receiver	0 of 2	0 of 2	
Block Valves	0 of 1	0 of 1	
Bores	0 of 4	0 of 4	
Hydrostatic Testing	0%	0%	

**Work Planned for next Reporting Period and Schedule Changes:**

- No work is planned for the next reporting period.

**Problem Areas, Corrective Actions and Effectiveness:**

- No problem areas were identified during reporting period.

**Non-Compliance Issues, Corrective Actions and Effectiveness:**

- No non-compliance during reporting period.

**Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:**

- No non-compliance during reporting period.

Copies included: Not applicable

**Landowner Issues:**

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

**TABLE 1-3b  
Tioga-Elkhorn Creek Pipeline- Spread 2 (MP 23.0 to 62.8)**

<b>Work Completed during Reporting Period</b>				
<ul style="list-style-type: none"> <li>No work was completed during this reporting period.</li> </ul>				
<b>Activity</b>	<b>Total % Completed This Period</b>	<b>% of Total Job Completed</b>	<b>Comments</b>	
<b>Pipeline</b>				
Clearing / Grading	0%	0%		
Stringing	0%	0%		
Bending	0%	0%		
Welding	0%	0%		
Joint Coating	0%	0%		
Ditching	0%	0%		
Lowering	0%	0 %		
Backfill	0%	0%		
Cleanup	0%	0%		
Seeding	0%	0%		
Pig Launcher/Receiver	0 of 1	0 of 1		
Block Valves	0 of 3	0 of 3		
Bores	0 of 51	0 of 51		
Hydrostatic Testing	0%	0%		
<b>Work Planned for next Reporting Period and Schedule Changes:</b>				
<ul style="list-style-type: none"> <li>No work is planned for the next reporting period.</li> </ul>				
<b>Problem Areas, Corrective Actions and Effectiveness:</b>				
<ul style="list-style-type: none"> <li>No problem areas were identified during reporting period.</li> </ul>				
<b>Non-Compliance Issues, Corrective Actions and Effectiveness:</b>				
<ul style="list-style-type: none"> <li>No non-compliance during reporting period.</li> </ul>				
<b>Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:</b>				
<ul style="list-style-type: none"> <li>No non-compliance during reporting period.</li> </ul> Copies included: Not applicable				
<b>Landowner Issues:</b>				
<b>Date</b>	<b>Name</b>	<b>Milepost / Alignment Sheet #</b>	<b>Problem/Concern</b>	<b>Corrective Action</b>

**TABLE 1-4a  
Lake Sakakawea HDD  
North Side of Lake Sakakawea**

**Work Completed during Reporting Period**

- No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
<b>Pipeline</b>			
Site Prep	0%	0%	
Stringing	0%	0%	
Bending	0%	0%	
Welding	0%	0%	
Joint Coating	0%	0%	
Pilot Hole Drilling	0%	0%	
Reaming Operations	0%	0 %	
Pipe Installation	0%	0%	
Hydrostatic Testing	0%	0%	

**Work Planned for next Reporting Period and Schedule Changes:**

- No work is planned for the next reporting period.

**Problem Areas, Corrective Actions and Effectiveness:**

- No problem areas were identified during reporting period.

**Non-Compliance Issues, Corrective Actions and Effectiveness:**

- No non-compliance during reporting period.

**Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:**

- No non-compliance during reporting period.

Copies included: Not applicable

**Landowner Issues:**

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

**TABLE 1-4b  
Lake Sakakawea HDD  
South Side of Lake Sakakawea**

**Work Completed during Reporting Period**

- No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
<b>Pipeline</b>			
Site Prep	0%	0%	
Pilot Hole Drilling	0%	0%	
Reaming Operations	0%	0 %	
Swab Pass	0%	0%	
Pull Back & Pipe Installation	0%	0%	

**Work Planned for next Reporting Period and Schedule Changes:**

- No work is planned for the next reporting period.

**Problem Areas, Corrective Actions and Effectiveness:**

- No problem areas were identified during reporting period.

**Non-Compliance Issues, Corrective Actions and Effectiveness:**

- No non-compliance during reporting period.

**Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:**

- No non-compliance during reporting period.

Copies included: Not applicable

**Landowner Issues:**

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

**TABLE 1-5  
Tioga Compressor Lateral**

**Work Completed during Reporting Period**

- No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
<b>Pipeline</b>			
Clearing / Grading	0%	0%	
Stringing	0%	0%	
Bending	0%	0%	
Welding	0%	0%	
Joint Coating	0%	0%	
Ditching	0%	0%	
Lowering	0%	0 %	
Backfill	0%	0%	
Cleanup	0%	0%	
Seeding	0%	0%	
Pig Launcher/Receiver	0 of 2	0 of 2	
Bores	0 of 1	0 of 1	
Hydrostatic Testing	0%	0%	

**Work Planned for next Reporting Period and Schedule Changes:**

- No work is planned for the next reporting period.

**Problem Areas, Corrective Actions and Effectiveness:**

- No problem areas were identified during reporting period.

**Non-Compliance Issues, Corrective Actions and Effectiveness:**

- No non-compliance during reporting period.

**Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:**

- No non-compliance during reporting period.

Copies included: Not applicable

**Landowner Issues:**

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action



**TABLE 1-6  
Elkhorn Creek to Northern Border Interconnect Pipeline**

**Work Completed during Reporting Period**

- No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
<b>Pipeline</b>			
Clearing / Grading	0%	0%	
Stringing	0%	0%	
Bending	0%	0%	
Welding	0%	0%	
Joint Coating	0%	0%	
Ditching	0%	0%	
Lowering	0%	0 %	
Backfill	0%	0%	
Cleanup	0%	0%	
Seeding	0%	0%	
Block Valves	0 of 1	0 of 1	
Hydrostatic Testing	0%	0%	

**Work Planned for next Reporting Period and Schedule Changes:**

No work is planned for the next reporting period.

**Problem Areas, Corrective Actions and Effectiveness:**

No problem areas were identified during reporting period.

**Non-Compliance Issues, Corrective Actions and Effectiveness:**

No non-compliance during reporting period.

**Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:**

- No non-compliance during reporting period.

Copies included: Not applicable

**Landowner Issues:**

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

**TABLE 1-7  
Line Section 25 Loop**

**Work Completed during Reporting Period**

- No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
<b>Pipeline</b>			
Clearing / Grading	0%	0%	
Stringing	0%	0%	
Bending	0%	0%	
Welding	0%	0%	
Joint Coating	0%	0%	
Ditching	0%	0%	
Lowering	0%	0 %	
Backfill	0%	0%	
Cleanup	0%	0%	
Seeding	0%	0%	
Pig Launcher/Receiver	0 of 2	0 of 2	
Block Valves	0 of 2	0 of 2	
Bores	0 of 27	0 of 27	
Hydrostatic Testing	0%	0%	

**Work Planned for next Reporting Period and Schedule Changes:**

- No work is planned for the next reporting period.

**Problem Areas, Corrective Actions and Effectiveness:**

- No problem areas were identified during reporting period.

**Non-Compliance Issues, Corrective Actions and Effectiveness:**

- No non-compliance during reporting period.

**Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:**

- No non-compliance during reporting period.

Copies included: Not applicable

**Landowner Issues:**

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

**TABLE 1-8  
Uprates to Line Section 25**

**Work Completed during Reporting Period**

- No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
<b>Pipeline</b>			
Clearing / Grading	0%	0%	
Stringing	0%	0%	
Bending	0%	0%	
Welding	0%	0%	
Joint Coating	0%	0%	
Ditching	0%	0%	
Lowering	0%	0 %	
Backfill	0%	0%	
Cleanup	0%	0%	
Seeding	0%	0%	
Pig Launcher/Receiver	0 of 3	0 of 3	
Bores	0 of 4	0 of 4	
Hydrostatic Testing	0%	0%	

**Work Planned for next Reporting Period and Schedule Changes:**

- No work is planned for the next reporting period.

**Problem Areas, Corrective Actions and Effectiveness:**

- No problem areas were identified during reporting period.

**Non-Compliance Issues, Corrective Actions and Effectiveness:**

- No non-compliance during reporting period.

**Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:**

- No non-compliance during reporting period.

Copies included: Not applicable

**Landowner Issues:**

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

**C. Construction Status – Aboveground Facilities**

**TABLE 2-1  
Tioga Compressor Station**

<b>Work Completed during Reporting Period</b>				
<ul style="list-style-type: none"> <li>No work was completed during this reporting period.</li> </ul>				
<b>Activity</b>	<b>Total % Completed This Period</b>	<b>% of Total Job Completed</b>	<b>Comments</b>	
Initial Site Work	0%	0%		
Waste Systems	0%	0%		
Foundations & Concrete	0%	0%		
Installation of Buildings	0%	0%		
Installation of Piping	0%	0%		
Installation of Structural Supports	0%	0%		
Setting of Equipment	0%	0%		
Insulation	0%	0%		
Start-Up & Commissioning - Mechanical	0%	0%		
Start-Up & Commissioning - Electrical	0%	0%		
Cleanup / Restoration	0%	0%		
<b>Work Planned for next Reporting Period and Schedule Changes:</b>				
<ul style="list-style-type: none"> <li>No work is planned for the next reporting period.</li> </ul>				
<b>Problem Areas, Corrective Actions and Effectiveness:</b>				
<ul style="list-style-type: none"> <li>No problem areas were identified during reporting period.</li> </ul>				
<b>Non-Compliance Issues, Corrective Actions and Effectiveness:</b>				
<ul style="list-style-type: none"> <li>No non-compliance during reporting period.</li> </ul>				
<b>Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:</b>				
<ul style="list-style-type: none"> <li>No non-compliance during reporting period.</li> </ul> Copies included: Not applicable				
<b>Landowner Issues:</b>				
<b>Date</b>	<b>Name</b>	<b>Milepost / Alignment Sheet #</b>	<b>Problem/Concern</b>	<b>Corrective Action</b>

**TABLE 2-2  
Elkhorn Creek Compressor Station**

**Work Completed during Reporting Period**

- No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Initial Site Work	0%	0%	
Waste Systems	0%	0%	
Foundations & Concrete	0%	0%	
Installation of Buildings	0%	0%	
Installation of Piping	0%	0%	
Installation of Structural Supports	0%	0%	
Setting of Equipment	0%	0%	
Insulation	0%	0%	
Start-Up & Commissioning - Mechanical	0%	0%	
Start-Up & Commissioning - Electrical	0%	0%	
Cleanup / Restoration	0%	0%	

**Work Planned for next Reporting Period and Schedule Changes:**

- No work is planned for the next reporting period.

**Problem Areas, Corrective Actions and Effectiveness:**

- No problem areas were identified during reporting period.

**Non-Compliance Issues, Corrective Actions and Effectiveness:**

- No non-compliance during reporting period.

**Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:**

- No non-compliance during reporting period.

Copies included: Not applicable

**Landowner Issues:**

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

**TABLE 3-1  
Lignite Plant Receipt and Town Border Stations**

<b>Work Completed during Reporting Period</b>				
<ul style="list-style-type: none"> <li>No work was completed during this reporting period.</li> </ul>				
Activity	Total % Completed This Period	% of Total Job Completed	Comments	
Site Preparation	0%	0%		
Facility Installation	0%	0%		
Cleanup	0%	0%		
<b>Work Planned for next Reporting Period and Schedule Changes:</b>				
<ul style="list-style-type: none"> <li>No work is planned for the next reporting period.</li> </ul>				
<b>Problem Areas, Corrective Actions and Effectiveness:</b>				
<ul style="list-style-type: none"> <li>No problem areas were identified during reporting period.</li> </ul>				
<b>Non-Compliance Issues, Corrective Actions and Effectiveness:</b>				
<ul style="list-style-type: none"> <li>No non-compliance during reporting period.</li> </ul>				
<b>Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:</b>				
<ul style="list-style-type: none"> <li>No non-compliance during reporting period.</li> </ul> Copies included: Not applicable				
<b>Landowner Issues:</b>				
Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

**TABLE 3-2  
Norse Plant Receipt Station**

<b>Work Completed during Reporting Period</b>			
<ul style="list-style-type: none"> <li>No work was completed during this reporting period.</li> </ul>			
Activity	Total % Completed This Period	% of Total Job Completed	Comments
Site Preparation	0%	0%	
Facility Installation	0%	0%	
Cleanup	0%	0%	
<b>Work Planned for next Reporting Period and Schedule Changes:</b>			
<ul style="list-style-type: none"> <li>No work is planned for the next reporting period.</li> </ul>			
<b>Problem Areas, Corrective Actions and Effectiveness:</b>			
<ul style="list-style-type: none"> <li>No problem areas were identified during reporting period.</li> </ul>			
<b>Non-Compliance Issues, Corrective Actions and Effectiveness:</b>			
<ul style="list-style-type: none"> <li>No non-compliance during reporting period.</li> </ul>			
<b>Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:</b>			
<ul style="list-style-type: none"> <li>No non-compliance during reporting period.</li> </ul> Copies included: Not applicable			

**Landowner Issues:**

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

TABLE 3-3 Norse Transfer Station				
<b>Work Completed during Reporting Period</b>				
<ul style="list-style-type: none"> <li>No work was completed during this reporting period.</li> </ul>				
Activity	Total % Completed This Period	% of Total Job Completed	Comments	
Site Preparation	0%	0%		
Facility Installation	0%	0%		
Cleanup	0%	0%		
<b>Work Planned for next Reporting Period and Schedule Changes:</b>				
<ul style="list-style-type: none"> <li>No work is planned for the next reporting period.</li> </ul>				
<b>Problem Areas, Corrective Actions and Effectiveness:</b>				
<ul style="list-style-type: none"> <li>No problem areas were identified during reporting period.</li> </ul>				
<b>Non-Compliance Issues, Corrective Actions and Effectiveness:</b>				
<ul style="list-style-type: none"> <li>No non-compliance during reporting period.</li> </ul>				
<b>Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:</b>				
<ul style="list-style-type: none"> <li>No non-compliance during reporting period.</li> </ul> Copies included: Not applicable				
<b>Landowner Issues:</b>				
Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

TABLE 3-4 Northern Border Interconnect			
<b>Work Completed during Reporting Period</b>			
<ul style="list-style-type: none"> <li>No work was completed during this reporting period.</li> </ul>			
Activity	Total % Completed This Period	% of Total Job Completed	Comments
Site Preparation	0%	0%	
Facility Installation	0%	0%	
Cleanup	0%	0%	
<b>Work Planned for next Reporting Period and Schedule Changes:</b>			
<ul style="list-style-type: none"> <li>No work is planned for the next reporting period.</li> </ul>			
<b>Problem Areas, Corrective Actions and Effectiveness:</b>			
<ul style="list-style-type: none"> <li>No problem areas were identified during reporting period.</li> </ul>			

**Non-Compliance Issues, Corrective Actions and Effectiveness:**

- No non-compliance during reporting period.

**Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:**

- No non-compliance during reporting period.

Copies included: Not applicable

**Landowner Issues:**

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

**TABLE 3-5  
Robinson Lake Plant Receipt Station**

**Work Completed during Reporting Period**

- No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Site Preparation	0%	0%	
Facility Installation	0%	0%	
Cleanup	0%	0%	

**Work Planned for next Reporting Period and Schedule Changes:**

- No work is planned for the next reporting period.

**Problem Areas, Corrective Actions and Effectiveness:**

- No problem areas were identified during reporting period.

**Non-Compliance Issues, Corrective Actions and Effectiveness:**

- No non-compliance during reporting period.

**Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:**

- No non-compliance during reporting period.

Copies included: Not applicable

**Landowner Issues:**

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

**TABLE 3-6  
Springbrook Plant Receipt Station**

**Work Completed during Reporting Period**

- No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Site Preparation	0%	0%	
Facility Installation	0%	0%	
Cleanup	0%	0%	



<b>Work Planned for next Reporting Period and Schedule Changes:</b>				
<ul style="list-style-type: none"> <li>No work is planned for the next reporting period.</li> </ul>				
<b>Problem Areas, Corrective Actions and Effectiveness:</b>				
<ul style="list-style-type: none"> <li>No problem areas were identified during reporting period.</li> </ul>				
<b>Non-Compliance Issues, Corrective Actions and Effectiveness:</b>				
<ul style="list-style-type: none"> <li>No non-compliance during reporting period.</li> </ul>				
<b>Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:</b>				
<ul style="list-style-type: none"> <li>No non-compliance during reporting period.</li> </ul> Copies included: Not applicable				
<b>Landowner Issues:</b>				
<b>Date</b>	<b>Name</b>	<b>Milepost / Alignment Sheet #</b>	<b>Problem/Concern</b>	<b>Corrective Action</b>

<b>TABLE 3-7 Tioga Plant Receipt Station</b>			
<b>Work Completed during Reporting Period</b>			
<ul style="list-style-type: none"> <li>No work was completed during this reporting period.</li> </ul>			
<b>Activity</b>	<b>Total % Completed This Period</b>	<b>% of Total Job Completed</b>	<b>Comments</b>
Site Preparation	0%	0%	
Facility Installation	0%	0%	
Cleanup	0%	0%	
<b>Work Planned for next Reporting Period and Schedule Changes:</b>			
<ul style="list-style-type: none"> <li>No work is planned for the next reporting period.</li> </ul>			
<b>Problem Areas, Corrective Actions and Effectiveness:</b>			
<ul style="list-style-type: none"> <li>No problem areas were identified during reporting period.</li> </ul>			
<b>Non-Compliance Issues, Corrective Actions and Effectiveness:</b>			
<ul style="list-style-type: none"> <li>No non-compliance during reporting period.</li> </ul>			
<b>Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:</b>			
<ul style="list-style-type: none"> <li>No non-compliance during reporting period.</li> </ul> Copies included: Not applicable			
<b>Landowner Issues:</b>			
<b>Date</b>	<b>Name</b>	<b>Milepost / Alignment Sheet #</b>	<b>Problem/Concern</b>