

1250 West Century Avenue Mailing Address: P.O. Box 5601 Bismarck, ND 58506-5601 (701) 530-1600

June 16, 2021

Kimberly D. Bose, Secretary Federal Energy Regulatory Commission 888 First Street, N.E., Room 1A Washington, D.C. 20426

Re: WBI Energy Transmission, Inc. Docket Nos. CP20-52-000 and CP20-52-001 North Bakken Expansion Project Weekly Status Report No. 2

Dear Ms. Bose:

WBI Energy Transmission, Inc. (WBI Energy) herewith submits its Weekly Status Report No. 2 for the North Bakken Expansion Project, in compliance with Environmental Condition 8 of the Appendix to the Federal Energy Regulatory Commission's June 1, 2021 Order Issuing Certificate in the above referenced dockets.

The attached report addresses the period June 9, 2021 to June 13, 2021.

Should you have any questions or comments regarding this filing, please call the undersigned at (701) 530-1563.

Sincerely,

/s/ Lori Myerchin

Lori Myerchin Director, Regulatory Affairs and Transportation Services

Courtesy Copies:

Dawn Ramsey, FERC Shannon Crosley, FERC



# WBI Energy Transmission, Inc. North Bakken Expansion Project Status Report No. 2 FERC Docket Nos. CP20-52-000 CP20-52-001

**Reporting Period:** June 9, 2021 through June 13, 2021

#### A. Update on Federal Authorizations

Please refer to WBI Energy's response to Environmental Condition 10 filed with its June 8, 2021 Response to Environmental Conditions of Order Issuing Certificate. WBI Energy has not yet received the right-of-way grant from the U.S. Department of the Interior, Bureau of Land Management and anticipates receiving such grant in June 2021.

# **B.** Construction Status - Pipeline Facilities

Work Completed during R		-Minot Reroute <sup>1</sup>	
	pleted during this reporting period.		
Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Clearing / Grading	0%	0%	
Stringing	0%	0%	
Bending	0%	0%	
Welding	0%	0%	
Joint Coating	0%	0%	
Ditching	0%	0%	
Lowering	0%	0%	
Backfill	0%	0%	
Cleanup	0%	0%	
Seeding	0%	0%	
Hydrostatic Testing	0%	0%	

# Work Planned for next Reporting Period and Schedule Changes:

• No work is planned for the next reporting period.

# **Problem Areas, Corrective Actions and Effectiveness:**

No problem areas were identified during reporting period.

#### Non-Compliance Issues, Corrective Actions and Effectiveness:

No non-compliance issues were identified during reporting period.

# Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

No non-compliance issues were identified during reporting period.

Copies included: Not applicable.

<sup>&</sup>lt;sup>1</sup> This reroute was included as part of WBI Energy's response to Environmental Condition 5 of its June 8, 2021 Response to Environmental Conditions of Order Issuing Certificate (Attachment 5-1, Table 5A, Modification Reference ID AF-1).

#### Landowner Issues:

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

#### TABLE 1-2 Line Section 30 Loop

#### **Work Completed during Reporting Period**

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Clearing / Grading	0%	0%	
Stringing	0%	0%	
Bending	0%	0%	
Welding	0%	0%	
Joint Coating	0%	0%	
Ditching	0%	0%	
Lowering	0%	0%	
Backfill	0%	0%	
Cleanup	0%	0%	
Seeding	0%	0%	
Pig Launcher/Receiver	0 of 2	0 of 2	
Bores	0 of 8	0 of 8	
Hydrostatic Testing	0%	0%	

# Work Planned for next Reporting Period and Schedule Changes:

• No work is planned for the next reporting period.

#### **Problem Areas, Corrective Actions and Effectiveness:**

No problem areas were identified during reporting period.

#### Non-Compliance Issues, Corrective Actions and Effectiveness:

No non-compliance issues were identified during reporting period.

#### Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

#### TABLE 1-3a Tioga-Elkhorn Creek Pipeline- Spread 1 (MP 0.0 to 23.0)

#### Work Completed during Reporting Period

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Clearing / Grading	0%	0%	
Stringing	0%	0%	
Bending	0%	0%	
Welding	0%	0%	
Joint Coating	0%	0%	
Ditching	0%	0%	
Lowering	0%	0%	
Backfill	0%	0%	
Cleanup	0%	0%	
Seeding	0%	0%	
Pig Launcher/Receiver	0 of 2	0 of 2	
Block Valves	0 of 1	0 of 1	
Bores	0 of 4	0 of 4	
Hydrostatic Testing	0%	0%	

#### Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period.

#### **Problem Areas, Corrective Actions and Effectiveness:**

• No problem areas were identified during reporting period.

#### Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

# Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

#### TABLE 1-3b Tioga-Elkhorn Creek Pipeline- Spread 2 (MP 23.0 to 62.8)

#### Work Completed during Reporting Period

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Clearing / Grading	0%	0%	
Stringing	0%	0%	
Bending	0%	0%	
Welding	0%	0%	
Joint Coating	0%	0%	
Ditching	0%	0%	
Lowering	0%	0%	
Backfill	0%	0%	
Cleanup	0%	0%	
Seeding	0%	0%	
Pig Launcher/Receiver	0 of 1	0 of 1	
Block Valves	0 of 3	0 of 3	
Bores	0 of 51	0 of 51	
Hydrostatic Testing	0%	0%	

#### Work Planned for next Reporting Period and Schedule Changes:

• No work is planned for the next reporting period.

#### **Problem Areas, Corrective Actions and Effectiveness:**

No problem areas were identified during reporting period.

#### Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

# Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

#### TABLE 1-4a Lake Sakakawea HDD North Side of Lake Sakakawea

#### Work Completed during Reporting Period

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments				
Pipeline							
Site Prep	0%	0%					
Stringing	0%	0%					
Bending	0%	0%					
Welding	0%	0%					
Joint Coating	0%	0%					
Pilot Hole Drilling	0%	0%					
Reaming Operations	0%	0%					
Pipe Installation	0%	0%					
Hydrostatic Testing	0%	0%					

# Work Planned for next Reporting Period and Schedule Changes:

• No work is planned for the next reporting period.

#### **Problem Areas, Corrective Actions and Effectiveness:**

• No problem areas were identified during reporting period.

#### Non-Compliance Issues, Corrective Actions and Effectiveness:

No non-compliance issues were identified during reporting period.

#### Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

#### TABLE 1-4b Lake Sakakawea HDD South Side of Lake Sakakawea

#### Work Completed during Reporting Period

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Site Prep	0%	0%	
Pilot Hole Drilling	0%	0%	
Reaming Operations	0%	0%	
Swab Pass	0%	0%	
Pull Back & Pipe Installation	0%	0%	

# Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period.

#### **Problem Areas, Corrective Actions and Effectiveness:**

No problem areas were identified during reporting period.

# Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

# Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

# TABLE 1-5 Tioga Compressor Lateral

#### **Work Completed during Reporting Period**

• No work was completed during this reporting period.

The work was completed during this reporting period.						
Activity	Total % Completed This Period	% of Total Job Completed	Comments			
Pipeline						
Clearing / Grading	0%	0%				
Stringing	0%	0%				
Bending	0%	0%				
Welding	0%	0%				
Joint Coating	0%	0%				
Ditching	0%	0%				
Lowering	0%	0%				
Backfill	0%	0%				
Cleanup	0%	0%				
Seeding	0%	0%				
Pig Launcher/Receiver	0 of 2	0 of 2				
Bores	0 of 1	0 of 1				
Hydrostatic Testing	0%	0%				

#### Work Planned for next Reporting Period and Schedule Changes:

• No work is planned for the next reporting period.

# **Problem Areas, Corrective Actions and Effectiveness:**

• No problem areas were identified during reporting period.

#### Non-Compliance Issues, Corrective Actions and Effectiveness:

No non-compliance issues were identified during reporting period.

# Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

# TABLE 1-6 Elkhorn Creek to Northern Border Interconnect Pipeline

#### Work Completed during Reporting Period

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Clearing / Grading	0%	0%	
Stringing	0%	0%	
Bending	0%	0%	
Welding	0%	0%	
Joint Coating	0%	0%	
Ditching	0%	0%	
Lowering	0%	0%	
Backfill	0%	0%	
Cleanup	0%	0%	
Seeding	0%	0%	
Block Valves	0 of 1	0 of 1	
Hydrostatic Testing	0%	0%	

#### Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period.

#### **Problem Areas, Corrective Actions and Effectiveness:**

No problem areas were identified during reporting period.

#### Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

#### Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

#### TABLE 1-7 Line Section 25 Loop

#### **Work Completed during Reporting Period**

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Clearing / Grading	0%	0%	
Stringing	0%	0%	
Bending	0%	0%	
Welding	0%	0%	
Joint Coating	0%	0%	
Ditching	0%	0%	
Lowering	0%	0%	
Backfill	0%	0%	
Cleanup	0%	0%	
Seeding	0%	0%	
Pig Launcher/Receiver	0 of 2	0 of 2	
Block Valves	0 of 2	0 of 2	
Bores	0 of 27	0 of 27	
Hydrostatic Testing	0%	0%	

#### Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period.

#### **Problem Areas, Corrective Actions and Effectiveness:**

• No problem areas were identified during reporting period.

# Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

# Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

#### TABLE 1-8 Uprates to Line Section 25

#### **Work Completed during Reporting Period**

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Clearing / Grading	0%	0%	
Stringing	0%	0%	
Bending	0%	0%	
Welding	0%	0%	
Joint Coating	0%	0%	
Ditching	0%	0%	
Lowering	0%	0%	
Backfill	0%	0%	
Cleanup	0%	0%	
Seeding	0%	0%	
Pig Launcher/Receiver	0 of 3	0 of 3	
Bores	0 of 4	0 of 4	
Hydrostatic Testing	0%	0%	

#### Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period.

#### **Problem Areas, Corrective Actions and Effectiveness:**

• No problem areas were identified during reporting period.

# Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

#### Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

# C. <u>Construction Status – Aboveground Facilities</u>

#### TABLE 2-1 Tioga Compressor Station

#### Work Completed during Reporting Period

No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Initial Site Work	0%	0%	
Waste Systems	0%	0%	
Foundations & Concrete	0%	0%	
Installation of Buildings	0%	0%	
Installation of Piping	0%	0%	
Installation of Structural Supports	0%	0%	
Setting of Equipment	0%	0%	
Insulation	0%	0%	
Start-Up & Commissioning - Mechanical	0%	0%	
Start-Up & Commissioning - Electrical	0%	0%	
Cleanup / Restoration	0%	0%	

#### Work Planned for next Reporting Period and Schedule Changes:

• No work is planned for the next reporting period.

#### **Problem Areas, Corrective Actions and Effectiveness:**

No problem areas were identified during reporting period.

#### Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

# Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

#### TABLE 2-2 Elkhorn Creek Compressor Station

#### **Work Completed during Reporting Period**

• No work was completed during this reporting period.

The french made descriptions and the repetiting periods						
Activity	Total % Completed This Period	% of Total Job Completed	Comments			
Initial Site Work	0%	0%				
Waste Systems	0%	0%				
Foundations & Concrete	0%	0%				
Installation of Buildings	0%	0%				
Installation of Piping	0%	0%				
Installation of Structural Supports	0%	0%				
Setting of Equipment	0%	0%				
Insulation	0%	0%				
Start-Up & Commissioning - Mechanical	0%	0%				
Start-Up & Commissioning - Electrical	0%	0%				
Cleanup / Restoration	0%	0%				

# Work Planned for next Reporting Period and Schedule Changes:

• No work is planned for the next reporting period.

#### **Problem Areas, Corrective Actions and Effectiveness:**

• No problem areas were identified during reporting period.

#### Non-Compliance Issues, Corrective Actions and Effectiveness:

No non-compliance issues were identified during reporting period.

# Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

#### TABLE 3-1 Lignite Plant Receipt and Town Border Stations

#### Work Completed during Reporting Period

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Site Preparation	0%	0%	
Facility Installation	0%	0%	
Cleanup	0%	0%	

#### Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period.

#### **Problem Areas, Corrective Actions and Effectiveness:**

No problem areas were identified during reporting period.

#### Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

#### Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

No non-compliance issues were identified during reporting period.

Copies included: Not applicable

#### Landowner Issues:

	Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action
-					

#### TABLE 3-2 Norse Plant Receipt Station

#### **Work Completed during Reporting Period**

• No work was completed during this reporting period.

Activity Total % Completed This Period		% of Total Job Completed	Comments
Site Preparation	0%	0%	
Facility Installation	0%	0%	
Cleanup	0%	0%	

#### Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period.

#### **Problem Areas, Corrective Actions and Effectiveness:**

• No problem areas were identified during reporting period.

#### Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

#### Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

#### Landowner Issues:

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

#### TABLE 3-3 Norse Transfer Station

#### **Work Completed during Reporting Period**

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Site Preparation	0%	0%	
Facility Installation	0%	0%	
Cleanup	0%	0%	

# Work Planned for next Reporting Period and Schedule Changes:

• No work is planned for the next reporting period.

#### **Problem Areas, Corrective Actions and Effectiveness:**

No problem areas were identified during reporting period.

#### Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

#### Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

No non-compliance issues were identified during reporting period.

Copies included: Not applicable

# Landowner Issues:

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

#### TABLE 3-4 Northern Border Interconnect

#### Work Completed during Reporting Period

No work was completed during this reporting period.

The Work Was completed duffit	140 Work was completed daring the reporting period.								
Activity	Total % Completed This Period	% of Total Job Completed	Comments						
Site Preparation	0%	0%							
Facility Installation	0%	0%							
Cleanup	0%	0%							

# Work Planned for next Reporting Period and Schedule Changes:

• No work is planned for the next reporting period.

#### **Problem Areas, Corrective Actions and Effectiveness:**

No problem areas were identified during reporting period.

#### Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

#### Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

#### Landowner Issues:

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

# TABLE 3-5 Robinson Lake Plant Receipt Station

#### **Work Completed during Reporting Period**

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Site Preparation	0%	0%	
Facility Installation	0%	0%	
Cleanup	0%	0%	

#### Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period.

# **Problem Areas, Corrective Actions and Effectiveness:**

No problem areas were identified during reporting period.

# Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

#### Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

No non-compliance issues were identified during reporting period.

Copies included: Not applicable

#### Landowner Issues:

	Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action
L					
L					

# TABLE 3-6 Springbrook Plant Receipt Station

#### **Work Completed during Reporting Period**

No work was completed during this reporting period

• No work was completed during this reporting period.							
Activity	Total % Completed This Period	% of Total Job Completed	Comments				
Site Preparation	0%	0%					
Facility Installation	0%	0%					
Cleanup	0%	0%					

# Work Planned for next Reporting Period and Schedule Changes:

• No work is planned for the next reporting period.

#### **Problem Areas, Corrective Actions and Effectiveness:**

• No problem areas were identified during reporting period.

#### Non-Compliance Issues, Corrective Actions and Effectiveness:

No non-compliance issues were identified during reporting period.

#### Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

#### Landowner Issues:

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

# TABLE 3-7 Tioga Plant Receipt Station

#### **Work Completed during Reporting Period**

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Site Preparation	0%	0%	
Facility Installation	0%	0%	
Cleanup	0%	0%	

# Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period.

#### **Problem Areas, Corrective Actions and Effectiveness:**

No problem areas were identified during reporting period.

#### Non-Compliance Issues, Corrective Actions and Effectiveness:

No non-compliance issues were identified during reporting period.

# Non-Compliance Issues from Federal, State or Local Permitting Agencies and Response:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action