Attachment C Restoration Photos South Spread – Tioga-Elkhorn Creek Pipeline Page **1** of **39**



Date: 12/10/2021

Location: Sta. No. 1370+00

Notes: Status of restored right-ofway and South Spread HDD bore site.



Date: 12/10/2021

Location: Sta. No. 1371+00

Notes: Status of restored right-ofway and South Spread HDD bore site.


Attachment C Restoration Photos South Spread – Tioga-Elkhorn Creek Pipeline Page **2** of **39**



Date: 12/10/2021

Location: Sta. No. 1380+00

Notes: Status of restored right-ofway. Lake Sakakawea in background.



Location: Sta. No. 1381+28

Notes: South Lake block valve.





Date: 12/10/2021

Location: Sta. No. 1388+00


Notes: Status of restored right-of-way.



Date: 12/10/2021

Location: Sta. No. 1389+00

Attachment C **Restoration Photos** South Spread – Tioga-Elkhorn Creek Pipeline Page 4 of 39



Date: 12/10/2021

Location: Sta. No. 1420+00

Notes: Status of restored right-ofway.



N

Tioga Elkhorn Creek Line 29 Nov 2021, 09:21:15 CST

=

Date: 11/29/2021

Location: Sta. No. 1430+67

Notes: Status of restored right-ofway and waterbody s-km-eb-001.

Attachment C Restoration Photos South Spread – Tioga-Elkhorn Creek Pipeline Page **5** of **39**



Date: 12/10/2021

Location: Sta. No. 1435+00

Notes: Status of restored right-of-way.



Date: 12/10/2021

Location: Sta. No. 1439+00

Attachment C Restoration Photos South Spread – Tioga-Elkhorn Creek Pipeline Page **6** of **39**



Date: 12/10/2021 Location: Sta. No. 1440+00

Notes: Status of restored right-of-way.



Date: 11/29/2021

Location: Sta. No. 1451+04

Notes: Status of waterbody s-mkea-001 crossed via a guided bore.



Attachment C Restoration Photos South Spread – Tioga-Elkhorn Creek Pipeline Page **7** of **39**

South East Elevation

LAT: 48.096253 LON: -103.101664 ±16ft 1900ft

Date: 12/10/2021

Location: Sta. No. 1460+00

Notes: Status of restored right-of-way.



South Elevation

LAT: 48.095654 LON: -103.101548 ±16ft 1898ft



Date: 12/10/2021

10 Dec 2021, 13:42:09

Location: Sta. No.1473+00

Attachment C Restoration Photos South Spread – Tioga-Elkhorn Creek Pipeline Page **8** of **39**

South East Elevation

LAT: 48.093690 LON: -103.101488 ±16ft 1933ft

Date: 12/10/2021

Location: Sta. No. 1478+00

Notes: Status of restored right-of-way.

STA 1478+00, facing N North Bakken Expansion

.58



Date: 12/10/2021

10 Dec 2021, 13:36:37

Location: Sta. No. 1510+00

Attachment C Restoration Photos South Spread – Tioga-Elkhorn Creek Pipeline Page **9** of **39**

South Elevation

LAT: 48.084576 LON: -103.103707 ±16ft 1958ft

Date: 12/10/2021

Location: Sta. No. 1515+00

Notes: Status of restored right-ofway.





Date: 11/30/2021


Location: Sta. No. 1531+26

Notes: Status of waterbody s-mkwa-001 crossed via a guided bore.

Attachment C Restoration Photos South Spread – Tioga-Elkhorn Creek Pipeline Page 10 of 39

South West Elevation

LAT: 48.078373 LON: -103.109765 ±16ft 1984ft



Date: 12/10/2021

Location: Sta. No. 1549+00

Notes: Status of restored right-of-way.

East Elevation

LAT: 48.078355 LON: -103.110535 ±16ft 1975ft

STA 1555+00, facing W North Bakken Expansion Date: 12/10/2021

Location: Sta. No. 1555+00

Attachment C Restoration Photos South Spread – Tioga-Elkhorn Creek Pipeline Page **11** of **39**

North East Elevation

LAT: 48.078197 LON: -103.119418 ±16ft 1909ft



Date: 12/10/2021

Location: Sta. No. 1570+00

Notes: Status of restored right-of-way.



Date: 11/29/2021

Location: Sta. No. 1592+42

Notes: Status of waterbody s-mkeb-002 (Tobacco Garden Creek) crossed via a guided bore.

Attachment C Restoration Photos South Spread – Tioga-Elkhorn Creek Pipeline Page **12** of **39**

EAT: 48.067445 LON: -103.127642 ±16ft ▲ 1881ft

Date: 12/10/2021

Location: Sta. No. 1620+00

Notes: Status of restored right-of-way.

North West Elevation

LAT: 48.067388 LON: -103.127624 ±16ft ▲ 1881ft

Date: 12/10/2021

Location: Sta. No. 1622+00



Date: 11/12/2021

Location: Sta. No. 1622+46

Notes: Status of restored rightof-way and bar ditch.



Date: 10/31/2021

Location: Sta. No. 1820+00



Date: 11/29/2021

Location: Sta. No. 1914+65

Notes: Status of waterbody smk-ea-003 crossed via a guided bore.



Date: 11/29/2021

Location: Sta. No. 1915+16

Notes: Status of restored rightof-way and waterbody s-mk-ea-003.


South West Elevation

LAT: 47.992574 LON: -103.154950 ±16ft ▲ 1996ft

Date: 12/10/2021

Location: Sta. No. 1940+00

Notes: Status of restored right-of-way.





Date: 11/30/2021

10 Dec 2021, 14:27:24

Location: Sta. No. 1943+02

Notes: Highway 10 block valve.

South Elevation



Date: 12/10/2021

Location: Sta. No. 1948+00

Notes: Status of restored right-of-way.

North East Elevation

LAT: 47.971867 LON: -103.175550 ±16ft 2005ft



Date: 12/10/2021

Location: Sta. No. 2035+00

Attachment C Restoration Photos South Spread – Tioga-Elkhorn Creek Pipeline Page **17** of **39**

South West Elevation

LAT: 47.972027 LON: -103.175509 ±16ft 2010ft

Date: 12/10/2021

Location: Sta. No. 2038+00

Notes: Status of restored right-of-way.

STA 2038+00, facing N North Bakken Expansion

WARNING



Date: 11/19/2021

10 Dec 2021, 14:37:59

Location: Sta. No. 2059+00

Notes: Status of restored waterbody s-mk-ea-002.

South West Elevation



Date: 12/10/2021

Location: Sta. No. 2078+00

Notes: Status of restored right-of-way.

East Elevation LAT: 47.961094 LON: -103.180885 ±16ft ▲ 1995ft

Date: 12/10/2021

Location: Sta. No. 2085+00



Date: 11/08/2021

Location: Sta. No. 2100+00

Notes: Status of restored wetland w-mk-ef-004e.



Date: 12/02/2021

Location: Sta. No. 2185+80

Notes: Status of restored rightof-way and bar ditch.

South Elevation

LAT: 47.905802 LON: -103.177039 ±16ft 2085ft



Date: 12/10/2021

Location: Sta. No. 2290+00

Notes: Status of restored right-of-way.



Date: 11/28/2021

Location: Sta. No. 2350+00

Notes: Status of waterbody s-lbt-003b crossed via a guided bore.

Attachment C Restoration Photos South Spread – Tioga-Elkhorn Creek Pipeline Page **21** of **39**


South East Elevation

LAT: 47.876697 LON: -103.175030 ±16ft 2068ft

Date: 12/11/2021

Location: Sta. No. 2400+00

Notes: Status of restored right-of-way.



North Elevation



Date: 12/11/2021

11 Dec 2021, 13:45:1

Location: Sta. No. 2415+00

South Elevation



STA 2505+00, facing N North Bakken Expansion Date: 12/11/2021

Location: Sta. No. 2505+00

Notes: Status of restored right-of-way.

South Elevation

LAT: 47.862560 LON: -103.174866 ±16ft ▲ 2052ft

Image: Constraint of the state of the

Date: 12/11/2021

11 Dec 2021, 14:05:05

Location: Sta. No. 2515+00

North East Elevation

LAT: 47.861840 LON: -103.174900 ±16ft 2042ft

Date: 12/11/2021

Location: Sta. No. 2520+00

Notes: Status of restored right-of-way.



South Elevation



Date: 12/11/2021

Location: Sta. No. 2545+00

Attachment C Restoration Photos South Spread – Tioga-Elkhorn Creek Pipeline Page **24** of **39**

North West Elevation

LAT: 47.836693 LON: -103.175251 ±16ft 2052ft

State in the

VILL D

STA 2555+00, facing S North Bakken Expansion Date: 12/11/2021

Location: Sta. No. 2555+00

Notes: Status of restored right-of-way.

West Elevation

Date: 12/11/2021

Location:

1 Dec 2021, 14:13:5

Sta. No. 2565+00



Attachment C Restoration Photos South Spread – Tioga-Elkhorn Creek Pipeline Page **25** of **39**


North West Elevation

LAT: 47.833254 LON: -103.174474 ±16ft 2105ft

Date: 12/11/2021

Location: Sta. No. 2572+00

Notes: Status of restored right-of-way.



North East Elevation

LAT: 47.828275 LON: -103.176366 ±16ft ▲ 2085ft

Date: 12/11/2021

Location: Sta. No. 2584+00

West Elevation

LAT: 47.828766 LON: -103.175886 ±16ft 2073ft

Date: 12/11/2021

Location: Sta. No. 2588+00

Notes: Status of restored right-of-way.



South Elevation

LAT: 47.818907 LON: -103.177491 ±16ft 2080ft



Date: 12/11/2021

Dec 2021, 14:37:15

Location: Sta. No. 2620+00

Attachment C Restoration Photos South Spread – Tioga-Elkhorn Creek Pipeline Page **27** of **39**


North Elevation

LAT: 47.818741 LON: -103.177951 ±16ft 2066ft

Date: 12/11/2021

Location: Sta. No. 2625+00

Notes: Status of restored right-of-way.





Date: 11/27/2021

Location: Sta. No. 2691+00

Notes: Cherry Creek block valve.

Watford City ND


LAT: 47.802779 LON: -103.169289 ±16ft 2018ft

Date: 11/15/2021

Location: Sta. No. 2698+00

Notes: Status of restored waterbody s-mk-eb-005 (Northfork Creek).

s-mk-eb-005, STA 2698+00, looking south North Bakken Expansion



Date: 11/15/2021

Tioga to Elkhorn Cree 15 Nov 2021, 15:05:5

> Location: Sta. No. 2698+00

Notes: Status of restored waterbody s-mk-eb-005 (Northfork Creek).



Date: 11/19/2021

Location: Sta. No. 2742+19

Notes: Status of restored waterbody s-ibt-001a (Cherry Creek).

EAT: 47.764924 LON: -103.198484 ±16ft ▲ 2073ft

Date: 12/12/2021

Location: Sta. No. 2888+00

North West Elevation

LAT: 47.764584 LON: -103.198566 ±16ft 2059ft



Date: 12/12/2021

Location: Sta. No. 2890+00

Notes: Status of restored right-of-way.

North Elevation

LAT: 47.739099 LON: -103.198540 ±16ft 2224ft



Date: 12/12/2021

Location: Sta. No. 2945+00

North West Elevation

LAT: 47.738953 LON: -103.198521 ±16ft 2227ft

Date: 12/12/2021


Location: Sta. No. 2980+00

Notes: Status of restored rightof-way.

STA 2980+00, facing N North Bakken Expansion

South East Elevation

LAT: 47.735734 LON: -103.197769 ±16ft 2239ft



Date: 12/12/2021

12 Dec 2021, 13:04:21

Location: Sta. No. 2992+00


South Elevation

LAT: 47.735745 LON: -103.197764 ±16ft ▲ 2241ft

Date: 12/12/2021

Location: Sta. No. 2995+00

Notes: Status of restored right-of-way.



West Elevation

LAT: 47.735615 LON: -103.197185 ±16ft 2237ft



Date: 12/12/2021

12 Dec 2021, 13:01:5

Location: Sta. No. 2998+00

Attachment C Restoration Photos South Spread – Tioga-Elkhorn Creek Pipeline Page **33** of **39**

East Elevation



Date: 12/12/2021

Location: Sta. No. 3009+00

Notes: Status of restored right-of-way.




Date: 12/12/2021

Location: Sta. No. 3012+00

East Elevation

LAT: 47.726717 LON: -103.196467 ±16ft 2267ft



Location: Sta. No. 3030+00

Notes: Status of restored right-of-way.





Date: 12/12/2021

Location: Sta. No. 3032+00

Attachment C Restoration Photos South Spread – Tioga-Elkhorn Creek Pipeline Page **35** of **39**

North East Elevation

LAT: 47.726488 LON: -103.196354 ±16ft 2273ft



Date: 12/12/2021

Location: Sta. No. 3033+00

Notes: Status of restored right-of-way.

South West Elevation

LAT: 47.719052 LON: -103.194720 ±16ft 2248ft



Date: 12/12/2021

Location: Sta. No. 3039+00



Date: 12/12/2021

Location: Sta. No. 3058+00

Notes: Status of restored right-of-way.

South Elevation

LAT: 47.720062 LON: -103.192074 ±16ft 2264ft



Date: 12/12/2021

Location: Sta. No. 3060+00

North East Elevation

LAT: 47.718896 LON: -103.194952 ±16ft 2243ft

Date: 12/12/2021

Location: Sta. No. 3065+00

Notes: Status of restored right-ofway.





Date: 12/12/2021

Location: Sta. No. 3112+00

Attachment C Restoration Photos South Spread – Tioga-Elkhorn Creek Pipeline Page **38** of **39**

West Elevation

LAT: 47.709484 LON: -103.209094 ±16ft 2269ft

Date: 12/12/2021

Location: Sta. No. 3120+00

Notes: Status of restored right-of-way.





Date: 12/12/2021

Location: Sta. No. 3150+00

South East Elevation

LAT: 47.705811 LON: -103.217900 ±16ft ▲ 2279ft

Date: 12/12/2021

Location: Sta. No. 3157+00

Notes: Grazing cattle on restored right-of-way.

