Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 1 of 52



Date: 11/29/2021

Location: Sta. No. 3+00

Notes: Status of restored right-of-

way.



Date: 11/29/2021

Location:

Sta. No. 17+00

Notes: Status of restored right-of-

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 2 of 52



Date: 11/29/2021

Location:

Sta. No. 18+00

Notes: Status of restored right-of-

way.



Date: 11/29/2021

Location:

Sta. No. 28+00

Notes: Status of restored right-of-

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 3 of 52



Date: 11/29/2021

Location:

Sta. No. 30+00

Notes: Status of restored right-of-

way.



Date: 11/17/2021

Location:

Sta. No. 38+10

Notes: Status of wetland w-wm-eb-002e crossed via a guided bore.

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 4 of 52



Date: 11/29/2021

Location: Sta. No. 40+00

Notes: Status of restored right-of-

way.



Date: 11/29/2021

Location:

Sta. No. 45+00

Notes: Status of restored right-of-

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 5 of 52



Date: 11/29/2021

Location:

Sta. No. 50+00

Notes: Status of restored right-of-

way.



Date: 11/29/2021

Location:

Sta. No. 55+00

Notes: Status of restored right-of-

way and bar ditch.

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 6 of 52




Date: 11/29/2021

Location:

Sta. No. 55+45

Notes: Status of restored right-of-

way.



Date: 11/23/2021

Location:

Sta. No. 70+00

Notes: Status of restored right-of-



Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 7 of 52



Date: 11/29/2021

Location:

Sta. No. 72+00

Notes: Status of restored right-of-

vay.



Date: 11/23/2021

Location:

Sta. No. 72+00

Notes: Status of restored right-of-

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 8 of 52



Date: 11/29/2021

Location:

Sta. No. 73+00

Notes: Status of restored right-of-

way.



Date: 11/29/2021

Location:

Sta. No. 103+00

Notes: Status of restored right-of-

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 9 of 52



Date: 11/29/2021

Location:

Sta. No. 105+00

Notes: Status of restored right-of-

way.



Date: 11/29/2021

Location:

Sta. No. 107+00

Notes: Status of restored right-of-way and bar ditch.

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 10 of 52



Date: 11/23/2021

Location:

Sta. No. 115+00

Notes: Status of restored right-of-

way.



Date: 11/23/2021

Location:

Sta. No. 160+00

Notes: Status of restored right-of-

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 11 of 52



Date: 11/23/2021

Location:

Sta. No. 162+00

Notes: Status of restored right-of-

wav.



Date: 11/23/2021

Location:

Sta. No. 214+00

Notes: Status of restored right-of-

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 12 of 52



Date: 11/23/2021

Location:

Sta. No. 235+00

Notes: Status of restored right-

of-way.



Date: 11/29/2021

Location:

Sta. No. 236+00

Notes: Status of restored right-

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 13 of 52



Date: 11/29/2021

Location:

Sta. No. 237+00

Notes: Status of restored right-of-

vav.



Date: 11/29/2021

Location:

Sta. No. 238+00

Notes: Status of restored right-of-

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 14 of 52



Date: 11/18/2021

Location:

Sta. No. 240+90

Notes: Status of restored wetland w-wm-ea-002e.



Date: 11/18/2021

Location:

Sta. No. 244+52

Notes: Status of restored wetland w-wm-ea-002e.

Date: 11/18/2021

Location:



Sta. No. 251+33

Notes: Status of restored wetland w-wm-ea-001e.



Date: 11/29/2021

Location:

Sta. No. 255+00

Notes: Status of restored right-

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 16 of 52



Date: 11/29/2021

Location:

Sta. No. 255+50

Notes: Status of restored right-

of-way.



Date: 11/23/2021

Location:

Sta. No. 272+00

Notes: Status of restored right-

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 17 of 52



Date: 11/29/2021

Location:

Sta. No. 285+00

Notes: Status of restored right-

of-way.



Date: 11/23/2021

Location:

Sta. No. 324+00

Notes: Status of restored right-

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 18 of 52



Date: 11/23/2021

Location:

Sta. No. 327+00

Notes: Status of restored right-

of-way.



Date: 11/23/2021

Location:

Sta. No. 345+00

Notes: Status of restored right-

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 19 of 52



Date: 11/23/2021

Location:

Sta. No. 350+00

Notes: Status of restored right-

of-way.



Date: 11/23/2021

Location:

Sta. No. 360+00

Notes: Status of restored right-

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 20 of 52



Date: 11/23/2021

Location:

Sta. No. 360+00

Notes: Valve No. 6.8 block

valve.



Date: 11/23/2021

Location:

Sta. No. 380+75

Notes: Status of restored right-

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 21 of 52



Date: 11/23/2021

Location:

Sta. No. 381+25

Notes: Status of restored right-

of-way.



Date: 11/23/2021

Location:

Sta. No. 434+50

Notes: Status of restored right-

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 22 of 52



Date: 11/23/2021

Location:

Sta. No. 445+00

Notes: Status of restored right-

of-way.



Date: 11/23/2021

Location:

Sta. No. 455+00

Notes: Status of restored right-

Attachment D Restoration Photos Line Section 25 Loop Pipeline Page 23 of 52



Date: 11/23/2021

Location:

Sta. No. 489+00

Notes: Status of restored right-

of-way.



Date: 11/23/2021

Location:

Sta. No. 490+00

Notes: Status of restored right-

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 24 of 52



Date: 11/18/2021

Location:

Sta. No. 516+08

Notes: Status of restored wetland

w-mt-ea-001e.



Date: 11/18/2021

Location:

Sta. No. 516+14

Notes: Status of restored wetland

w-mt-ea-001e.

Attachment D Restoration Photos Line Section 25 Loop Pipeline Page 25 of 52



Date: 11/23/2021

Location:

Sta. No. 543+80

Notes: Status of restored right-

of-way.



Date: 11/23/2021

Location:

Sta. No. 544+00

Notes: Status of restored right-of-way and bar ditch.

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 26 of 52



Date: 11/23/2021

Location:

Sta. No. 547+50

Notes: Status of restored right-

of-way.



Date: 11/18/2021

Location:

Sta. No. 579+91

Notes: Status of restored wetland

w-bk-ea-013.

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 27 of 52



Date: 11/23/2021

Location:

Sta. No. 585+00

Notes: Status of restored right-

of-way.



Date: 11/23/2021

Location:

Sta. No. 595+00

Notes: Status of restored right-

Attachment D Restoration Photos Line Section 25 Loop Pipeline Page 28 of 52



Date: 11/23/2021

Location:

Sta. No. 603+75

Notes: Status of restored right-

of-way.



Date: 11/23/2021

Location:

Sta. No. 604+75

Notes: Status of restored right-of-way and bar ditch.

Attachment D Restoration Photos Line Section 25 Loop Pipeline Page 29 of 52



Date: 11/17/2021

Location:

Sta. No. 624+01

Notes: Status of restored wetland

w-bk-ea-005e.



Date: 11/17/2021

Location:

Sta. No. 626+62

Notes: Status of restored wetland

w-bk-ea-006e.

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 30 of 52

SE S SW W 240 270

195°S (T) \* 48°34'4.4", -102°51'41.3" ±3 m ▲ 686 m

Date: 11/23/2021

Location:

Sta. No. 630+00

Notes: Status of restored right-

of-way.



Date: 11/23/2021

Location:

Sta. No. 635+00

Notes: Status of restored right-

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 31 of 52



Date: 11/29/2021

Location:

Sta. No. 660+00

Notes: Status of restored right-

of-way.



Date: 11/18/2021

Location:

Sta. No. 695+18

Notes: Status of restored wetland

w-bk-ee-002e.

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 32 of 52



Date: 11/22/2021

Location:

Sta. No. 702+00

Notes: Status of restored right-

of-way.



Date: 11/22/2021

Location:

Sta. No. 705+23

Notes: Status of waterbody s-bk-eb-001p (White Earth Creek) crossed via a guided bore.

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 33 of 52

NE E | SE S | 150 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130 | 130

Date: 11/18/2021

Location:

Sta. No. 711+41

Notes: Status of restored wetland

w-bk-eb-001e.



Date: 11/18/2021

Location:

18 Nov 2021, 11:10 AM

Sta. No. 717+00

Notes: Valve No. 13.6 block

valve.

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 34 of 52



Date: 11/22/2021

Location:

Sta. No. 719+00

Notes: Status of restored right-

of-way.



Date: 11/22/2021

Location:

Sta. No. 721+00

Notes: Status of restored right-

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 35 of 52

SE | S | SW | W | 270 | 185°S (T) \* 48°35′42.2″, -102°51′5.9″ ±3 m ▲ 670 m

Date: 11/22/2021

Location:

Sta. No. 742+00

Notes: Status of restored right-

of-way.



Date: 11/22/2021

Location:

Sta. No. 750+00

Notes: Status of restored right-

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 36 of 52



Date: 11/22/2021

Location:

Sta. No. 773+50

Notes: Status of restored right-

of-way.



Date: 11/22/2021

Location:

Sta. No. 775+75

Notes: Status of restored right-

of-way and bar ditch.

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 37 of 52



Date: 11/22/2021

Location:

Sta. No. 776+60

Notes: Status of restored right-of-way and bar ditch.



Date: 11/17/2021

Location:

Sta. No. 777+10

Notes: Status of restored wetland w-bk-wa-001e.

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 38 of 52



Date: 11/22/2021

Location:

Sta. No. 788+00

Notes: Status of restored right-

of-way.



Date: 11/22/2021

Location:

Sta. No. 804+00



Notes: Status of restored right-of-way.

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 39 of 52



Date: 11/22/2021

Location:

Sta. No. 817+00

Notes: Status of restored right-

of-way.





Date: 11/22/2021

Location:

Sta. No. 829+00

Notes: Status of restored right-



Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 40 of 52

Date: 11/22/2021

Location:

Sta. No. 842+60

Notes: Status of restored right-

of-way.



Date: 11/17/2021

Location:

Sta. No. 843+08

Notes: Status of restored wetland

w-bk-ea-003e.

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 41 of 52



Date: 11/17/2021

Location:

Sta. No. 845+00

Notes: Status of restored wetland

w-bk-ea-002e.



Date: 11/17/2021

Location:

Sta. No. 857+00

Notes: Status of restored wetland

w-bk-ea-001e.

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 42 of 52



Date: 11/17/2021

Location:

Sta. No. 858+22

Notes: Status of restored wetland w-bk-ea-001e.



Date: 11/22/2021

Location:

Sta. No. 860+00

Notes: Status of restored right-

Attachment D Restoration Photos Line Section 25 Loop Pipeline Page 43 of 52



Date: 11/22/2021

Location:

Sta. No. 874+00

Notes: Status of restored right-

of-way.



Date: 11/22/2021

Location:

Sta. No. 899+00

Notes: Status of restored right-

of-way.

22 Nov 2021, 01:10 PM

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 44 of 52

Date: 11/22/2021

Location:

Sta. No. 899+98

Notes: Status of restored right-of-way and bar ditch.



Date: 11/22/2021

Location:

Sta. No. 901+00

Notes: Status of restored right-of-way and bar ditch.

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 45 of 52

SE S 150 SW 240 270 300

◆ 214°SW (T) \* 48°37′25.1″, -102°47′57.4″ ±3 m ▲ 718 m

North Sakte(i Expansion)

22 Nov 7021.61.05 PM

Date: 11/22/2021

Location:

Sta. No. 922+85

Notes: Status of restored right-of-way and bar ditch.



Date: 11/22/2021

Location:

Sta. No. 923+00

Notes: Status of restored right-

of-way and bar ditch.

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 46 of 52



Date: 11/22/2021

Location:

Sta. No. 930+00

Notes: Status of restored right-

of-way.



Date: 11/22/2021

Location:

Sta. No. 938+00

Notes: Status of restored right-

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 47 of 52



Date: 11/22/2021

Location:

Sta. No. 980+00

Notes: Status of restored right-

of-way.



Date: 11/22/2021

Location:

Sta. No. 991+00

Notes: Status of restored right-

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 48 of 52

Date: 11/22/2021

Location:

Sta. No. 994+00

Notes: Status of restored right-

of-way.



Date: 11/22/2021

Location:

Sta. No. 1006+00

Notes: Status of restored right-

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 49 of 52



Date: 11/22/2021

Location:

Sta. No. 1016+00

Notes: Status of restored right-

of-way.



Date: 11/22/2021

Location:

Sta. No. 1017+25

Notes: Status of restored right-

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 50 of 52



Date: 11/22/2021

Location:

Sta. No. 1020+00

Notes: Status of restored right-

of-way.



Date: 11/22/2021

Location:

Sta. No. 1030+00

Notes: Status of restored right-

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 51 of 52



Date: 11/22/2021

Location:

Sta. No. 1040+00

Notes: Status of restored right-

of-way.



Date: 11/22/2021

Location:

Sta. No. 1060+00

Notes: Status of restored right-

Attachment D
Restoration Photos
Line Section 25 Loop Pipeline
Page 52 of 52



Date: 11/22/2021

Location:

Sta. No. 1068+00

Notes: Status of restored right-