



Date: 11/22/2021

Location: 86th Street NW bore crossing (west side tie-in)

Notes: Status of restored temporary workspace for guided bore.



Date: 11/22/2021

Location: 86th Street NW bore crossing

Notes: Status of restored right-of-way.



Date: 11/22/2021

Location: 86th Street NW bore crossing

Notes: Status of restored additional temporary workspace.



Date: 11/22/2021

Location: Highway 40 guided bore crossing (east side tie-in)

Notes: Status of restored additional temporary workspace.



Date: 11/22/2021

Location: Highway 40 guided bore crossing (west side tie-in)

Notes: Status of restored additional temporary workspace.



Date: 11/22/2021

Location: 92nd Street NW bore crossing (north side tie-in)

Notes: Status of restored additional temporary workspace.



Date: 11/22/2021

Location: 92nd Street NW bore crossing (south side tie-in)

Notes: Status of restored additional temporary workspace. The pre-existing rockpile was avoided by the guided bore.



Date: 11/22/2021

Location: 92nd Street NW bore crossing (south side tie-in)

Notes: Status of restored right-of-way.



Date: 11/22/2021

Location: 93rd Street NW / 89th Avenue NW bore crossing (south side tie-in)

Notes: Status of restored additional temporary workspace.



Date: 11/22/2021

Location: 93rd Street NW / 89th Avenue NW bore crossing (north side tie-in)

Notes: Status of restored additional temporary workspace.