

1250 West Century Avenue Mailing Address: P.O. Box 5601 Bismarck, ND 58506-5601 (701) 530-1600

June 12, 2025

Debbie-Anne Reese, Secretary Federal Energy Regulatory Commission 888 First Street, N.E., Room 1A Washington, D.C. 20426

Re: WBI Energy Transmission, Inc. Wahpeton Expansion Project Docket No. CP22-466-000 Weekly Status Report No. 68

Dear Ms. Reese:

WBI Energy Transmission, Inc. (WBI Energy) herewith submits its Weekly Status Report No. 68 for the Wahpeton Expansion Project, in compliance with Environmental Condition 9 of the Appendix to the Federal Energy Regulatory Commission's October 23, 2023 Order Issuing Certificate in the above referenced docket.

The attached report addresses the status of the project from June 2, 2025 to June 8, 2025.

Should you have any questions or comments regarding this filing, please call the undersigned at (701) 530-1563.

Sincerely,

/s/ Lori Myerchin

Lori Myerchin Vice President, Regulatory Affairs and Transportation Services

Attachment

cc: via email

Jennifer Fink FERC Dawn Ramsey, FERC Official Service List



Project Status Report No. 68 Reporting Period: 06-02-2025 – 06-08-2025

A. Update on Federal Authorizations

- WBI Energy has obtained all necessary federal permits and authorizations required for construction of the Wahpeton Expansion Project.
- On November 26, 2024, FERC granted approval to place the Project into service. WBI Energy placed Project facilities into service on December 1, 2024.

B. Construction Status - Pipeline Facilities

• Environmental Inspectors continue to conduct onsite environmental training as needed.

TABLE 1-1 Wahpeton Expansion Pipeline

Work Completed during Reporting Period:

- · Continued painting of valve sites.
- Continued cleanup/restoration activities at the laydown yard, valve sites, and along construction right-of-way.
- Continued re-staking the construction right-of-way requiring anomaly (ACVG) digs.
- Continued ACVG investigations. Completed 7 anomaly digs during this reporting period.
 - Approximately 99% complete with anomaly digs.
- Continued installation and maintenance of Project signage and erosion control devices, as conditions allowed.
- Began reseeding remaining construction right-of-way.

% of Total Job Completed **Activity** Total % Comments Completed This Period **Pipeline** Clearing / Grading 100% Stringing 100% Bending 100% Welding 100% Joint Coating 100% Ditching 100% 100% Lowering Backfill 100% Bores 68 of 68 94% Cleanup 1% Seeding¹ 50% 75% Final Tie-in and 100% Commissioning Hydrostatic Testing 2 of 2

Approximately 17.5 acres (out of 70 acres requiring seeding) remain to be seeded.



Project Status Report No. 68 Reporting Period: 06-02-2025 – 06-08-2025

Appurtenant Facilities ²			
Valve Site #1 and Pig Launcher / Receiver #1 at MP 0.0		2 of 2	
Cleanup/Restoration		100%	
Valve Site #2 and Pig Launcher / Receiver #2 at MP 11.6		2 of 2	
Cleanup/Restoration	<1%	97%	Continued painting of equipment.
Valve Site #3 at MP 23.4		1 of 1	
Cleanup/Restoration	<1%	96%	Continued painting of equipment.
Valve Site #4 at MP 31.3		1 of 1	
Cleanup/Restoration	10%	60%	Continued painting of equipment. Continued restoration of station perimete
Valve Site #5 and Pig Launcher / Receiver #3 at MP 39.5		2 of 2	
Cleanup/Restoration	<1%	90%	Continued painting of equipment.
Valve Site #6 at MP 48.9		1 of 1	
Cleanup/Restoration	0%	96%	
Valve Site #7 and Pig Launcher / Receiver #4 at MP 60.5		2 of 2	
Cleanup/Restoration	<1%	96%	Continued painting of equipment.

Work Planned for next Reporting Period and Schedule Changes:

- Complete cleanup/restoration activities at the laydown yard.
- Continue painting of valve sites.
- Continue cleanup/restoration activities at valve sites and along construction right-of-way.
- Continue installation and maintenance of Project signage and erosion control devices.
- Continue re-staking the construction right-of-way requiring an ACVG dig.
- Continue reseeding remaining construction right-of-way and valve site perimeters, as conditions allow.

Problem Areas, Corrective Actions and Effectiveness: None

Non-Compliance Issues, Corrective Actions and Effectiveness: None

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

² Remaining pad construction and cleanup/restoration at Valve Sites 2, 3, 4, 5, 6, and 7 include the spreading of gravel and seeding of the valve site perimeters and will be completed in the summer of 2025. Permanent fencing at Valve Sites 2, 4, 5, and 6 will be installed in the summer of 2025.



Project Status Report No. 68 Reporting Period: 06-02-2025 – 06-08-2025

Date	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action



Date: 06/02/2025

Location: Sta. No. 615+00 and

Valve Site 2.

Notes: Painting valve equipment.



Project Status Report No. 68 Reporting Period: 06-02-2025 – 06-08-2025



Date: 06/02/2025

Location: Sta. No. 1879+00

Notes: Removal of debris along construction right-of-way prior to

reseeding.



Date: 06/02/2025

Location: Sta. No. 1879+00

Notes: Applying straw after reseeding remaining open rangeland along construction right-

of-way.



Project Status Report No. 68 Reporting Period: 06-02-2025 – 06-08-2025



Date: 06/03/2025

Location: Sta. No. 1655+00 and

Valve Site 4.

Notes: Removal of additional sand to prepare station perimeter for

reseeding.



Date: 06/03/2025

Location: Sta. No. 1940+00

Notes: Straw crimped into reseeded open rangeland along construction right-of-way.



Project Status Report No. 68 Reporting Period: 06-02-2025 – 06-08-2025



Date: 06/04/2025

Location: 4 Suns Contractor Yard

Notes: Raking and removing remaining construction debris.



Date: 06/04/2025

Location: Sta. No. 1655+00 and

Valve Site 4.

Notes: Replacing topsoil along

station perimeter.



Project Status Report No. 68 Reporting Period: 06-02-2025 – 06-08-2025



Date: 06/04/2025

Location: Sta. No. 2348+00

Notes: Straw crimped into reseeded open rangeland along construction

right-of-way.



Date: 06/04/2025

Location: Sta. No. 2401+00

Notes: Spreading straw after reseeding open rangeland along construction right-of-way.



Project Status Report No. 68 Reporting Period: 06-02-2025 – 06-08-2025



Date: 06/05/2025

Location: 4 Suns Contractor Yard

Notes: Removal of construction

debris.



Date: 06/05/2025

Location: Sta. No. 1655+00 and

Valve Site 4.

Notes: Replacing topsoil along

station perimeter.



Project Status Report No. 68 Reporting Period: 06-02-2025 – 06-08-2025



Date: 06/05/2025

Location: Sta. No. 2529+00

Notes: Cleanup of construction debris along construction right-of-

wav.



Date: 06/06/2025

Location: 4 Suns Contractor Yard

Notes: Removal of construction

debris.



Project Status Report No. 68 Reporting Period: 06-02-2025 – 06-08-2025



Date: 06/06/2025

Location: Sta. No. 1655+00 and

Valve Site 4.

Notes: Removal of excess sand

prior to reseeding.



Date: 06/07/2025

Location: Sta. No. 432+00

Notes: Repairing low spots along

construction right-of-way.



Project Status Report No. 68 Reporting Period: 06-02-2025 – 06-08-2025



Date: 06/06/2025

Location: Sta. No. 617+00

Notes: Removal of construction debris along construction right-of-

way.



Date: 06/06/2025

Location: Sta. No. 1861+00

Notes: Crimping straw into reseeded open rangeland along construction right-of-way.



Project Status Report No. 68 Reporting Period: 06-02-2025 – 06-08-2025

C. Construction Status - Aboveground Facilities

TABLE 2-1 Modifications at Mapleton Compressor Station

Work Completed during Reporting Period:

No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Install Aboveground Station Piping		100%	
Install Belowground Station Piping		100%	
Cleanup / Restoration ³		100%	

Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Landowner Issues: None

Latituowiter Issues. Notie					
Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action	

³ Final cleanup and restoration will be in conjunction with Block Valve #1 and Pig Launcher / Receiver #1 within the compressor station yard.



Project Status Report No. 68 Reporting Period: 06-02-2025 – 06-08-2025

TABLE 2-2 MDU- Kindred Border Station

Work Completed during Reporting Period:

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Initial Site Work	0%	99%	4/
Concrete Work		100%	
Install Aboveground Piping		100%	
Install Belowground Piping		100%	
Install Buildings		100%	
Cleanup / Restoration ⁴	0%	96%	
Install Security Fence		100%	

Work Planned for next Reporting Period and Schedule Changes:

• Continue initial site work and cleanup/restoration activities.

Problem Areas, Corrective Actions and Effectiveness:

No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Landowner Issues: None

Landowner issues: None					
Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action	

⁴ Remaining initial site work, cleanup, and restoration will be completed in conjunction with Block Valve #3 within the border station yard.



Project Status Report No. 68 Reporting Period: 06-02-2025 – 06-08-2025

TABLE 2-3 MDU- Wahpeton Border Station

Work Completed during Reporting Period:

• Continued cleanup/restoration activities.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Initial Site Work	<1%	98%	5/
Concrete Work		100%	
Install Aboveground Piping		100%	
Install Belowground Piping		100%	
Install Buildings		100%	
Cleanup / Restoration ⁵	<1%	95%	Seeding of the site perimeters will be completed in the summer of 2025.
Install Security Fence		100%	

Work Planned for next Reporting Period and Schedule Changes:

• Continue cleanup/restoration activities.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Landowner Issues: None

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

⁵ Remaining initial site work and cleanup, and restoration will be completed in conjunction with Block Valve #7 within the border station yard.



Project Status Report No. 68 Reporting Period: 06-02-2025 – 06-08-2025



Date: 06/06/2025

Location: MDU – Wahpeton Border Station and Valve Site 7.

Notes: Removal of construction debris before topsoil is spread.



Project Status Report No. 68 Reporting Period: 06-02-2025 – 06-08-2025

D. Changes to Stream Crossings or Work in Environmental Sensitive Areas

TABLE 3 Changes to Stream Crossings or Work in Environmental Sensitive Areas

Schedule changes to stream crossings.

• None during reporting period.

Schedule changes for work in other environmentally sensitive areas.

None during reporting period.