

1250 West Century Avenue Mailing Address: P.O. Box 5601 Bismarck, ND 58506-5601 (701) 530-1600

August 21, 2025

Debbie-Anne Reese, Secretary Federal Energy Regulatory Commission 888 First Street, N.E., Room 1A Washington, D.C. 20426

Re: WBI Energy Transmission, Inc. Wahpeton Expansion Project Docket No. CP22-466-000 Weekly Status Report No. 78

Dear Ms. Reese:

WBI Energy Transmission, Inc. (WBI Energy) herewith submits its Weekly Status Report No. 78 for the Wahpeton Expansion Project, in compliance with Environmental Condition 9 of the Appendix to the Federal Energy Regulatory Commission's October 23, 2023 Order Issuing Certificate in the above referenced docket.

The attached report addresses the status of the project from August 11, 2025 to August 17, 2025.

Should you have any questions or comments regarding this filing, please call the undersigned at (701) 530-1563.

Sincerely,

/s/ Lori Myerchin

Lori Myerchin Vice President, Regulatory Affairs and Transportation Services

Attachment

cc: via email

Jennifer Fink FERC Dawn Ramsey, FERC Official Service List



Project Status Report No. 78 Reporting Period: 08-11-2025 – 08-17-2025

A. Update on Federal Authorizations

- WBI Energy has obtained all necessary federal permits and authorizations required for construction of the Wahpeton Expansion Project.
- On November 26, 2024, FERC granted approval to place the Project into service. WBI Energy placed Project facilities into service on December 1, 2024.

B. Construction Status - Pipeline Facilities

• Environmental Inspectors continue to conduct onsite environmental training as needed.

TABLE 1-1 Wahpeton Expansion Pipeline

Work Completed during Reporting Period:

• Continued seeding remaining open rangeland.

Activity Total % % of Total Job Completed Comments Completed This Period Pipeline Clearing / Grading 100% Stringing 100% 100% Bending Welding 100% Joint Coating 100% 100% Ditching Lowering 100% Backfill 100% Bores 68 of 68 99% Cleanup <1% Seeding¹ <1% 98% Final Tie-in and Commissioning 100% Hydrostatic Testing 2 of 2 Appurtenant Facilities Valve Site #1 and Pig Launcher / 2 of 2 Receiver #1 at MP 0.0 Cleanup/Restoration 100% Valve Site #2 and Pig Launcher / 2 of 2 Receiver #2 at MP 11.6 Cleanup/Restoration 100% Valve Site #3 at MP 23.4 1 of 1 Cleanup/Restoration 100% Valve Site #4 at MP 31.3 1 of 1 Cleanup/Restoration 100% $2 \text{ of } \overline{2}$ Valve Site #5 and Pig Launcher / Receiver #3 at MP 39.5 Cleanup/Restoration 100%

_

¹ Seeding of remaining CRP parcel along construction ROW will be completed in August 2025 to comply with the program's seeding window requirements. Remaining bar ditches will be seeded in August 2025, as conditions allow.



Project Status Report No. 78 Reporting Period: 08-11-2025 – 08-17-2025

Valve Site #6 at MP 48.9	1 of 1	
Cleanup/Restoration	100%	
Valve Site #7 and Pig Launcher / Receiver #4 at MP 60.5	2 of 2	
Cleanup/Restoration	100%	

Work Planned for next Reporting Period and Schedule Changes:

• No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness: None

Non-Compliance Issues, Corrective Actions and Effectiveness: None

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:

No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Date	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action



Project Status Report No. 78 Reporting Period: 08-11-2025 – 08-17-2025



Date: 08/15/2025

Location: Sta. No. 1235+00 and

Valve Site 3.

Notes: Revegetation on slope of

valve site perimeter.



Date: 08/15/2025

Location: Sta. No. 1910+00

Notes: Looking south across seeded open range along construction right-of-way.



Project Status Report No. 78 Reporting Period: 08-11-2025 – 08-17-2025

C. Construction Status – Aboveground Facilities

TABLE 2-1 Modifications at Mapleton Compressor Station

Work Completed during Reporting Period:

No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Install Aboveground Station Piping		100%	
Install Belowground Station Piping		100%	
Cleanup / Restoration		100%	

Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action



Project Status Report No. 78 Reporting Period: 08-11-2025 – 08-17-2025

TABLE 2-2 MDU- Kindred Border Station

Work Completed during Reporting Period:

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Initial Site Work		100%	
Concrete Work		100%	
Install Aboveground Piping		100%	
Install Belowground Piping		100%	
Install Buildings		100%	
Cleanup / Restoration		100%	
Install Security Fence		100%	

Work Planned for next Reporting Period and Schedule Changes:

• No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action



Project Status Report No. 78 Reporting Period: 08-11-2025 – 08-17-2025

TABLE 2-3 MDU- Wahpeton Border Station

Work Completed during Reporting Period:

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Initial Site Work		100%	
Concrete Work		100%	
Install Aboveground Piping		100%	
Install Belowground Piping		100%	
Install Buildings		100%	
Cleanup / Restoration		100%	
Install Security Fence		100%	

Work Planned for next Reporting Period and Schedule Changes:

• No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

	Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action
Ī					



Project Status Report No. 78 Reporting Period: 08-11-2025 – 08-17-2025

D. Changes to Stream Crossings or Work in Environmental Sensitive Areas

TABLE 3 Changes to Stream Crossings or Work in Environmental Sensitive Areas

Schedule changes to stream crossings.

None during reporting period.

Schedule changes for work in other environmentally sensitive areas.

None during reporting period.