



---

1250 West Century Avenue

Mailing Address:

P.O. Box 5601

Bismarck, ND 58506-5601

(701) 530-1600

August 28, 2025

Debbie-Anne Reese, Secretary  
Federal Energy Regulatory Commission  
888 First Street, N.E., Room 1A  
Washington, D.C. 20426

Re: WBI Energy Transmission, Inc.  
Wahpeton Expansion Project  
Docket No. CP22-466-000  
Weekly Status Report No. 79

Dear Ms. Reese:

WBI Energy Transmission, Inc. (WBI Energy) herewith submits its Weekly Status Report No. 79 for the Wahpeton Expansion Project, in compliance with Environmental Condition 9 of the Appendix to the Federal Energy Regulatory Commission's October 23, 2023 Order Issuing Certificate in the above referenced docket.

The attached report addresses the status of the project from August 18, 2025 to August 25, 2025.

Should you have any questions or comments regarding this filing, please call the undersigned at (701) 530-1563.

Sincerely,

/s/ Lori Myerchin

Lori Myerchin  
Vice President, Regulatory Affairs  
and Transportation Services

Attachment

cc: via email  
Jennifer Fink FERC  
Dawn Ramsey, FERC  
Official Service List



**WBI Energy Transmission, Inc.**  
**Wahpeton Expansion Project**  
**FERC Docket No. CP22-466-000**  
 Project Status Report No. 79  
 Reporting Period: 08-18-2025 – 08-24-2025

**A. Update on Federal Authorizations**

- WBI Energy has obtained all necessary federal permits and authorizations required for construction of the Wahpeton Expansion Project.
- On November 26, 2024, FERC granted approval to place the Project into service. WBI Energy placed Project facilities into service on December 1, 2024.

**B. Construction Status – Pipeline Facilities**

| TABLE 1-1<br>Wahpeton Expansion Pipeline                                                                                                 |                               |                          |          |
|------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------|--------------------------|----------|
| <b>Work Completed during Reporting Period:</b>                                                                                           |                               |                          |          |
| <ul style="list-style-type: none"> <li>• Resumed seeding of open rangeland.</li> <li>• Dewatered areas for remaining seeding.</li> </ul> |                               |                          |          |
| Activity                                                                                                                                 | Total % Completed This Period | % of Total Job Completed | Comments |
| <b>Pipeline</b>                                                                                                                          |                               |                          |          |
| Clearing / Grading                                                                                                                       |                               | 100%                     |          |
| Stringing                                                                                                                                |                               | 100%                     |          |
| Bending                                                                                                                                  |                               | 100%                     |          |
| Welding                                                                                                                                  |                               | 100%                     |          |
| Joint Coating                                                                                                                            |                               | 100%                     |          |
| Ditching                                                                                                                                 |                               | 100%                     |          |
| Lowering                                                                                                                                 |                               | 100%                     |          |
| Backfill                                                                                                                                 |                               | 100%                     |          |
| Bores                                                                                                                                    |                               | 68 of 68                 |          |
| Cleanup                                                                                                                                  | <1%                           | 99%                      |          |
| Seeding <sup>1</sup>                                                                                                                     | <1%                           | 98%                      |          |
| Final Tie-in and Commissioning                                                                                                           |                               | 100%                     |          |
| Hydrostatic Testing                                                                                                                      |                               | 2 of 2                   |          |
| <b>Appurtenant Facilities</b>                                                                                                            |                               |                          |          |
| Valve Site #1 and Pig Launcher / Receiver #1 at MP 0.0                                                                                   |                               | 2 of 2                   |          |
| Cleanup/Restoration                                                                                                                      |                               | 100%                     |          |
| Valve Site #2 and Pig Launcher / Receiver #2 at MP 11.6                                                                                  |                               | 2 of 2                   |          |
| Cleanup/Restoration                                                                                                                      |                               | 100%                     |          |
| Valve Site #3 at MP 23.4                                                                                                                 |                               | 1 of 1                   |          |
| Cleanup/Restoration                                                                                                                      |                               | 100%                     |          |
| Valve Site #4 at MP 31.3                                                                                                                 |                               | 1 of 1                   |          |
| Cleanup/Restoration                                                                                                                      |                               | 100%                     |          |
| Valve Site #5 and Pig Launcher / Receiver #3 at MP 39.5                                                                                  |                               | 2 of 2                   |          |
| Cleanup/Restoration                                                                                                                      |                               | 100%                     |          |

<sup>1</sup> Seeding of remaining open range parcels and bar ditches along construction ROW, and additional temporary workspaces at Valve Sites 2, 3, 4 and 5 will be completed in August/September 2025, as conditions allow.

**WBI Energy Transmission, Inc.**  
**Wahpeton Expansion Project**  
**FERC Docket No. CP22-466-000**  
 Project Status Report No. 79  
 Reporting Period: 08-18-2025 – 08-24-2025

| Valve Site #6 at MP 48.9                                                                                                                                                                                                                         |                              | 1 of 1          |                   |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------|-----------------|-------------------|
| Cleanup/Restoration                                                                                                                                                                                                                              |                              | 100%            |                   |
| Valve Site #7 and Pig Launcher / Receiver #4 at MP 60.5                                                                                                                                                                                          |                              | 2 of 2          |                   |
| Cleanup/Restoration                                                                                                                                                                                                                              |                              | 100%            |                   |
| <b>Work Planned for next Reporting Period and Schedule Changes:</b> <ul style="list-style-type: none"> <li>Resume seeding of remaining bar ditches.</li> <li>Continue maintenance of erosion control devices, as necessary.</li> </ul>           |                              |                 |                   |
| <b>Problem Areas, Corrective Actions and Effectiveness:</b> None                                                                                                                                                                                 |                              |                 |                   |
| <b>Non-Compliance Issues, Corrective Actions and Effectiveness:</b> None                                                                                                                                                                         |                              |                 |                   |
| <b>Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:</b> <ul style="list-style-type: none"> <li>No non-compliance issues were identified during reporting period.</li> </ul> Copies included: Not applicable |                              |                 |                   |
| <b>Landowner Issues:</b> None                                                                                                                                                                                                                    |                              |                 |                   |
| Date                                                                                                                                                                                                                                             | Milepost / Alignment Sheet # | Problem/Concern | Corrective Action |
|                                                                                                                                                                                                                                                  |                              |                 |                   |
|                                                                                                                                                                                                                                                  |                              |                 |                   |



Date: 08/19/2025

Location: Sta. No. 2580+00 and Valve Site 6.

Notes: Revegetation on slope of valve site perimeter.



**WBI Energy Transmission, Inc.**  
**Wahpeton Expansion Project**  
**FERC Docket No. CP22-466-000**  
Project Status Report No. 79  
Reporting Period: 08-18-2025 – 08-24-2025



Date: 08/23/2025

Location: Sta. No. 1760+00

Notes: Dewatering remaining open range parcel along construction right-of-way.



Date: 08/23/2025

Location: Sta. No. 1895+00

Notes: Seeding open range along construction right-of-way.



**WBI Energy Transmission, Inc.**  
**Wahpeton Expansion Project**  
**FERC Docket No. CP22-466-000**  
 Project Status Report No. 79  
 Reporting Period: 08-18-2025 – 08-24-2025

**C. Construction Status – Aboveground Facilities**

| <b>TABLE 2-1</b><br><b>Modifications at Mapleton Compressor Station</b>                                                                                                                                                                          |                                      |                                     |                        |                          |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|-------------------------------------|------------------------|--------------------------|
| <b>Work Completed during Reporting Period:</b> <ul style="list-style-type: none"> <li>No work was completed during this reporting period.</li> </ul>                                                                                             |                                      |                                     |                        |                          |
| <b>Activity</b>                                                                                                                                                                                                                                  | <b>Total % Completed This Period</b> | <b>% of Total Job Completed</b>     | <b>Comments</b>        |                          |
| Install Aboveground Station Piping                                                                                                                                                                                                               |                                      | 100%                                |                        |                          |
| Install Belowground Station Piping                                                                                                                                                                                                               |                                      | 100%                                |                        |                          |
| Cleanup / Restoration                                                                                                                                                                                                                            |                                      | 100%                                |                        |                          |
| <b>Work Planned for next Reporting Period and Schedule Changes:</b> <ul style="list-style-type: none"> <li>No work is planned for the next reporting period</li> </ul>                                                                           |                                      |                                     |                        |                          |
| <b>Problem Areas, Corrective Actions and Effectiveness:</b> <ul style="list-style-type: none"> <li>No problem areas were identified during reporting period.</li> </ul>                                                                          |                                      |                                     |                        |                          |
| <b>Non-Compliance Issues, Corrective Actions and Effectiveness:</b> <ul style="list-style-type: none"> <li>No non-compliance issues were identified during reporting period.</li> </ul>                                                          |                                      |                                     |                        |                          |
| <b>Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:</b> <ul style="list-style-type: none"> <li>No non-compliance issues were identified during reporting period.</li> </ul> Copies included: Not applicable |                                      |                                     |                        |                          |
| <b>Landowner Issues: None</b>                                                                                                                                                                                                                    |                                      |                                     |                        |                          |
| <b>Date</b>                                                                                                                                                                                                                                      | <b>Name</b>                          | <b>Milepost / Alignment Sheet #</b> | <b>Problem/Concern</b> | <b>Corrective Action</b> |
|                                                                                                                                                                                                                                                  |                                      |                                     |                        |                          |
|                                                                                                                                                                                                                                                  |                                      |                                     |                        |                          |
|                                                                                                                                                                                                                                                  |                                      |                                     |                        |                          |



**WBI Energy Transmission, Inc.**  
**Wahpeton Expansion Project**  
**FERC Docket No. CP22-466-000**  
 Project Status Report No. 79  
 Reporting Period: 08-18-2025 – 08-24-2025

**TABLE 2-2**  
**MDU- Kindred Border Station**

**Work Completed during Reporting Period:**

- No work was completed during this reporting period.

| Activity                   | Total % Completed This Period | % of Total Job Completed | Comments |
|----------------------------|-------------------------------|--------------------------|----------|
| Initial Site Work          |                               | 100%                     |          |
| Concrete Work              |                               | 100%                     |          |
| Install Aboveground Piping |                               | 100%                     |          |
| Install Belowground Piping |                               | 100%                     |          |
| Install Buildings          |                               | 100%                     |          |
| Cleanup / Restoration      |                               | 100%                     |          |
| Install Security Fence     |                               | 100%                     |          |

**Work Planned for next Reporting Period and Schedule Changes:**

- No work is planned for the next reporting period.

**Problem Areas, Corrective Actions and Effectiveness:**

- No problem areas were identified during reporting period.

**Non-Compliance Issues, Corrective Actions and Effectiveness:**

- No non-compliance issues were identified during reporting period.

**Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:**

- No non-compliance issues were identified during reporting period.

Copies included: Not applicable

**Landowner Issues: None**

| Date | Name | Milepost / Alignment Sheet # | Problem/Concern | Corrective Action |
|------|------|------------------------------|-----------------|-------------------|
|      |      |                              |                 |                   |
|      |      |                              |                 |                   |
|      |      |                              |                 |                   |



**WBI Energy Transmission, Inc.**  
**Wahpeton Expansion Project**  
**FERC Docket No. CP22-466-000**  
 Project Status Report No. 79  
 Reporting Period: 08-18-2025 – 08-24-2025

**TABLE 2-3**  
**MDU- Wahpeton Border Station**

**Work Completed during Reporting Period:**

- No work was completed during this reporting period.

| Activity                   | Total % Completed This Period | % of Total Job Completed | Comments |
|----------------------------|-------------------------------|--------------------------|----------|
| Initial Site Work          |                               | 100%                     |          |
| Concrete Work              |                               | 100%                     |          |
| Install Aboveground Piping |                               | 100%                     |          |
| Install Belowground Piping |                               | 100%                     |          |
| Install Buildings          |                               | 100%                     |          |
| Cleanup / Restoration      |                               | 100%                     |          |
| Install Security Fence     |                               | 100%                     |          |

**Work Planned for next Reporting Period and Schedule Changes:**

- No work is planned for the next reporting period.

**Problem Areas, Corrective Actions and Effectiveness:**

- No problem areas were identified during reporting period.

**Non-Compliance Issues, Corrective Actions and Effectiveness:**

- No non-compliance issues were identified during reporting period.

**Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:**

- No non-compliance issues were identified during reporting period.

Copies included: Not applicable

**Landowner Issues: None**

| Date | Name | Milepost / Alignment Sheet # | Problem/Concern | Corrective Action |
|------|------|------------------------------|-----------------|-------------------|
|      |      |                              |                 |                   |
|      |      |                              |                 |                   |
|      |      |                              |                 |                   |



**WBI Energy Transmission, Inc.**  
**Wahpeton Expansion Project**  
**FERC Docket No. CP22-466-000**  
Project Status Report No. 79  
Reporting Period: 08-18-2025 – 08-24-2025

**D. Changes to Stream Crossings or Work in Environmental Sensitive Areas**

**TABLE 3**  
**Changes to Stream Crossings or**  
**Work in Environmental Sensitive Areas**

**Schedule changes to stream crossings.**

- None during reporting period.

**Schedule changes for work in other environmentally sensitive areas.**

- None during reporting period.