

1250 West Century Avenue Mailing Address: P.O. Box 5601 Bismarck, ND 58506-5601 (701) 530-1600

September 4, 2025

Debbie-Anne Reese, Secretary Federal Energy Regulatory Commission 888 First Street, N.E., Room 1A Washington, D.C. 20426

Re: WBI Energy Transmission, Inc. Wahpeton Expansion Project Docket No. CP22-466-000 Weekly Status Report No. 80

Dear Ms. Reese:

WBI Energy Transmission, Inc. (WBI Energy) herewith submits its Weekly Status Report No. 80 for the Wahpeton Expansion Project, in compliance with Environmental Condition 9 of the Appendix to the Federal Energy Regulatory Commission's October 23, 2023 Order Issuing Certificate in the above referenced docket.

The attached report addresses the status of the project from August 25, 2025 to August 31, 2025.

Should you have any questions or comments regarding this filing, please call the undersigned at (701) 530-1563.

Sincerely,

/s/ Lori Myerchin

Lori Myerchin Vice President, Regulatory Affairs and Transportation Services

Attachment

cc: via email

Jennifer Fink FERC Dawn Ramsey, FERC Official Service List



Project Status Report No. 80 Reporting Period: 08-25-2025 – 08-31-2025

A. Update on Federal Authorizations

- WBI Energy has obtained all necessary federal permits and authorizations required for construction of the Wahpeton Expansion Project.
- On November 26, 2024, FERC granted approval to place the Project into service. WBI Energy placed Project facilities into service on December 1, 2024.

B. Construction Status – Pipeline Facilities

TABLE 1-1 Wahpeton Expansion Pipeline

Work Completed during Reporting Period:

- Continued seeding bar ditches.
- Continued follow-up restoration work along construction right-of-way and valve sites, as necessary.
- Continued maintenance and installation of erosion control devices.

% of Total Job Completed Activity Total % Comments Completed **This Period Pipeline** Clearing / Grading 100% 100% Stringing Bending 100% Welding 100% Joint Coating 100% Ditching 100% Lowering 100% Backfill 100% Bores 68 of 68 <1% Cleanup 99% Seeding¹ 1% 99% Final Tie-in and Commissioning 100% **Hydrostatic Testing** 2 of 2 Appurtenant Facilities Valve Site #1 and Pig Launcher / 2 of 2 Receiver #1 at MP 0.0 Cleanup/Restoration 100% Valve Site #2 and Pig Launcher / 2 of 2 Receiver #2 at MP 11.6 100% Cleanup/Restoration Valve Site #3 at MP 23.4 1 of 1 Cleanup/Restoration 100% Valve Site #4 at MP 31.3 1 of 1 Cleanup/Restoration 100% Valve Site #5 and Pig Launcher / 2 of 2 Receiver #3 at MP 39.5 Cleanup/Restoration 100% Valve Site #6 at MP 48.9 1 of 1

Seeding of remaining open range parcels and bar ditches along construction ROW, and additional temporary workspaces at Valve Sites 2, 3, 4 and 5 will be completed in September 2025, as conditions allow.



Project Status Report No. 80 Reporting Period: 08-25-2025 – 08-31-2025

| Cleanup/Restoration | 100% | |
|--|--------|--|
| Valve Site #7 and Pig Launcher / Receiver #4 at MP 60.5 | 2 of 2 | |
| Cleanup/Restoration | 100% | |

Work Planned for next Reporting Period and Schedule Changes:

- · Continue seeding, as conditions allow.
- Continue maintenance of erosion control devices, as necessary.
- Continue follow-up restoration work along construction right-of-way and valve sites, as necessary.

Problem Areas, Corrective Actions and Effectiveness: None

Non-Compliance Issues, Corrective Actions and Effectiveness: None

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Landowner Issues: None

| Edita Wild 133003. Note | | | | | |
|-------------------------|------------------------------------|-----------------|-------------------|--|--|
| Date | Milepost / Alignment Sheet # | Problem/Concern | Corrective Action | | |
| | | | | | |
| | | | | | |



Date: 08/25/2025

Location: Sta. No. 1764+00

Notes: Removal of filter bag after dewatering open rangeland along construction right-of-way prior to

seeding.



Project Status Report No. 80 Reporting Period: 08-25-2025 – 08-31-2025



Date: 08/25/2025

Location: Sta. No. 1908+00

Notes: Raking seed into bare spots along construction right-of-way.



Date: 08/25/2025

Location: Sta. No. 2412+00

Notes: Setting up dewatering equipment prior to follow-up restoration work along construction right-of-way.



Project Status Report No. 80 Reporting Period: 08-25-2025 – 08-31-2025



Date: 08/26/2025

Location: Sta. No. 2987+00 and

Farm Tap.

Notes: Removing erosion control blankets prior to follow-up restoration to recontour bar ditch along construction right-of-way.



Date: 08/26/2025

Location: Sta. No. 3083+00

Notes: Recontouring bar ditch prior to seeding along construction

right-of-way.



Project Status Report No. 80 Reporting Period: 08-25-2025 – 08-31-2025



Date: 08/27/2025

Location: Sta. No. 2987+00 and

Farm Tap.

Notes: Installing erosion control blankets on recontoured slopes of seeded bar ditch along construction

right-of-way.



Date: 08/28/2025

Location: Sta. No. 2740+00

Notes: Repairing road approach along construction right-of-way.



Project Status Report No. 80 Reporting Period: 08-25-2025 – 08-31-2025



Date: 08/28/2025 Location: Sta. No. 2740+00

Notes: Repaired road approach along construction right-of-way.



Date: 08/29/2025

Location: Sta. No. 2553+00

Notes: Recontouring bar ditch prior to seeding along construction

right-of-way.



Project Status Report No. 80 Reporting Period: 08-25-2025 – 08-31-2025



Date: 08/29/2025

Location: Sta. No. 2553+00

Notes: Recontoured and seeded bar ditch along construction right-of-

way.



Date: 08/30/2025

Location: Sta. No. 2320+00

Notes: Recontouring bar ditch prior to seeding along construction

right-of-way.



Project Status Report No. 80 Reporting Period: 08-25-2025 – 08-31-2025



Date: 08/30/2025

Location: Sta. No. 2331+00

Notes: Removing weeds prior to recontouring and seeding bar ditch along construction right-of-way.



Project Status Report No. 80 Reporting Period: 08-25-2025 – 08-31-2025

C. Construction Status – Aboveground Facilities

TABLE 2-1 Modifications at Mapleton Compressor Station

Work Completed during Reporting Period:

No work was completed during this reporting period.

| Activity | Total % Completed This Period | % of Total Job Completed | Comments |
|------------------------------------|-------------------------------------|-----------------------------|----------|
| Install Aboveground Station Piping | | 100% | |
| Install Belowground Station Piping | | 100% | |
| Cleanup / Restoration | | 100% | |

Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Landowner Issues: None

| Da | ate | Name | Milepost / Alignment Sheet # | Problem/Concern | Corrective Action |
|----|-----|------|------------------------------------|-----------------|-------------------|
| | | | | | |
| | | | | | |
| | | | | | |



Project Status Report No. 80 Reporting Period: 08-25-2025 – 08-31-2025

TABLE 2-2 MDU- Kindred Border Station

Work Completed during Reporting Period:

• No work was completed during this reporting period.

| Activity | Total % Completed This Period | % of Total Job Completed | Comments |
|----------------------------|-------------------------------------|-----------------------------|----------|
| Initial Site Work | | 100% | |
| Concrete Work | | 100% | |
| Install Aboveground Piping | | 100% | |
| Install Belowground Piping | | 100% | |
| Install Buildings | | 100% | |
| Cleanup / Restoration | | 100% | |
| Install Security Fence | | 100% | |

Work Planned for next Reporting Period and Schedule Changes:

• No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Landowner Issues: None

| Date | Name | Milepost / Alignment Sheet # | Problem/Concern | Corrective Action |
|------|------|------------------------------------|-----------------|-------------------|
| | | | | |
| | | | | |
| | | | | |



Project Status Report No. 80 Reporting Period: 08-25-2025 – 08-31-2025

TABLE 2-3 MDU- Wahpeton Border Station

Work Completed during Reporting Period:

• Resumed follow-up restoration work.

| Activity | Total % Completed This Period | % of Total Job Completed | Comments |
|----------------------------|-------------------------------|-----------------------------|----------|
| Initial Site Work | | 100% | |
| Concrete Work | | 100% | |
| Install Aboveground Piping | | 100% | |
| Install Belowground Piping | | 100% | |
| Install Buildings | | 100% | |
| Cleanup / Restoration | | 100% | |
| Install Security Fence | | 100% | |

Work Planned for next Reporting Period and Schedule Changes:

• No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Landowner Issues: None

| Date | Name | Milepost / Alignment Sheet # | Problem/Concern | Corrective Action |
|------|------|------------------------------------|-----------------|-------------------|
| | | | | |
| | | | | |
| | | | | |



Project Status Report No. 80 Reporting Period: 08-25-2025 – 08-31-2025



Date: 08/26/2025

Location: MDU – Wahpeton Border Station and Valve Site 7.

Notes: Removing discharged material and resuming follow-up restoration work along seeded

station perimeter.



Date: 08/26/2025

Location: MDU – Wahpeton Border Station and Valve Site 7.

Notes: Reseeding after follow-up restoration work along seeded

station perimeter.



Project Status Report No. 80 Reporting Period: 08-25-2025 – 08-31-2025

D. Changes to Stream Crossings or Work in Environmental Sensitive Areas

TABLE 3 Changes to Stream Crossings or Work in Environmental Sensitive Areas

Schedule changes to stream crossings.

• None during reporting period.

Schedule changes for work in other environmentally sensitive areas.

None during reporting period.