

1250 West Century Avenue Mailing Address: P.O. Box 5601 Bismarck, ND 58506-5601 (701) 530-1600

June 19, 2025

Debbie-Anne Reese, Secretary Federal Energy Regulatory Commission 888 First Street, N.E., Room 1A Washington, D.C. 20426

Re: WBI Energy Transmission, Inc. Wahpeton Expansion Project Docket No. CP22-466-000 Weekly Status Report No. 69

Dear Ms. Reese:

WBI Energy Transmission, Inc. (WBI Energy) herewith submits its Weekly Status Report No. 69 for the Wahpeton Expansion Project, in compliance with Environmental Condition 9 of the Appendix to the Federal Energy Regulatory Commission's October 23, 2023 Order Issuing Certificate in the above referenced docket.

The attached report addresses the status of the project from June 9, 2025 to June 15, 2025.

Should you have any questions or comments regarding this filing, please call the undersigned at (701) 530-1563.

Sincerely,

/s/ Lori Myerchin

Lori Myerchin Vice President, Regulatory Affairs and Transportation Services

Attachment

cc: via email

Jennifer Fink FERC Dawn Ramsey, FERC Official Service List



Project Status Report No. 69 Reporting Period: 06-09-2025 – 06-15-2025

A. Update on Federal Authorizations

- WBI Energy has obtained all necessary federal permits and authorizations required for construction of the Wahpeton Expansion Project.
- On November 26, 2024, FERC granted approval to place the Project into service. WBI Energy placed Project facilities into service on December 1, 2024.

B. Construction Status – Pipeline Facilities

• Environmental Inspectors continue to conduct onsite environmental training as needed.

TABLE 1-1 Wahpeton Expansion Pipeline

Work Completed during Reporting Period:

- Completed cleanup/restoration activities at the laydown yard.
- Continued cleanup/restoration activities at the valve sites, anomaly investigations, and along construction right-of-way.
- Re-staked the approved construction right-of-way for the remaining anomaly (ACVG) dig near end of Bore 64.
- Began removal of topsoil within approved construction right-of-way for remaining ACVG investigation.
- Continued installation and maintenance of Project signage and erosion control devices, as conditions allowed.
- Continued seeding remaining construction right-of-way.

Approximately 10.5 acres (out of 70 acres requiring seeding) remain to be seeded.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Clearing / Grading		100%	
Stringing		100%	
Bending		100%	
Welding		100%	
Joint Coating		100%	
Ditching		100%	
Lowering		100%	
Backfill		100%	
Bores		68 of 68	
Cleanup	1%	95%	
Seeding	10%	85%	
Final Tie-in and Commissioning		100%	
Hydrostatic Testing		2 of 2	



Project Status Report No. 69 Reporting Period: 06-09-2025 – 06-15-2025

Appurtenant Facilities ¹			
Valve Site #1 and Pig Launcher / Receiver #1 at MP 0.0		2 of 2	
Cleanup/Restoration		100%	
Valve Site #2 and Pig Launcher / Receiver #2 at MP 11.6		2 of 2	
Cleanup/Restoration	0%	97%	
Valve Site #3 at MP 23.4		1 of 1	
Cleanup/Restoration	0%	96%	
Valve Site #4 at MP 31.3		1 of 1	
Cleanup/Restoration	5%	65%	Continued restoration of station perimeter.
Valve Site #5 and Pig Launcher / Receiver #3 at MP 39.5		2 of 2	
Cleanup/Restoration	1%	91%	Continued restoration of station perimeter.
Valve Site #6 at MP 48.9		1 of 1	
Cleanup/Restoration	0%	96%	
Valve Site #7 and Pig Launcher / Receiver #4 at MP 60.5		2 of 2	
Cleanup/Restoration	0%	96%	

Work Planned for next Reporting Period and Schedule Changes:

- Complete staking additional temporary workspace requested in a variance request for the remaining anomaly investigation near end of Bore 64.
- Continue cleanup/restoration activities at valve sites and along construction right-of-way.
- Continue installation and maintenance of Project signage and erosion control devices, as necessary.
- Continue reseeding remaining construction right-of-way and valve site perimeters, as conditions allow.

Problem Areas, Corrective Actions and Effectiveness: None

Non-Compliance Issues, Corrective Actions and Effectiveness: None

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:

No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Date	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action	

Remaining pad construction and cleanup/restoration at Valve Sites 2, 3, 4, 5, 6, and 7 include the spreading of gravel and seeding of the valve site perimeters and will be completed in the summer of 2025. Permanent fencing at Valve Sites 2, 4, 5, and 6 will be installed in the summer of 2025.



Project Status Report No. 69 Reporting Period: 06-09-2025 – 06-15-2025



Date: 06/09/2025

Location: 4 Suns Contractor Yard

Notes: Laydown yard after removing construction debris.



Date: 06/09/2025

Location: Sta. No. 721+00

Notes: Cleanup of construction debris along construction right-of-

way.



Project Status Report No. 69 Reporting Period: 06-09-2025 – 06-15-2025



Date: 06/09/2025

Location: Sta. No. 1655+00 and

Valve Site 4.

Notes: Removal of excess sand to prepare station perimeter for

seeding.



Date: 06/10/2025

Location: Sta. No. 1655+00 and

Valve Site 4.

Notes: Spread topsoil prior to seeding station perimeter.



Project Status Report No. 69 Reporting Period: 06-09-2025 – 06-15-2025



Date: 06/10/2025

Location: Sta. No. 1879+00

Notes: Repaired fence after reseeding open rangeland along construction right-of-way.



Date: 06/10/2025

Location: Sta. No. 1910+00

Notes: Disced open rangeland along construction right-of-way

prior to reseeding.



Project Status Report No. 69 Reporting Period: 06-09-2025 – 06-15-2025



Date: 06/11/2025

Location: Sta. No. 1655+00 and

Valve Site 4.

Notes: Grading topsoil prior to seeding station perimeter.



Date: 06/11/2025

Location: Sta. No. 3060+00

Notes: Spreading topsoil after pipeline anomaly investigation along construction right-of-way.



Project Status Report No. 69 Reporting Period: 06-09-2025 – 06-15-2025



Date: 06/12/2025

Location: Sta. No. 1655+00 and

Valve Site 4.

Notes: Grading topsoil prior to seeding station perimeter.



Date: 06/12/2025

Location: Sta. No. 2986+00

Notes: Replaced topsoil after pipeline anomaly investigation along construction right-of-way.

Farm tap to the right.



Project Status Report No. 69 Reporting Period: 06-09-2025 – 06-15-2025



Date: 06/14/2025

Location: Sta. No. 2090+00 and

Valve Site 5.

Notes: Grading topsoil of station perimeter prior to seeding.



Date: 06/14/2025

Location: Sta. No. 2090+00 and

Valve Site 5.

Notes: Grading station pad.



Project Status Report No. 69 Reporting Period: 06-09-2025 – 06-15-2025



Date: 06/14/2025

Location: Sta. No. 2736+00 and

Bore 64.

Notes: Stripping topsoil for access to final pipeline anomaly investigation (in background) along approved construction right-

of-way.



Project Status Report No. 69 Reporting Period: 06-09-2025 – 06-15-2025

C. Construction Status - Aboveground Facilities

TABLE 2-1 Modifications at Mapleton Compressor Station

Work Completed during Reporting Period:

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Install Aboveground Station Piping		100%	
Install Belowground Station Piping		100%	
Cleanup / Restoration ²		100%	

Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Landowner issu	es: None			
Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

² Final cleanup and restoration will be in conjunction with Block Valve #1 and Pig Launcher / Receiver #1 within the compressor station yard.



Project Status Report No. 69 Reporting Period: 06-09-2025 – 06-15-2025

TABLE 2-2 MDU- Kindred Border Station

Work Completed during Reporting Period:

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Initial Site Work	0%	99%	4/
Concrete Work		100%	
Install Aboveground Piping		100%	
Install Belowground Piping		100%	
Install Buildings		100%	
Cleanup / Restoration ³	0%	96%	
Install Security Fence		100%	

Work Planned for next Reporting Period and Schedule Changes:

• Continue initial site work and cleanup/restoration activities.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Landowner issue	es: None			
Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

³ Remaining initial site work, cleanup, and restoration will be completed in conjunction with Block Valve #3 within the border station yard.



Project Status Report No. 69 Reporting Period: 06-09-2025 – 06-15-2025

TABLE 2-3 MDU- Wahpeton Border Station

Work Completed during Reporting Period:

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Initial Site Work	0%	98%	5/
Concrete Work		100%	
Install Aboveground Piping		100%	
Install Belowground Piping		100%	
Install Buildings		100%	
Cleanup / Restoration ⁴	0%	95%	Seeding of the site perimeters will be completed in the summer of 2025.
Install Security Fence		100%	

Work Planned for next Reporting Period and Schedule Changes:

Continue cleanup/restoration activities.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

⁴ Remaining initial site work and cleanup, and restoration will be completed in conjunction with Block Valve #7 within the border station yard.



Project Status Report No. 69 Reporting Period: 06-09-2025 – 06-15-2025

D. Changes to Stream Crossings or Work in Environmental Sensitive Areas

TABLE 3 Changes to Stream Crossings or Work in Environmental Sensitive Areas

Schedule changes to stream crossings.

None during reporting period.

Schedule changes for work in other environmentally sensitive areas.

None during reporting period.